



***Federal Railroad Administration
Office of Railroad Safety
Accident and Analysis Branch***

***Accident Investigation Report
HQ-2016-1129***

***Amtrak ((National Railroad Passenger Corporation) ATK)
Madera, CA
May 16, 2016***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report, including this one, made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

SYNOPSIS

On May 13, 2016, at approximately 12:32 p.m., PDT, westbound Amtrak Passenger Train No. 713, traveling at a recorded speed of 79 mph on BNSF Railway's (BNSF) main line track, struck a motor vehicle at a private highway-rail grade crossing near the city of Madera, California. As a result of the collision, three occupants of the motor vehicle were fatally injured and four of the 211 passengers on the train were injured. There were no reported injuries to Amtrak's train crew.

The accident occurred on single main track at CP Gregg, Milepost 1012.1 on BNSF's California Division, Stockton Subdivision. Movements on this part of the railroad are under a traffic control system by a dispatcher located in San Bernardino, California. The maximum authorized speed for freight and passenger trains in the area of the accident is 80 mph and 90 mph, respectively. The train consisted of one head-end locomotive and five passenger cars. The crossing, which runs over a private dirt road, is guarded only with stop signs and rectangular signs depicting crossbucks. BNSF Freight Train No. ZNBYWSB7-131 was stopped approximately 1,500 to 2,000 feet clear of the private crossing located on the west siding which partially blocked the view on approach to the crossing.

Weather at the time of the accident was sunny and clear with a temperature of approximately 85 °F.

Equipment damage was estimated at \$83,708 to the locomotive; damage to track, signal or structures was estimated at \$300.

There were no hazardous materials involved and was not PTC-preventable.

The probable cause of the accident was inattentiveness on the part of the highway user.

TRAIN SUMMARY

1. Name of Railroad Operating Train #1 Amtrak (National Railroad Passenger Corporation)	1a. Alphabetic Code ATK	1b. Railroad Accident/Incident No. 142375
--	----------------------------	--

GENERAL INFORMATION

1. Name of Railroad or Other Entity Responsible for Track Maintenance BNSF Railway Company		1a. Alphabetic Code BNSF	1b. Railroad Accident/Incident No. CA0516201	
2. U.S. DOT Grade Crossing Identification Number 028596W		3. Date of Accident/Incident 5/13/2016	4. Time of Accident/Incident 12:32 PM	
5. Type of Accident/Incident Hwy-Rail Crossing				
6. Cars Carrying HAZMAT 0	7. HAZMAT Cars Damaged/Derailed 0	8. Cars Releasing HAZMAT 0	9. People Evacuated 0	10. Subdivision Stockton
11. Nearest City/Town Madera		12. Milepost (to nearest tenth) 01012.1	13. State Abbr. CA	14. County MADERA
15. Temperature (F) 85 °F	16. Visibility Day	17. Weather Clear	18. Type of Track Main	
19. Track Name/Number Single Main		20. FRA Track Class Freight Trains-80, Passenger Trains-90	21. Annual Track Density (gross tons in millions) 52.68	22. Time Table Direction West

OPERATING TRAIN #1

1. Type of Equipment Consist: Passenger Train-Pulling					2. Was Equipment Attended? Yes		3. Train Number/Symbol 713					
4. Speed (recorded speed, if available) R - Recorded 79 MPH E - Estimated		Code R	5. Trailing Tons (gross excluding power units)		6a. Remotely Controlled Locomotive? 0 = Not a remotely controlled operation 1 = Remote control portable transmitter 2 = Remote control tower operation 3 = Remote control portable transmitter - more than one remote control transmitter					Code 0		
6. Type of Territory Signalization: <u>Signaled</u> Method of Operation/Authority for Movement: <u>Direct Train Control</u> Supplemental/Adjunct Codes: <u>Q</u>												
7. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded (yes/no)		8. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box		Alcohol	Drugs	
(1) First Involved (derailed, struck, etc.)		CDTX2004		1		yes				0	0	
(2) Causing (if mechanical, cause reported)		CDTX2004		1		yes		9. Was this consist transporting passengers?			Yes	
10. Locomotive Units (Exclude EMU, DMU, and Cab Car Locomotives.)	a. Head End	Mid Train		Rear End		11. Cars (Include EMU, DMU, and Cab Car Locomotives.)	Loaded		Empty		e. Caboose	
		b. Manual	c. Remote	d. Manual	e. Remote		a. Freight	b. Pass.	c. Freight	d. Pass.		
(1) Total in Train	1	0	0	0	0	(1) Total in Equipment Consist	0	5	0	0	0	
(2) Total Derailed	0	0	0	0	0	(2) Total Derailed	0	0	0	0	0	
12. Equipment Damage This Consist 83708				13. Track, Signal, Way & Structure Damage 300								
14. Primary Cause Code M302 - Highway user inattentiveness												
15. Contributing Cause Code M302 - Highway user inattentiveness												
Number of Crew Members						Length of Time on Duty						
16. Engineers/Operators		17. Firemen		18. Conductors		19. Brakemen		20. Engineer/Operator		21. Conductor		
1		0		2		0		Hrs: 3 Mins: 32		Hrs: 3 Mins: 32		
Casualties to:		22. Railroad Employees		23. Train Passengers		24. Others		25. EOT Device?		26. Was EOT Device Properly Armed?		
Fatal		0		0		3		N/A		N/A		
Nonfatal		0		4		0		27. Caboose Occupied by Crew?				N/A
28. Latitude 36.887627000				29. Longitude -119.942260000								

CROSSING INFORMATION

Highway User Involved			Rail Equipment Involved		
1. Type Pick-Up Truck			5. Equipment Train (Units Pulling)		
2. Vehicle Speed (<i>est. mph at impact</i>) 20	3. Direction (<i>geographical</i>) East		6. Position of Car Unit in Train 1		
4. Position of Involved Highway User Moved over Crossing			7. Circumstance Rail Equipment Struck Highway User		
8a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? Neither			8b. Was there a hazardous materials release by Neither		
8c. State here the name and quantity of the hazardous material released, if any. N/A					
9. Type of Crossing 1. Gates 4. Wig wags 7. Crossbucks 10. Flagged by crew 2. Cantilever FLS 5. Hwy. traffic signals 8. Stop signs 11. Other (<i>spec. in narr.</i>) 3. Standard FLS 6. Audible 9. Watchman 12. None 7, 8			10. Signaled Crossing Warning		11. Roadway Conditions Dry
12. Location of Warning Both Sides		13. Crossing Warning Interconnected with Highway Signals No		14. Crossing Illuminated by Street Lights or Special Lights No	
15. Highway User's Age 40	16. Highway User's Gender Male	17. Highway User Went Behind or in Front of Train and Struck or was Struck by Second Train Yes		18. Highway User Did not stop	
19. Driver Passed Standing Highway Vehicle No		20. View of Track Obscured by (<i>primary obstruction</i>) Not Obstructed			
Casualties to:		Killed	Injured	21. Driver was Killed	22. Was Driver in the Vehicle? Yes
23. Highway-Rail Crossing Users	3	0	24. Highway Vehicle Property Damage (<i>est. dollar damage</i>)	10000	25. Total Number of Vehicle Occupants (<i>including driver</i>) 3
26. Locomotive Auxiliary Lights? Yes			27. Locomotive Auxiliary Lights Operational? Yes		
28. Locomotive Headlight Illuminated? Yes			29. Locomotive Audible Warning Sounded? Yes		

10. Signaled Crossing Warning

Explanation Code

- | | |
|--|--|
| 1 - Provided minimum 20-second warning | A - Insulated rail vehicle |
| 2 - Alleged warning time greater than 60 seconds | B - Storm/lightning damage |
| 3 - Alleged warning time less than 20 seconds | C - Vandalism |
| 4 - Alleged no warning | D - No power/batteries dead |
| 5 - Confirmed warning time greater than 60 seconds | E - Devices down for repair |
| 6 - Confirmed warning time less than 20 seconds | F - Devices out of service |
| 7 - Confirmed no warning | G - Warning time greater than 60 seconds attributed to accident-involved train stopping short of the crossing, but within track circuit limits, while warning devices remain continuously active with no other in-motion train present |
| N/A - N/A | H - Warning time greater than 60 seconds attributed to track circuit failure (e.g., insulated rail joint or rail bonding failure, track or ballast fouled) |
| | J - Warning time greater than 60 seconds attributed to other train/equipment within track circuit limits |
| | K - Warning time less than 20 seconds attributed to signals timing out before train's arrival at the crossing/island circuit |
| | L - Warning time less than 20 seconds attributed to train operating counter to track circuit design direction |
| | M - Warning time less than 20 seconds attributed to train speed in excess of track circuit's design speed |
| | N - Warning time less than 20 seconds attributed to signal system's failure to detect train approach |
| | O - Warning time less than 20 seconds attributed to violation of special train operating instructions |
| | P - No warning attributed to signal systems failure to detect the train |
| | R - Other cause(s). Explain in Narrative Description |




SKETCHES

Madera Sketch

ATK713-13 came to rest 1,645' NW of POI

HQ-2016-1129
Gregg, CA
05/13/16
12:32 p.m. PDT

Timetable Stations/MP



Private crossing DOT #028596W MP 1012.1

Standing BNSF ZNBYWSB7-131 EB

Amtrak 713-13 WB

9th Avenue DOT #028595P MP 1011.5

NARRATIVE

For the purpose of this report, the railroad timetable is west and geographical directions are north/northwest. Directions will be expressed per railroad timetable.

Circumstances Prior to the Accident

The crew of Amtrak Train No. 713, an engineer, a conductor, and an assistant conductor, went on duty at 8:50 a.m., May 13, 2016, at Bakersfield, California, their home terminal, and departed at 10:05 a.m. All crew members received more than their statutorily required off-duty time. Their train consisted of one locomotive and 5 passenger cars with 211 passengers on-board. They described the trip as uneventful. As the crew approached the accident site, the Engineer was seated on the east side of the lead locomotive and the Conductor and Assistant Conductor were in the coach cars. Amtrak Train No. 713 had been traveling in the east track alongside a stopped eastbound BNSF Freight Train No. ZNBYWSB7-131 that was in an adjacent siding on the west track and had stopped over the Avenue 9 crossing at CP Gregg approximately 10 miles south of the city of Madera (Madera County), California.

According to the Engineer's statement, Amtrak Train No. 713 was traveling timetable west on a clear signal at a recorded speed of 79 mph. The maximum authorized speed for freight and passenger trains in the area of the accident is 80 mph and 90 mph, respectively. As the train approached the Avenue 9 grade crossing, the Engineer could see a stopped BNSF freight train to his left. He observed motor vehicle traffic stopped at the Avenue 9 crossing, which is an active grade crossing with warning lights and gates. Amtrak Train No. 713 continued to travel west and reached the end of the freight train which was stopped at approximately 2,000 feet from a private road crossing. To his left, he observed dust from a motor vehicle on the farm road that runs parallel to the track. The motor vehicle did not come into the Engineer's view until after Amtrak Train No. 713 cleared the freight train. The Engineer then observed the motor vehicle quickly approaching the private crossing traveling in the same direction as his train. The motor vehicle then made a right turn onto the private crossing directly in front of Amtrak Train No. 713.

The Engineer started blowing his horn at the location known as the W, or Whistle Board, prior to noticing the approaching vehicle. The train's head light and ditch lights were on bright and the bell was actuated.

The Accident

As the motor vehicle turned in front of Amtrak Train No. 713, the Locomotive Engineer had enough time to initiate a full emergency application of the train air brakes. The train impacted the motor vehicle on the passenger's side at a recorded speed of 79 mph and fatally injured the three occupants. There was no derailment and only minor damage to the locomotive as well as to the track, signals and structures. The motor vehicle came to rest in three sections, north of the main line, just off the right-of-way. Police and

emergency services arrived immediately after the accident. According to the Madera County Coroner, the three victims suffered fatal injuries immediately on impact.

The train crew was uninjured but four passengers complained of injuries at the scene and were transported to a local hospital for treatment. The Federal Railroad Administration's (FRA) post-accident toxicology testing was not conducted on the train crew.

Post-Accident Investigation

Inspector's from FRA and California Public Utilities Commission (CPUC), along with BNSF railroad managers arrived at the scene to begin the investigation and obtain statements, take photographs, and inspect the locomotive and passenger cars, signal and train control devices and track. The area of the crossing is open and visibility is unencumbered by trees or vegetation. The crossing is guarded by stop signs and white, rectangular signs depicting crossbucks in both directions.

Analysis and Conclusions

Analysis – Mechanical: An inspection of the locomotive revealed no mechanical defects and only minor damage to the front from the collision. A review of all records of tests and inspections of the equipment showed no defects that would have contributed to the accident.

Conclusions – Mechanical: Mechanical issues are excluded as having contributed to the accident.

Analysis – Operating Practices: An analysis of the event recorder download substantiates the crew's statements, confirms their timeline of the events, and reveals no issues with train handling and their reaction to the events on approach to the accident site.

Conclusions – Operating Practices: Train operations and the actions of the crew are excluded as having contributed to the accident.

Analysis – Signal & Train Control: An analysis of condition of the signal and train control systems directing the train functioned as intended, as was the operation of the signaled and guarded highway-rail grade crossing at Avenue 9. The private/farm grade crossing was not signaled and only guarded by white, rectangular signs depicting crossbucks.

Conclusions – Signal & Train Control: Signal and train control systems are excluded as having contributed to the accident.

Analysis – Track: An analysis of the track and right-of-way in the area of the accident showed no defects or conditions that had any bearing on the accident.

Conclusions – Track: Track is excluded as having contributed to the accident.

Overall Conclusions

An analysis of the crew's actions and condition of the equipment used in Amtrak Train No. 713, signal and train control systems and crossing warning devices, and track and right-of-way excludes each as having contributed to the accident.

Probable Cause and Contributing Factors

FRA has concluded the probable cause of the accident was highway user inattentiveness. There were no contributing factors.