



1

2 U.S. Department of
3 Transportation

4

5 Federal Railroad
6 Administration



7

8

9

10

11

12

Office of Railroad Safety Summary Report

13

Derailment of Metro-North Passenger Train 8808

14

Spuyten Duyvil, Bronx, New York

15

December 1, 2013

16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33

Executive Summary

On December 1, 2013, at 7:16 a.m., EST, southbound Metro-North Railroad (MNCW) Passenger Train 8808 derailed near Spuyten Duyvil Station in Bronx, New York, on Main Track 2. Train 8808 originated in Poughkeepsie, New York, with a destination of Grand Central Terminal (GCT) in New York, New York. Train 8808 consisted of one cab car¹, six passenger cars, and one diesel electric locomotive at the rear in a push/pull configuration. The entire train derailed and came to rest on the west side of the tracks with the lead car stopping at the bank of the Harlem River. The derailment occurred on MNCW's Hudson Division in a 6.5-degree, left-hand curve where the maximum authorized speed was restricted to 30 mph. The locomotive event recorder data indicated the train was traveling at 82 mph when it derailed. The derailment resulted in 4 fatalities, 82 injuries, a fuel spill, equipment and track damage of \$5,876,090, and disruption to MNCW's Hudson Division service for 2 days. The total number of passengers on the train was unknown, however, MNCW reports the average ridership for this train to be around 110. The weather at the time of the accident was clear and the temperature was 39 °F. The Federal Railroad Administration's (FRA) investigation determined the probable cause to be excessive speed. A contributing cause was determined to be the Engineer suffering from severe Obstructive Sleep Apnea (OSA).

34

CIRCUMSTANCES PRIOR TO THE ACCIDENT

35 Train 8808 was manned by a train crew of four certified and qualified MNCW employees which
36 included a Locomotive Engineer, Conductor, and two Assistant Conductors. The Engineer and
37 Conductor reported for duty at 5:04 a.m., EST, and an Assistant Conductor reported for duty at

¹ A passenger car that has controls for the Engineer to operate from when the locomotive is on the rear in push/pull configuration.

38 5:30 a.m., EST, at the Poughkeepsie Engine House, in Poughkeepsie, New York, which is their
39 home-terminal. One Assistant Conductor joined the crew at Croton Harmon Station at 6:25 a.m.,
40 EST, in Croton-on-Hudson, New York. All crew members received more than the statutory off-
41 duty rest period prior to reporting for duty.

42 Train 8808 consisted of Cab Car 6222 in the lead, six passenger cars and one diesel electric
43 locomotive on the rear. The locomotive was providing the power for movement in a push mode
44 at the rear of the train. The train departed Poughkeepsie on-time and made nine station stops en
45 route to GCT. The equipment had received all required inspections and tests prior to starting its
46 daily operating cycle.

47 As the train approached the derailment area, the Locomotive Engineer was seated at the controls
48 on the right side of Cab Car 6222 facing the direction of movement. An Assistant Conductor
49 was seated in the passenger area of the cab car, and the Conductor and second Assistant
50 Conductor were seated in Car 6147.

51 In the area of the derailment, the Hudson Line consists of three main line tracks. The tracks are
52 geographically oriented north to south and referenced by timetable direction as north to south
53 and labeled east to west as track 1, 2 and 4. On Track 2, a curve begins at Milepost (MP) 11.38
54 and ends at MP 11.16. The length² of the curve is 1,198 feet. Timetable speed for the three main
55 tracks through Spuyten Duyvil is 70 mph with a 30-mph permanent speed restriction between
56 MP 11.5 and MP 9.9 as designated in MNCW's Timetable Number 1, effective April 7, 2013.
57 The derailment occurred at MP 11.3. The method of operation at this location is Centralized
58 Traffic Control (CTC)³.

² Due to changes in track alignment, RR mileposts are not always exactly one mile apart.

³ Centralized Traffic Control (CTC) is a method of operation, in which all train movements are authorized and governed by interlocking signals, cab signals and instructions issued by the Rail Traffic Controller.

59 Train 8808, per the event recorder data, departed Tarrytown Station at 7:02 a.m., EST, operating
60 south on Main Track 2. The event recorder data also shows the Engineer manipulated the
61 controls several times after leaving Tarrytown, New York. At 7:05:34 a.m., EST, the Engineer
62 shut off the throttle after reaching the maximum authorized speed (MAS) of 70 mph. Train 8808
63 then coasted for 4 minutes and 35 seconds and slowed to 47 mph before the throttle was moved
64 to position 8⁴ at 7:10:19 a.m., EST. The Engineer then manipulated the controls several times to
65 comply with speed restrictions and sounded the horn when required by MNCW rule, and Federal
66 regulations. The last recorded action prior to the derailment occurred at 7:14:37 a.m., EST, when
67 the Engineer placed the throttle in position 8.

68


69 **THE ACCIDENT**

70 As Train 8808 approached the left-hand curve north of Spuyten Duyvil Station, the event
71 recorder data indicates the train reached MAS of 70 mph at 7:15:41 a.m., EST. The Engineer
72 took no action to prevent an over speed condition and continued to accelerate. At 7:16.45 a.m.,
73 EST, at MP 11.50, Train 8808 entered a segment of track where speed was restricted to 30 mph
74 traveling 79 mph and took no action to reduce his speed. The train speed continued to increase
75 to 82 mph at MP 11.3 at 7:16:53 a.m., EST, and the event recorder stopped recording at 7:16:56
76 a.m., EST, the recorded time of the derailment.

77 The derailment occurred at MP 11.35, in a 6.5-degree curve, where the leading west wheel of
78 Cab Car 6222 climbed the west rail due to high lateral wheel forces. Simultaneously a high cant
79 deficiency induced in the car resulted in complete unloading of the wheels on the east side rail,
80 or low rail, allowing the car to turn onto its side. As the train continued forward, cars two

⁴ Throttle position 8 is the maximum throttle position.

81 through seven derailed in the same manner. The first five cars rolled onto their right sides, then
82 the fourth car rolled over coming to rest leaning to the left. Cars one and five up-righted
83 themselves, while cars six and seven, as well as the locomotive, traveled through the debris field
84 at a 45-degree angle and were slowed by plowing into the ballast. The train traveled
85 approximately 880 feet from the point of derailment (POD) before coming to rest. When the
86 train came to rest, the first car, Cab Car 6222, was upright. The second and third car, 6228 and
87 6345 respectively, were on their right sides. The fourth car, 6440, rolled over completely and
88 was leaning at a 45-degree angle to the left. The fifth car, 6188, and the sixth car, 6147, were
89 upright with their wheels buried deep in the ballast. The seventh car, 6156, and Locomotive 225,
90 was leaning at a 45-degree angle on its right side. (Figure 1).



91

92

Figure 1: Aerial view of MNCW Passenger Train 8808 derailment

93

94 **INVESTIGATION FINDINGS AND ANALYSIS**

95 FRA investigators arrived on-scene at 8:30 a.m., EST, on December 1, 2013, and the field
96 investigation concluded on December 9, 2013. FRA’s investigation team was comprised of a
97 Chief Inspector, who served as the Inspector in Charge, and inspectors from the Motive Power
98 and Equipment (MP&E), Operating Practices (OP), Track, and Signal and Train Control
99 disciplines.

100 FRA’s investigation included an inspection of the equipment, a review of records of tests and
101 maintenance performed on the equipment prior to the accident, an inspection of the signal system
102 to include a review of records of tests and maintenance performed prior to the accident, a review
103 of the train operation for compliance with the railroads applicable rules and timetable
104 instructions, and the crew’s status regarding physical exams, training, and hours of service.
105 Measurements of the post-accident track geometry were made and previous automated track
106 geometry records in the area of the derailment were reviewed and analyzed. MNCW’s track
107 inspection reports, periodic continuous welded rail (CWR) joint bar inspection reports, and rail
108 inspection records were reviewed.

109

110 ***Track***

111 FRA investigators reviewed the derailment site and determined the POD to be located on Track
112 2, west rail, at MP 11.35. Investigators observed a continuous mark beginning at the inside
113 corner of the west rail that traveled in a southerly direction and diagonally across the top of the
114 rail surface. This is indicative of the point of derailment.

115 Measurements of the post-accident track geometry and review of previous automated track
116 geometry records near the POD by investigators confirmed the track geometry was in

117 compliance with FRA track safety standards. Review of MNCW track inspection reports,
118 periodic CWR joint bar inspection reports, and rail inspection records revealed MNCW indicated
119 compliance with the minimum required frequency of inspections, reporting exceptions, and
120 taking the required remedial action on exceptions. Investigators determined the track, rail,
121 surface, ties, and drainage were not a factor in this derailment.

122

123 *MP&E*

124 Investigators performed detailed post-accident inspections and testing of the equipment and
125 carefully reviewed pertinent records of tests and maintenance performed on the train prior to the
126 accident. All equipment functioned as designed and records were in compliance with Federal
127 regulations. Cab Car 6222 was ordered on November 8, 2000, and placed in service on
128 September 5, 2002. The cab car was not, nor was it required to be, equipped with an alerter
129 device⁵. No equipment-related contributing causes were found.

130

131 *Signal System*

132 The signal systems were inspected for proper operation. Inspection records for both
133 interlockings, the track and the Supervisory Control and Data Acquisition (SCADA)⁶ event
134 recorder were reviewed. It was determined the signal system displayed the proper wayside and
135 onboard signals up to the time of the derailment and was not a contributing factor in this
136 derailment.

137

138

⁵ A device that sounds an audible alert if no action is taken by the Engineer in a specified time limit.

⁶ An In-Cab signal system that displays information that controls the movement of trains.

139 *OP*

140 The OP investigation included review of training and compliance records, interviews, sight
141 distance evaluation, fatigue analysis, review of toxicology testing results, and review of event
142 recorder data.

143

144 *Review of Operating Rules and Training Records*

145 FRA investigators reviewed MNCW Operating Rules and determined the Engineer of Train 8808
146 failed to operate the train in compliance with MNCW operating rules, and in violation of Title 49
147 Code of Federal Regulations (CFR) Section 240.305(a)(2) which states it shall be unlawful to
148 “[o]perate a locomotive or train at a speed which exceeds the maximum authorized limit by at
149 least 10 miles per hour.” The investigation found the Engineer of Train 8808 was certified and
150 qualified on the territory where the derailment occurred and required training was current.

151

152 *Sight Distance Evaluation*

153 A simulated reenactment of the Engineer’s view approaching the 30-mph speed restriction at MP
154 11.5 from the cab of Train 8808 was performed. The reenactment used train equipment similar
155 in design to the equipment involved, at the approximate time of the accident, with similar
156 weather conditions, and a certified and qualified crew. The purpose of the test was to determine
157 the sight distance where the curve, and its 30-mph speed restriction, could be confidently
158 identified by the operating engineer. The test concluded the Engineer could view the
159 approaching curve, and its speed restriction, with ample time to apply the trains braking system
160 to comply with the speed restriction before entering the curve, consistent with good train
161 handling.

162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183

Review of Event Recorder Data

Review of the event recorder data determined the train was not operated in compliance with the railroad’s applicable rules and timetable instructions. The event recorder data confirmed an overspeed event was the primary cause of the derailment.

Fatigue Analysis Study

FRA performed a fatigue analysis using the Fatigue Avoidance Scheduling Tool (FAST)⁷. FRA uses an overall effectiveness rate of 77.5 percent as the baseline for fatigue analysis. At or above this baseline, FRA does not consider fatigue as probable for any employee. Inputs into the FAST software vary according to information obtained from each employee. Based on the results of the FAST analysis, FRA concluded that fatigue was not probable for the Engineer and Conductor of Train 8808.

Voluntary post-accident sleep disorder medical tests of the Engineer were performed. It was reported these tests indicated the Engineer suffered from severe OSA.

Toxicological Testing

This accident met the criteria for Title 49 CFR Part 219, Subpart C, Post Accident Toxicological Testing. The entire crew on Train 8808 and the two Rail Traffic Controllers were tested under FRA guidelines for the use of alcohol and drugs with negative results for all employees tested. Investigators determined that neither drug nor alcohol use was a factor in this accident.

⁷ FAST is designed to identify fatigue based on work-rest cycles from inputs from the subjects and is not intended to diagnose medical conditions.

184

185 Interviews

186 In an interview with the investigators, the Engineer stated all equipment operated normally and
187 he “didn’t take any exceptions” during the trip. He stated he began to feel “dazed and
188 hypnotized” looking ahead at the track leading up to the accident site, and the “feeling of the
189 train” shook him out of this state. The Engineer also stated that no one was in the operating
190 compartment with him the entire trip.


191 The Engineer told investigators that he had been working this assignment since November 18,
192 2013, and he has been working nights consistently for the last 2.5 years. The Engineer
193 categorized his overall health to investigators as “excellent”.

194

195 ***Forensics Team***

196 FRA dispatched a separate team to analyze damaged passenger cars and to make a correlation
197 between the nature and extent of injuries with the equipment damage involved. This team noted
198 the windows and gaskets were torn from their frames while the cars were sliding on their sides.
199 The Forensics Team determined the fatally injured passengers were ejected from the train via
200 windows during the derailment. The causal mechanism of these fatalities was most likely the
201 lack of glazing securement during car body derailment and rollover. Victims appear to have
202 been pulled out when they contacted the ground through window openings, as the cars continued
203 to slide. (*Figure 2*). Nearly all the polycarbonate window panes remained substantially intact, as
204 did the car sidewalls.

Derailment Overview



205

206

Figure 2: Derailment car and fatality locations

207

208 CONCLUSIONS

209

210

211

1. The cause of the derailment was excessive speed. The train entered the curve at 82 mph within the 30-mph restriction. Train 8808 was not operated in compliance with the railroads applicable rules and timetable instructions.

212

213

214

2. Equipment was not a contributing factor in this derailment. Of note, Cab Car 6222 was not required to be equipped with an alerter. Had the cab car been equipped with an alerter device, the Engineer would have been provided a safeguard to prevent loss of situational awareness.

215

216

217

3. Fatigue, as determined by FRA's FAST model, was not probable for the crew of Train 8808.

218 4. A separate sleep evaluation external of FRA investigation reportedly concluded the
219 Engineer suffered a sleep disorder, specifically severe OSA.

220

221 **FRA ACTIONS**

222 On December 11, 2013, FRA issued an Emergency Order ([EO-29](#)) requiring MNCW to take
223 certain actions to control passenger train speed at any location on main track where there is a
224 reduction of more than 20 mph from the maximum authorized train speed. On December 11,
225 2013, FRA issued a Safety Advisory ([SA-2013-08](#)) which urged railroads to provide additional
226 training, increase the frequency of operational testing, and reinforce the importance of
227 communication between crew members. FRA also initiated [Operation Deep Dive](#), a safety
228 assessment of MNCW's operations and safety compliance on December 16, 2013. FRA worked
229 closely with MNCW in developing their remedial actions. FRA's Administrator met with the
230 Metropolitan Transit Authority's Board Chairman regarding the accident. Following the
231 derailment, FRA conducted assessments, to include a forensics investigation of side window loss
232 and occupant expulsion.

233

234 Forensics Investigation

235 The forensics investigation determined all the fatally injured passengers were ejected from the
236 train via windows during the derailment. All train occupants that were contained within the cars
237 survived the derailment. Results of the forensics investigation indicate the rubber gaskets
238 holding the window panes in place were pulled out when the cars slid on their sides and the
239 windows were pushed inside the cars creating openings.

240 In addition to functioning as a window, glazing systems are also expected to be impact-resistant,
241 provide emergency egress and access, be fire-resistant, and provide occupant containment. FRA
242 is conducting research on glazing integrity, including assessing the performance of current
243 glazing systems in meeting all expectations. Specifically, occupant containment, developing
244 modifications for improving safety performance, and comparing the performance of
245 conventional and modified glazing systems are being studied. The objective of FRA's glazing
246 integrity research is to comprehensively describe all the engineering requirements placed on
247 glazing systems and to develop effective strategies for balancing all safety demands.

248

249 **RAILROAD ACTIONS**

250 MNCW made circuit changes to the signal system near the Spuyten Duyvil station on December
251 9, 2013. The signal system will now enforce the 30-mph permanent speed restriction on the
252 curve near the Spuyten Duyvil station. MNCW also implemented similar changes at five other
253 critical curves and five moveable bridges. MNCW acted to install alerter devices in all cab cars
254 not previously equipped. After the accident, MNCW established a significant shift in the
255 functional responsibilities of their Office of System Safety. Their focus was to improve the
256 railroad's overall safety culture by implementing meaningful safety enhancements. The
257 enhancement includes reorganizing the Safety Department to create a Data Analysis Unit and a
258 separate Incident Investigation Unit. Additionally, MNCW revised their System Safety Program
259 Plan (SSPP) to include a hazard assessment component and has implemented communications
260 and training programs in the SSPP, as well as entered into an Implementing Memorandum of
261 Understanding with the labor unions and FRA to participate in the Confidential Close Call
262 Reporting System.