



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2008-22***

***Norfolk Southern (NS)
Tennille, GA
March 1, 2008***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2008-22</u>	
1. Name of Railroad Operating Train #1 Norfolk Southern Corp. [NS]			1a. Alphabetic Code NS		1b. Railroad Accident/Incident No. 032113		
2. Name of Railroad Operating Train #2 N/A			2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A		
3. Name of Railroad Operating Train #3 N/A			3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A		
4. Name of Railroad Responsible for Track Maintenance: Norfolk Southern Corp. [NS]			4a. Alphabetic Code NS		4b. Railroad Accident/Incident No. 032113		
5. U.S. DOT_AAR Grade Crossing Identification Number			6. Date of Accident/Incident Month 03 Day 01 Year 2008		7. Time of Accident/Incident 06:30: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM		
8. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction
					10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts		13. Other (describe in narrative)
9. Cars Carrying HAZMAT 11			10. HAZMAT Cars Damaged/Derailed 2		11. Cars Releasing HAZMAT 1		12. People Evacuated 0
14. Nearest City/Town Tennille			15. Milepost (to nearest tenth) 138.08		16. State Abbr Code N/A GA		17. County WILKINSON
18. Temperature (F) (specify if minus) 58 F		19. Visibility (single entry) 1. Dawn 3. Dusk 2. Day 4. Dark		20. Weather (single entry) 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow		21. Type of Track 1. Main 3. Siding 2. Yard 4. Industry	
		Code 1		Code 1		Code 1	
22. Track Name/Number single main			23. FRA Track Class (1-9, X) 4		24. Annual Track Density (gross tons in millions) 28		25. Time Table Direction 1. North 3. East 2. South 4. West
						Code 4	
OPERATING TRAIN #1							
26. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car	
						A. Spec. MoW Equip. Code 1	
27. Was Equipment Attended?		1. Yes 2. No		Code 1		28. Train Number/Symbol NS191G529	
29. Speed (recorded speed, if available) R - Recorded E - Estimated 35 MPH R		30. Trailing Tons (gross tonnage, excluding power units) 5240				31. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) e. Traffic k. Direct traffic control Code(s) f. Interlocking l. Yard limits g j N/A N/A N/A	
						31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter	
						0	
32. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded (yes/no)	
(1) First involved (derailed, struck, etc)		UTLX640852		3		yes	
(2) Causing (if mechanical cause reported)		0		0		N/A	
33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.		Alcohol		Drugs			
		N/A		N/A			
34. Was this consist transporting passengers? (Y/N)		N/A					
35. Locomotive Units		a. Head End		Mid Train		Rear End	
		b. Manual		c. Remote		d. Manual c. Remote	
(1) Total in Train		2		0		0	
(2) Total Derailed		2		0		0	
36. Cars		a. Freight		b. Pass.		c. Freight d. Pass. e. Caboose	
(1) Total in Equipment Consist		31		0		40	
(2) Total Derailed		16		0		12	
37. Equipment Damage		This Consist \$645,750.00		38. Track, Signal, Way, & Structure Damage \$50,000.00		39. Primary Cause Code T220	
						40. Contributing Cause Code N/A	
Number of Crew Members				Length of Time on Duty			
41. Engineer/Operators 1		42. Firemen 0		43. Conductors 1		44. Brakemen 0	
45. Engineer/Operator Hrs 3 Mi 29		46. Conductor Hrs 3 Mi 29					
Casualties to:		47. Railroad Employees		48. Train Passengers		49. Other	
Fatal		0		0		0	
Nonfatal		0		0		0	
50. EOT Device?		1. Yes 2. No		1		51. Was EOT Device Properly Armed?	
						1. Yes 2. No 1	
52. Caboose Occupied by Crew?		1. Yes 2. No		2			
OPERATING TRAIN #2							
53. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car	
						A. Spec. MoW Equip. Code N/A	
54. Was Equipment Attended?		1. Yes 2. No		Code N/A		55. Train Number/Symbol N/A	
56. Speed (recorded speed, if available) R - Recorded E - Estimated N/A MPH N/A		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track				58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2008-22</u>	
57. Trailing Tons (<i>gross tonnage, excluding power units</i>)		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (<i>Specify in narrative</i>) Code(s) N/A N/A N/A N/A N/A	
N/A						2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A	
59. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)	
(1) First involved (<i>derailed, struck, etc</i>)		N/A		N/A		N/A	
(2) Causing (<i>if mechanical cause reported</i>)		N/A		N/A		N/A	
						60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	
						Alcohol N/A	
						Drugs N/A	
						61. Was this consist transporting passengers? (Y/N) N/A	
62. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote	
(1) Total in Train		N/A		N/A		N/A	
(2) Total Derailed		N/A		N/A		N/A	
63. Cars		a. Freight		b. Pass.		c. Freight d. Pass.	
(1) Total in Equipment Consist		N/A		N/A		N/A	
(2) Total Derailed		N/A		N/A		N/A	
64. Equipment Damage This Consist		N/A		65. Track, Signal, Way, & Structure Damage		N/A	
Number of Crew Members				Length of Time on Duty			
68. Engineer/Operators		69. Firemen		70. Conductors		71. Brakemen	
N/A		N/A		N/A		N/A	
72. Engineer/Operator Hrs N/A Mi N/A		73. Conductor Hrs N/A Mi N/A					
Casualties to:		74. Railroad Employees		75. Train Passengers		76. Other	
Fatal		N/A		N/A		N/A	
Nonfatal		N/A		N/A		N/A	
						77. EOT Device? 1. Yes 2. No N/A	
						78. Was EOT Device Properly Armed? 1. Yes 2. No N/A	
						79. Caboose Occupied by Crew? 1. Yes 2. No N/A	
OPERATING TRAIN #3							
80. Type of Equipment Consist (<i>single entry</i>)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car	
						A. Spec. MoW Equip. Code N/A	
						81. Was Equipment Attended? 1. Yes 2. No N/A	
						82. Train Number/Symbol N/A	
83. Speed (<i>recorded speed, if available</i>)		Code R - Recorded E - Estimated N/A MPH N/A		85. Method(s) of Operation (<i>enter code(s) that apply</i>)		85a. Remotely Controlled Locomotive?	
						0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A	
84. Trailing Tons (<i>gross tonnage, excluding power units</i>)		N/A					
86. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)	
(1) First involved (<i>derailed, struck, etc</i>)		N/A		N/A		N/A	
(2) Causing (<i>if mechanical cause reported</i>)		N/A		N/A		N/A	
						87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	
						Alcohol N/A	
						Drugs N/A	
						88. Was this consist transporting passengers? (Y/N) N/A	
89. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote	
(1) Total in Train		N/A		N/A		N/A	
(2) Total Derailed		N/A		N/A		N/A	
90. Cars		a. Freight		b. Pass.		c. Freight d. Pass.	
(1) Total in Equipment Consist		N/A		N/A		N/A	
(2) Total Derailed		N/A		N/A		N/A	
91. Equipment Damage This Consist		N/A		92. Track, Signal, Way, & Structure Damage		N/A	
Number of Crew Members				Length of Time on Duty			
95. Engineer/Operators		96. Firemen		97. Conductors		98. Brakemen	
N/A		N/A		N/A		N/A	
99. Engineer/Operator Hrs N/A Mi N/A		100. Conductor Hrs N/A Mi N/A					
Casualties to:		101. Railroad Employees		102. Train		103. Other	
Fatal		N/A		N/A		N/A	
Nonfatal		N/A		N/A		N/A	
						104. EOT 1. Yes 2. No N/A	
						105. Was EOT Device Properly 1. Yes 2. No N/A	
						106. Caboose Occupied by Crew? 1. Yes 2. No N/A	
Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer. F. Bus J. Other Motor Vehicle Code A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (<i>spec. in narrative</i>) N/A				111. Equipment 3. Train (<i>standing</i>) 6. Light Loco(s) (<i>moving</i>) Code 1. Train(<i>units pulling</i>) 4. Car(s) (<i>moving</i>) 7. Light(s) (<i>standing</i>) 2. Train(<i>units pushing</i>) 5. Car(s) (<i>standing</i>) 8. Other (<i>specify in narrative</i>) N/A			
108. Vehicle Speed (<i>est. MPH at impact</i>) N/A				112. Position of Car Unit in N/A			
109. geographical Code 1. North 2. South 3. East 4. West N/A							

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT		FRA File # <u>HQ-2008-22</u>	
110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped		Code N/A		113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User	
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither		Code N/A		114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither	
114c. State here the name and quantity of the hazardous materials released, if any. N/A					
115. Type 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None		Code N/A		116. Signaled Crossing (See instructions for codes) Code N/A	
117. Whistle Ban 1. Yes 2. No 3. Unknown		Code N/A			
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach		Code N/A		119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown Code N/A	
120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown		Code N/A			
121. Age N/A		122. Driver's Gender 1. Male 2. Female Code N/A		123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown Code N/A	
124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop		Code N/A			
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown		Code N/A		126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed	
Casualties to:		Killed Injured		127. Driver 1. Killed 2. Injured 3. Uninjured Code N/A	
128. Was Driver in the Vehicle? 1. Yes 2. No		Code N/A			
129. Highway-Rail Crossing Users		N/A		130. Highway Vehicle Property Damage (est. dollar damage) N/A	
131. Total Number of Highway-Rail Crossing Users (include driver) N/A					
132. Locomotive Auxiliary Lights? 1. Yes 2. No		Code N/A		133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No	
134. Locomotive Headlight Illuminated? 1. Yes 2. No		Code N/A		135. Locomotive Audible Warning Sounded? 1. Yes 2. No	

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

U.S. Department of Transportation Federal Railroad Administration	FRA FACTUAL RAILROAD ACCIDENT REPORT	FRA File # HQ-2008-22
108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.		
		

137. SYNOPSIS OF THE ACCIDENT

On March 01, 2008, at 6:30 a.m. EST westbound Norfolk Southern (NS) freight Train 191G5-29 derailed 28 cars. The derailment occurred in Wilkinson County near the town of Tennille, Georgia (GA) at milepost (MP) 138.08 on the Savannah District Main Track. The Savannah District timetable speed is 45 miles per hour (mph), Federal Railroad Administration (FRA) Class 4 track.

There were no injuries reported to the crew members or evacuation ordered of any local citizens. One hazardous material hopper car involved in the derailment, NS 253159, containing Ammonium Nitrate leaked approximately 900 pounds of product. Damage estimates include \$695,750 for equipment and \$50,000 for track.

At the time of the derailment, it was clear and the temperature was 58 °F.

The probable cause of the accident is a broken rail - transverse/compound fissure at MP 138.08.

138. NARRATIVE

CIRCUMSTANCES PRIOR TO THE ACCIDENT

The crew of NS Train 191G5-29 consisted of a locomotive engineer and conductor. The crew went on duty on February 29, 2008 at 11:25 p.m. EST at the NS Nixon Yard Terminal. The crew received the required statutory off duty rest period according to the hours of service records prior to going on duty. The crew received consist paperwork at Nixon Yard, then boarded the mixed freight train on the west end of the yard at 2:45 a.m. NS Train 191G5-29 received a Class 2 train air brake test and departed Nixon Yard at 3:15 a.m. NS Train 191G5-29 departed the Nixon Yard limits with authority to occupy the Main Track on the Savannah Subdivision from MP 123.3 with 32 loads and 39 empties consisting of 5,240 tons and a length of 4,099 feet. NS Train 191G5-29 proceeded west to MP 138.08. The crew reported no exceptions to the train handling prior to MP 138.8.

THE ACCIDENT:

The engineer said as he approached MP 138.02 he noticed a piece of the rail missing in the track. The engineer then put the train into an emergency brake application. The crew reported when the lead Locomotive, NS 06609, went over the broken rail the trailing trucks of the locomotive shifted to the north. Twenty-eight cars in the train derailed. The lead and trailing locomotives stayed upright and the first 28 cars in the train turned over. The remaining cars of the 71 car train remained on the track. About 6:50 a.m., the engineer notified the NS train dispatcher by radio of the accident. The NS train dispatcher notified the proper authorities and Hulcher Derailment Services was called to the scene.

ANALYSIS AND CONCLUSION

ANALYSIS:

FRA obtained fatigue related information for the 10-day period preceding the incident including the 10-day work history (on duty/off duty cycles) for all of the employees involved.

CONCLUSION:

Upon analysis of that data, FRA Inspectors concluded that one or more of the employees may have been working at a diminished level of safety (effectiveness) due to mental and/or physical attributes associated with fatigue, however it would not have contributed to the cause of the accident.

ANALYSIS:

The investigation revealed that the train's recorder indicated a speed of 35 mph prior to an emergency brake application. No exceptions to train handling or braking operations were noted.

No toxicology test was required or administered by NS management.

The Main Track has a maximum speed of 49 mph. FRA Class 4 requires twice weekly track inspections by the railroad staff. The accident location was last inspected by an NS Track Inspector on February 29, 2008 and no exceptions were noted in the remedial action section of the report.

The 131 lb. rail was installed in 1939 by the Colorado Railroad. On January 7, 2007 HARSCO Technologies conducted an inspection of the tracks over this segment and noted no exceptions. On September 18, 2007 Sperry Rail Service ultrasonically tested this location for internal rail defects with no exceptions noted.

CONCLUSION:

At the accident scene, the NS Railroad Engineering Department recovered three sections of rail from the east side of the track that were broken due to internal rail defects. The first was a 42-1/2" long piece with a Transverse Fissure (TDT), the piece is marked "EAST". The fractured end showed receiving batter on the running surface of the head. The second piece was 29" long with a TDT at both ends, this piece is marked "MIDDLE". The third piece was 23-1/4" long with a TDT. All three pieces fit together from east, middle to west. The TDT matching the East to Middle rails revealed a 45% Detailed Fracture (TDD) with 20% normal growth, and 15% rapid growth. This TDD showed flange marks on the head of the rail consistent with an eastbound train moving over the defect.

The probable cause of the accident is a broken rail-Transverse Compound Fissure- at MP 138.08.