



***Federal Railroad Administration  
Office of Safety  
Headquarters Assigned  
Accident Investigation Report  
HQ-2008-28***

***Montana Rail Link (MRL)  
Bozeman, MT  
March 15, 2008***


***Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.***



DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2008-28</u>			
57. Trailing Tons ( <i>gross tonnage, excluding power units</i> )		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other ( <i>Specify in narrative</i> ) Code(s)		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter	
N/A						N/A N/A N/A N/A N/A		N/A	
59. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	
(1) First involved ( <i>derailed, struck, etc</i> )		0		0		N/A		Alcohol N/A	
(2) Causing ( <i>if mechanical cause reported</i> )		0		0		N/A		Drugs N/A	
62. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote		63. Cars	
(1) Total in Train		0		0 0		0 0		(1) Total in Equipment Consist	
(2) Total Derailed		0		0 0		0 0		(2) Total Derailed	
64. Equipment Damage This Consist		\$0.00		65. Track, Signal, Way, & Structure Damage		\$0.00		66. Primary Cause Code	
								N/A	
67. Contributing Cause Code								N/A	
Number of Crew Members								Length of Time on Duty	
68. Engineer/Operators		69. Firemen		70. Conductors		71. Brakemen		72. Engineer/Operator	
0		0		0		0		Hrs 0 Mi 0	
73. Conductor								Hrs 0 Mi 0	
Casualties to:		74. Railroad Employees		75. Train Passengers		76. Other		77. EOT Device?	
Fatal		0		0		0		1. Yes 2. No N/A	
Nonfatal		0		0		0		78. Was EOT Device Properly Armed?	
								1. Yes 2. No N/A	
								79. Caboose Occupied by Crew?	
								1. Yes 2. No N/A	
OPERATING TRAIN #3									
80. Type of Equipment Consist ( <i>single entry</i> )		1. Freight train		4. Work train		7. Yard/switching		A. Spec. MoW Equip. Code	
		2. Passenger train		5. Single car		8. Light loco(s).		N/A	
		3. Commuter train		6. Cut of cars		9. Maint./inspect.car		81. Was Equipment Attended?	
								1. Yes 2. No N/A	
83. Speed ( <i>recorded speed, if available</i> )		Code		85. Method(s) of Operation ( <i>enter code(s) that apply</i> )				85a. Remotely Controlled Locomotive?	
R - Recorded				a. ATCS		g. Automatic block		0 = Not a remotely controlled	
E - Estimated		N/A MPH 0		b. Auto train control		h. Current of traffic		1 = Remote control portable	
				c. Auto train stop		i. Time table/train orders		2 = Remote control tower	
				d. Cab		j. Track warrant control		3 = Remote control transmitter - more than one remote control transmitter	
				e. Traffic		k. Direct traffic control			
				f. Interlocking		l. Yard limits		N/A	
84. Trailing Tons ( <i>gross tonnage, excluding power units</i> )		N/A						N/A	
86. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	
(1) First involved ( <i>derailed, struck, etc</i> )		0		0		N/A		Alcohol N/A	
(2) Causing ( <i>if mechanical cause reported</i> )		0		0		N/A		Drugs N/A	
								88. Was this consist transporting passengers? (Y/N)	
								N/A	
89. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote		90. Cars	
(1) Total in Train		0		0 0		0 0		(1) Total in Equipment Consist	
(2) Total Derailed		0		0 0		0 0		(2) Total Derailed	
91. Equipment Damage This Consist		\$0.00		92. Track, Signal, Way, & Structure Damage		\$0.00		93. Primary Cause Code	
								N/A	
94. Contributing Cause Code								N/A	
Number of Crew Members								Length of Time on Duty	
95. Engineer/Operators		96. Firemen		97. Conductors		98. Brakemen		99. Engineer/Operator	
0		0		0		0		Hrs 0 Mi 0	
100. Conductor								Hrs 0 Mi 0	
Casualties to:		101. Railroad Employees		102. Train		103. Other		104. EOT	
Fatal		0		0		0		1. Yes 2. No N/A	
Nonfatal		0		0		0		105. Was EOT Device Properly	
								1. Yes 2. No N/A	
								106. Caboose Occupied by Crew?	
								1. Yes 2. No N/A	
Highway User Involved					Rail Equipment Involved				
107. C. Truck-Trailer. F. Bus J. Other Motor Vehicle Code					111. Equipment				
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian					3. Train ( <i>standing</i> ) 6. Light Loco(s) ( <i>moving</i> ) Code				
B. Truck E. Van H. Motorcycle M. Other ( <i>spec. in narrative</i> )					1. Train( <i>units pulling</i> ) 4. Car(s) ( <i>moving</i> ) 7. Light(s) ( <i>standing</i> )				
N/A					2. Train( <i>units pushing</i> ) 5. Car(s) ( <i>standing</i> ) 8. Other ( <i>specify in narrative</i> )				
108. Vehicle Speed ( <i>est. MPH at impact</i> )					112. Position of Car Unit in				
N/A					N/A				

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT		FRA File # <u>HQ-2008-28</u>	
110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped		Code N/A		113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User	
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither		Code N/A		114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither	
114c. State here the name and quantity of the hazardous materials released, if any. N/A					
115. Type 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None		Code N/A		116. Signaled Crossing (See instructions for codes)	
Code(s)		N/A		N/A	
117. Whistle Ban 1. Yes 2. No 3. Unknown		Code N/A			
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach		Code N/A		119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown	
120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown		Code N/A			
121. Age N/A		122. Driver's Gender 1. Male 2. Female		123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown	
Code N/A		Code N/A		124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop	
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown		Code N/A		126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed	
Casualties to:		Killed Injured		127. Driver 1. Killed 2. Injured 3. Uninjured	
128. Was Driver in the Vehicle? 1. Yes 2. No		Code N/A		129. Highway-Rail Crossing Users N/A	
130. Highway Vehicle Property Damage (est. dollar damage)		N/A		131. Total Number of Highway-Rail Crossing Users (include driver) N/A	
132. Locomotive Auxiliary Lights? 1. Yes 2. No		Code N/A		133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No	
134. Locomotive Headlight Illuminated? 1. Yes 2. No		Code N/A		135. Locomotive Audible Warning Sounded? 1. Yes 2. No	

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

On March 15, 2008 at 4:20 a.m. MDT westbound Montana Rail Link (MRL) Unit Coal Train CSCMCECO085 derailed on the MRL Second Subdivision about seven miles east of Bozeman, Montana at mile post 133.2. The train was traveling on a single main track at a speed of 25 mph. The maximum authorized timetable track speed at the accident site is 25 mph.

The train consisted of four locomotives, 115 loaded coal hopper cars, with 16,330 trailing tons and was 6,401 feet in length. A total of 25 cars, the 20th through the 44th, derailed. There were no injuries reported and no release of hazardous materials. The estimated damage of the derailment was \$110,000 to track & structures and \$1,728,552 for equipment.

At the time of the accident it was dark, cloudy and the temperature was 16 degrees F.

The probable cause of the accident was a broken rail.

138. NARRATIVE

CIRCUMSTANCES PRIOR TO THE ACCIDENT

On March 14, 2008, after completing more than the required statutory off duty rest period, a crew consisting of an engineer and assistant engineer (conductor) reported for duty at their home terminal at Laurel, Montana, at 11:00 p.m., MDT. The crew was assigned to operate an eastbound unit coal train from Laurel to Helena, Montana, a distance of about 239 miles.

The train consisted of four locomotives, 115 loaded rail hopper cars of coal, 16,330 trailing tons and 6,401 feet in length.

MRL Unit Coal Train CSCMCECO085 had received a 1,500 mile air brake inspection by MRL Carmen at Missoula, Montana, during its empty cycle on March 12, 2008.

According to the crew, the engineer performed a daily locomotive inspection before departing. The crew boarded the train and departed Laurel at 11:45 p.m. MDT.

The train approached the derailment area traveling geographically and timetable direction west. Timetable directions will be used throughout the report. The engineer was seated at the controls on the right (north) side of the leading locomotive and the conductor was seated on the left (south) side.

Approaching the accident site from the west at mile 132.2, there is in succession, tangent 728 feet in length, a 4-degree 4-minute curve to the left 1,100 feet in length, tangent 1,220 feet in length, a 8-degree .8-minute curve to the right 498 in length, tangent 330 feet in length, 7-degree 30-minute curve to the left 558 feet in length, tangent 258 feet in length, a 5-degree 4-minute curve to the right 588 feet to the point of derailment and 256 feet beyond. The grade at the accident area is 1.65 percent descending.

According to the crew the trip was uneventful as the train approached the accident area.

## THE ACCIDENT

As the train approached the accident site and at the time the accident occurred, the train was being operated at 25 mph. The speed was recorded by the event recorder located on controlling locomotive. In the accident area, trains operate on a single main track under the authority of a Traffic Control System (TCS) controlled by a dispatcher located in Missoula. The maximum authorized speed for freight trains is 25 mph as designated in the current MRL Timetable No. 14.

According to the train crew there was no observation of any unusual track condition approaching the accident area. The crew stated that the crew experienced an undesired train line induced emergency brake application of the train air brake system and came to a stop. After the train stopped the conductor left the locomotive to investigate. He observed and reported to the engineer that a portion of the train had derailed. The engineer immediately contacted the dispatcher and advised that the train was stopped and derailed.

## ANALYSIS AND CONCLUSIONS:

### ANALYSIS - D & A TESTING:

This accident met the criteria for 49 CFR Part 219 Subpart C Post Accident Toxicological Testing and the crew was tested.

### CONCLUSION:

The test results were negative.

### ANALYSIS - FATIGUE:

Federal Railroad Administration (FRA) obtained fatigue related information, for the 10-day period preceding this incident including the 10-day work history (on duty/off duty cycles) for all of the employees involved.

### CONCLUSION:

Upon analysis of that information FRA concluded that one or more of the employees may have been working at a diminished level of safety (effectiveness) due to mental and/or physical attributes associated with fatigue which may have contributed to the cause of the accident.

Analysis of the data from the lead locomotive event recorder shows the train traveling at a speed of 25 mph. The locomotives were producing retarding effort in dynamic brake position four. The air brakes were applied with a nine pound reduction of brake pipe pressure. The emergency brake application was caused by a train line induced application of the air brakes.

The FRA inspected the track inspection records for January, February, and March which revealed no defective track conditions in the accident area. The internal rail inspection records revealed the last inspection was conducted on January 30, 2008 and no rail defects were documented in the accident area. In 2006 the MRL installed crossties and surfaced the curve in the derailment area. In August of 2005, the MRL had transposed the north and south rails of the curve in the derailment area.

The FRA and MRL determined the rail broke due to a detailed fracture of the rail head caused by shelling, head checking and flaking near the surface of the rail head. The rail was manufactured by C F & I in 1989. The broken rail had evidence of impacting wheels at the POD. The broken rail was located on the high rail (south side) of the 5-degree 4-minute curve at milepost 133.2.

### PROBABLE CAUSE:

The probable cause was FRA Code T207-Broken rail-Detail fracture from shelling or head checking.