



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2007-26***

***Amtrak (ATK)
Riverbank, California
May 8, 2007***


Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2007-26</u>	
1. Name of Railroad Operating Train #1 Amtrak [ATK]			1a. Alphabetic Code ATK		1b. Railroad Accident/Incident No. 104320		
2. Name of Railroad Operating Train #2 N/A			2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A		
3. Name of Railroad Operating Train #3 N/A			3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A		
4. Name of Railroad Responsible for Track Maintenance: BNSF Rwy Co. [BNSF]			4a. Alphabetic Code BNSF		4b. Railroad Accident/Incident No. CA0507200		
5. U.S. DOT_AAR Grade Crossing Identification Number 028755B			6. Date of Accident/Incident Month 05 Day 08 Year 2007		7. Time of Accident/Incident 02:05: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM		
8. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction
					10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts		13. Other (describe in narrative) Code 07
9. Cars Carrying HAZMAT 0		10. HAZMAT Cars Damaged/Derailed N/A		11. Cars Releasing HAZMAT N/A		12. People Evacuated 0	
						13. Division California	
14. Nearest City/Town Riverbank			15. Milepost (to nearest tenth) 1094.5		16. State Abbr Code N/A CA		17. County STANISLAUS
18. Temperature (F) (specify if minus) 96 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark Code 2		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow Code 1		21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry Code 1	
22. Track Name/Number Main Track			23. FRA Track Class (1-9, X) Code 5		24. Annual Track Density (gross tons in millions) N/A		25. Time Table Direction Code 1. North 3. East 2. South 4. Code 4
OPERATING TRAIN #1							
26. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car	
						A. Spec. MoW Equip. Code 2	
						27. Was Equipment Attended? Code 1. Yes 2. No 1	
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 76 MPH R		31. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) e. Traffic k. Direct traffic control Code(s) f. Interlocking l. Yard limits e N/A N/A N/A N/A				31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
30. Trailing Tons (gross tonnage, excluding power units) 0							
32. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded (yes/no)	
(1) First involved (derailed, struck, etc)		ATK2011		1		N/A	
(2) Causing (if mechanical cause reported)		0		0		N/A	
						33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol Drugs N/A N/A	
						34. Was this consist transporting passengers? (Y/N) Y	
35. Locomotive Units		a. Head End		Mid Train		Rear End	
		b. Manual		c. Remote		d. Manual c. Remote	
(1) Total in Train		1		0		0	
(2) Total Derailed		0		0		0	
						36. Cars	
						a. Freight b. Pass. c. Freight d. Pass. e. Caboose	
						(1) Total in Equipment Consist	
						0 4 0 0 0	
						(2) Total Derailed	
						0 0 0 0 0	
37. Equipment Damage		11624.00		38. Track, Signal, Way, & Structure Damage		4000.00	
This Consist						39. Primary Cause Code M302	
						40. Contributing Cause Code N/A	
Number of Crew Members				Length of Time on Duty			
41. Engineer/Operators 1		42. Firemen 0		43. Conductors 2		44. Brakemen 0	
						45. Engineer/Operator Hrs 7 Mi 45	
Casualties to:		47. Railroad Employees		48. Train Passengers		49. Other	
Fatal		0		0		6	
Nonfatal		0		0		0	
						50. EOT Device? 1. Yes 2. No 2	
						51. Was EOT Device Properly Armed? 1. Yes 2. No N/A	
						52. Caboose Occupied by Crew? 1. Yes 2. No N/A	
OPERATING TRAIN #2							
53. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car	
						A. Spec. MoW Equip. Code N/A	
						54. Was Equipment Attended? Code 1. Yes 2. No N/A	
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A		58. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track				58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2007-26</u>	
57. Trailing Tons (gross tonnage, excluding power units) <div style="text-align: right;">0</div>		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s) <div style="display: flex; justify-content: space-around;"><div>N/A</div><div>N/A</div><div>N/A</div><div>N/A</div><div>N/A</div></div>	
						2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter <div style="text-align: right;">N/A</div>	
59. Principal Car/Unit (1) First involved (derailed, struck, etc) <div style="text-align: right;">0</div>		a. Initial and Number <div style="text-align: right;">0</div>		b. Position in Train <div style="text-align: right;">0</div>		c. Loaded(yes/no) <div style="text-align: right;">N/A</div>	
(2) Causing (if mechanical cause reported) <div style="text-align: right;">0</div>						60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. <div style="display: flex; justify-content: space-around;"><div>Alcohol N/A</div><div>Drugs N/A</div></div>	
						61. Was this consist transporting passengers? (Y/N) <div style="text-align: right;">N/A</div>	
62. Locomotive Units (1) Total in Train <div style="text-align: right;">0</div>		a. Head End <div style="text-align: right;">0</div>		Mid Train b. Manual <div style="text-align: right;">0</div> c. Remote <div style="text-align: right;">0</div>		Rear End d. Manual <div style="text-align: right;">0</div> e. Remote <div style="text-align: right;">0</div>	
(2) Total Derailed <div style="text-align: right;">0</div>						63. Cars (1) Total in Equipment Consist <div style="text-align: right;">0</div>	
						Loaded a. Freight <div style="text-align: right;">0</div> b. Pass. <div style="text-align: right;">0</div>	
						Empty c. Freight <div style="text-align: right;">0</div> d. Pass. <div style="text-align: right;">0</div>	
						e. Caboose <div style="text-align: right;">0</div>	
64. Equipment Damage This Consist <div style="text-align: right;">0</div>		65. Track, Signal, Way, & Structure Damage <div style="text-align: right;">0</div>		66. Primary Cause Code <div style="text-align: right;">N/A</div>		67. Contributing Cause Code <div style="text-align: right;">N/A</div>	
Number of Crew Members				Length of Time on Duty			
68. Engineer/Operators <div style="text-align: right;">0</div>		69. Firemen <div style="text-align: right;">0</div>		70. Conductors <div style="text-align: right;">0</div>		71. Brakemen <div style="text-align: right;">0</div>	
72. Engineer/Operator Hrs <div style="text-align: right;">0</div> Mi <div style="text-align: right;">0</div>		73. Conductor Hrs <div style="text-align: right;">0</div> Mi <div style="text-align: right;">0</div>					
Casualties to:		74. Railroad Employees		75. Train Passengers		76. Other	
Fatal <div style="text-align: right;">0</div>		<div style="text-align: right;">0</div>		<div style="text-align: right;">0</div>		77. EOT Device? 1. Yes 2. No <div style="text-align: right;">N/A</div>	
Nonfatal <div style="text-align: right;">0</div>		<div style="text-align: right;">0</div>		<div style="text-align: right;">0</div>		78. Was EOT Device Properly Armed? 1. Yes 2. No <div style="text-align: right;">N/A</div>	
						79. Caboose Occupied by Crew? 1. Yes 2. No <div style="text-align: right;">N/A</div>	
OPERATING TRAIN #3							
80. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car	
						A. Spec. MoW Equip. Code <div style="text-align: right;">N/A</div>	
						81. Was Equipment Attended? 1. Yes 2. No <div style="text-align: right;">N/A</div>	
						82. Train Number/Symbol <div style="text-align: right;">N/A</div>	
83. Speed (recorded speed, if available) R - Recorded E - Estimated <div style="text-align: right;">N/A</div> MPH <div style="text-align: right;">0</div>		85. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking		g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) <div style="display: flex; justify-content: space-around;"><div>N/A</div><div>N/A</div><div>N/A</div><div>N/A</div><div>N/A</div></div>	
84. Trailing Tons (gross tonnage, excluding power units) <div style="text-align: right;">0</div>						85a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter <div style="text-align: right;">N/A</div>	
86. Principal Car/Unit (1) First involved (derailed, struck, etc) <div style="text-align: right;">0</div>		a. Initial and Number <div style="text-align: right;">0</div>		b. Position in Train <div style="text-align: right;">0</div>		c. Loaded(yes/no) <div style="text-align: right;">N/A</div>	
(2) Causing (if mechanical cause reported) <div style="text-align: right;">0</div>						87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. <div style="display: flex; justify-content: space-around;"><div>Alcohol N/A</div><div>Drugs N/A</div></div>	
						88. Was this consist transporting passengers? (Y/N) <div style="text-align: right;">N/A</div>	
89. Locomotive Units (1) Total in Train <div style="text-align: right;">0</div>		a. Head End <div style="text-align: right;">0</div>		Mid Train b. Manual <div style="text-align: right;">0</div> c. Remote <div style="text-align: right;">0</div>		Rear End d. Manual <div style="text-align: right;">0</div> e. Remote <div style="text-align: right;">0</div>	
(2) Total Derailed <div style="text-align: right;">0</div>						90. Cars (1) Total in Equipment Consist <div style="text-align: right;">0</div>	
						Loaded a. Freight <div style="text-align: right;">0</div> b. Pass. <div style="text-align: right;">0</div>	
						Empty c. Freight <div style="text-align: right;">0</div> d. Pass. <div style="text-align: right;">0</div>	
						e. Caboose <div style="text-align: right;">0</div>	
91. Equipment Damage This Consist <div style="text-align: right;">0</div>		92. Track, Signal, Way, & Structure Damage <div style="text-align: right;">0</div>		93. Primary Cause Code <div style="text-align: right;">N/A</div>		94. Contributing Cause Code <div style="text-align: right;">N/A</div>	
Number of Crew Members				Length of Time on Duty			
95. Engineer/Operators <div style="text-align: right;">0</div>		96. Firemen <div style="text-align: right;">0</div>		97. Conductors <div style="text-align: right;">0</div>		98. Brakemen <div style="text-align: right;">0</div>	
99. Engineer/Operator Hrs <div style="text-align: right;">0</div> Mi <div style="text-align: right;">0</div>		100. Conductor Hrs <div style="text-align: right;">N/A</div> Mi <div style="text-align: right;">0</div>					
Casualties to:		101. Railroad Employees		102. Train		103. Other	
Fatal <div style="text-align: right;">0</div>		<div style="text-align: right;">0</div>		<div style="text-align: right;">0</div>		104. EOT 1. Yes 2. No <div style="text-align: right;">N/A</div>	
Nonfatal <div style="text-align: right;">0</div>		<div style="text-align: right;">0</div>		<div style="text-align: right;">0</div>		105. Was EOT Device Properly 1. Yes 2. No <div style="text-align: right;">N/A</div>	
						106. Caboose Occupied by Crew? 1. Yes 2. No <div style="text-align: right;">N/A</div>	
Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer. F. Bus J. Other Motor Vehicle Code A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative) <div style="text-align: right;">J</div>				111. Equipment 3. Train (standing) 6. Light Loco(s) (moving) Code 1. Train(units pulling) 4. Car(s) (moving) 7. Light(s) (standing) 2. Train(units pushing) 5. Car(s) (standing) 8. Other (specify in narrative) <div style="text-align: right;">1</div>			
108. Vehicle Speed (est. MPH at impact) <div style="text-align: right;">N/A</div>				112. Position of Car Unit in <div style="text-align: right;">1</div>			
109. geographical 1. North 2. South 3. East 4. West <div style="text-align: right;">3</div>							

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT		FRA File # <u>HQ-2007-26</u>	
110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped		Code 3		113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User	
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither		Code 4		114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither	
114c. State here the name and quantity of the hazardous materials released, if any. N/A					
115. Type Crossing 1. Gates 4. Wig Wags 7. Crossbucks 10. Flagged by crew Warning 2. Cantilever FLS 5. Hwy. traffic signals 8. Stop signs 11. Other (spec. in narr.) 3. Standard FLS 6. Audible 9. Watchman 12. None		Code 01		116. Signaled Crossing (See instructions for codes)	
Code(s) 05 N/A N/A N/A N/A N/A				117. Whistle 1. Yes 2. No 3. Unknown	
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach		Code 1		119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown	
121. Age 23		122. Driver's Gender 1. Male 2. Female		Code 2	
123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown		Code 2		124. Driver 1. Drove around or thru the Gate 4. Stopped on Crossing 2. Stopped and then Proceeded 5. Other (specify in 3. Did not Stop narrative)	
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown		Code 2		126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative) 2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed	
Casualties to:		Killed	Injured	127. Driver 1. Killed 2. Injured 3. Uninjured	
		6	0	Code 1	
129. Highway-Rail Crossing Users		6		130. Highway Vehicle Property Damage (est. dollar damage) 7000	
132. Locomotive Auxiliary Lights? 1. Yes 2. No		Code 1		133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No	
134. Locomotive Headlight Illuminated? 1. Yes 2. No		Code 1		135. Locomotive Audible Warning Sounded? 1. Yes 2. No	
				Code 1	
				131. Total Number of Highway-Rail Crossing Users (include driver) 6	

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

On May 8, 2007, at approximately 2:05 p.m. PDT, a northbound (timetable west) Amtrak (ATK) passenger train 713 operating locomotive forward, collided with a sports utility vehicle (SUV) at a highway-rail grade crossing. The accident occurred at Claribel Road, milepost 1094.5, located near Riverbank, California, on BNSF's Stockton Subdivision.

All six occupants of the vehicle were killed and the SUV completely destroyed. There were no injuries to the train crew or passengers, no derailment, and no hazardous materials involved. The lead locomotive sustained minor front end damage.

For the purposes of this report, geographical directions will be used.

At the time of the accident it was daylight and clear. The temperature was about 96 degrees F.

Damages were estimated as: \$11,624, equipment; \$4,000 track, signals and structures.

FRA concludes the cause of the accident was the failure of the motor vehicle operator to yield the right of way to the approaching train.

138. NARRATIVE

Circumstances Prior to the Accident

The train crew of ATK 713 consisted of a locomotive engineer, conductor, and assistant conductor. After receiving his statutory off-duty period, the engineer reported for duty at the ATK facility in Oakland, California, on May 8, 2007. He departed Oakland at 7:30 a.m. PDT on train 712, and arrived in Merced, California, at 10:48 a.m., and waited there on-duty until he relieved the engineer on train 713 at 1:22 p.m. After receiving their statutory off-duty period, the conductor and assistant conductor went on duty at 8:45 a.m., and 9:15 a.m. respectively, at Bakersfield, California, May 8, 2007. The train had received an initial terminal air brake test and departed Bakersfield at 10:15 a.m. The train assigned to the crew consisted of a locomotive, baggage car, coach car, diner car, and a cab car. The train was scheduled to travel to Oakland and was operated with the locomotive forward.

Traffic Control governs train movements on this section of railroad, and trains are controlled by a BNSF Dispatcher in San Bernardino, California. This section of the railroad operates in a timetable east-west direction. For the purposes of this report, geographical directions are used to coincide with police reports.

According to the engineer, the train was traveling north (timetable west) at approximately 79 mph as it approached Claribel Road highway-rail grade crossing. The locomotive engineer was seated at the controls and the conductor and assistant conductor were located in the train. Approaching Claribel Road from the south, the track is tangent and nearly level. The maximum authorized timetable speed for passenger train movement is 79 mph. The railroad has a whistle sign in place 1,332 feet south of the crossing. The engineer began sounding the whistle when the train neared this sign. This was later validated by analysis of the event recorder.

A 2001 Chevrolet Tracker SUV driven by a 23-year old female driver, with five other passengers, was proceeding eastbound on Claribel Road towards the highway-rail grade crossing when it encountered a stop sign and overhead four-way flashing traffic light at the intersection of Terminal Avenue and Claribel Road. According to the California Highway Patrol, eastbound vehicular traffic was stopped at the stop sign and overhead four-way flashing red signal at the intersection of Terminal Avenue and Claribel Road located about 44 feet east of the track. Witnesses reported that the driver had pulled onto and fouled the track, and apparently noticed the train approaching. The driver placed the vehicle in reverse and backed up to clear the track. At this time, the active warning devices activated. As the gate descended, it struck the hood of the car and the driver drove forward into the path of the train.

The Accident

As it approached the accident site, ATK 713 was traveling at 78 mph, as indicated by the event recorder. The engineer stated that approximately one mile away, he noticed that automobile traffic was backed up at the intersection of Claribel Road and Terminal Avenue, and that the subject SUV was sitting on top of the crossing, fouling the track. The engineer noticed that the same SUV began to back up, as if the driver had noticed the train's presence and prepared to clear for the train. The automobile was well within clearance of his train when the #2 (or west) gate lowered onto the automobile. When the train

was approximately 2 car lengths away from the crossing , the driver of the SUV pulled forward onto the main track, at which time the engineer initiated an emergency brake application.

The lead locomotive struck the middle of the SUV as the vehicle was moving across the highway-rail grade crossing and pushed it along the track in a northward direction until it came to a stop 1,930 feet beyond the point of impact. The driver of the SUV was ejected from the vehicle on impact.

Post-Accident Investigation

The driver of the SUV and its five occupants were fatally injured and pronounced dead at the scene of the accident. The Stanislaus County Coroner listed massive blunt force, traumatic, and cranio-cerebral injuries as the causes of death.

Post-accident inspections and tests performed on lead locomotive ATK 2011 revealed minor damage to the snow plow and a broken auxiliary light. The locomotive bell, horn, sanders, air brake apparatus, and operating lights were in working condition. The information from the locomotive's event recorder was downloaded and analyzed. The information indicated that the passenger train was traveling at 76 mph at the time of impact.

Shortly after the accident, employees of the BNSF signal department arrived on the scene and conducted operational tests to determine if the highway-rail grade crossing warning system functioned as intended. Post- accident testing indicated that the system was detecting the presence of trains and providing adequate warning time for motorist.

Analysis and Conclusions

Analysis

The driver was a 23-year old female. The other five occupants of the vehicle were two females, ages 40 and 19, and three male children, two 5-year olds and a 3-year old. The Stanislaus County Coroner performed a post-mortem test for alcohol on the driver. The results were negative.

Claribel Road is an east/west paved 24-foot wide road that crosses the BNSF single main line track at a near 90 degree angle. It has one traffic lane for each direction of vehicle traffic with a posted speed limit of 45 mph. The method of operation is by signal indication of a Traffic Control System (TCS). The warning system consists of two standard five-inch diameter signal masts located near the edge of the roadway on each side of the main track. Attached to each mast is a crossbuck, a 12-inch flashing light unit, an audible bell, and gate arm. A Safetran Grade Crossing Predictor (GCP 3000 D2) provides train detection on an approach circuit sufficient to allow at least twenty-five seconds warning time during train movements. Claribel Road's DOT/AAR Inventory Number is 028755B.

The active warning devices were tested by the BNSF signal department in the presence of a FRA Signal & Train Control inspector. The devices functioned as intended and were in full compliance with Federal regulations. Event information retrieved from the GCP 3000 D2 was downloaded and analyzed. The download revealed a warning time of 27 seconds.

The lead locomotive was equipped with a headlight, auxiliary lights, and the audible warning device. The ATK Road Foreman, who accompanied the train to destination in Oakland, stated that these devices functioned as intended and were in full compliance with Federal requirements.

The locomotive was also equipped with a speed indicator and an event recorder as required. The relevant event recorder data was downloaded by the mechanical department when the train arrived in Oakland. The analysis disclosed that the locomotive engineer was in compliance with all railroad operating and train handling requirements. FRA reviewed the results of this analysis and concurred with the conclusions.

Conclusions

The railroad was in compliance with their own and applicable Federal standards. A review of records relating to the inspection and maintenance of the signal system and grade crossing warning devices indicated they functioned as intended and provided adequate warning to the motorists. There were no mechanical defects on the equipment that would have contributed to the accident.

Probable Cause

FRA concludes the cause of the accident was the failure of the motor vehicle operator to yield the right of way to the approaching train.