



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2007-35***

***Union Pacific (UP)
Groesbeck, Texas
June 10, 2007***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2007-35</u>	
1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP]			1a. Alphabetic Code UP		1b. Railroad Accident/Incident No. 0607FW012		
2. Name of Railroad Operating Train #2 N/A			2a. Alphabetic Code N/A		2b. Railroad Accident/Incident No. N/A		
3. Name of Railroad Operating Train #3 N/A			3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A		
4. Name of Railroad Responsible for Track Maintenance: Union Pacific RR Co. [UP]			4a. Alphabetic Code UP		4b. Railroad Accident/Incident No. 0607FW012		
5. U.S. DOT_AAR Grade Crossing Identification Number			6. Date of Accident/Incident Month 06 Day 10 Year 2007		7. Time of Accident/Incident 04:14: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM		
8. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction
					10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts		13. Other (describe in narrative) Code 01
9. Cars Carrying HAZMAT 1		10. HAZMAT Cars Damaged/Derailed N/A		11. Cars Releasing HAZMAT N/A		12. People Evacuated 0	
14. Nearest City/Town Groesbeck			15. Milepost (to nearest tenth) 174.6		16. State Abbr Code N/A TX		17. County LIMESTONE
18. Temperature (F) (specify if minus) 71 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1		21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1	
22. Track Name/Number Single Main			23. FRA Track Class (1-9, X) Code 4		24. Annual Track Density (gross tons in millions) 43.95		25. Time Table Direction Code 1. North 3. East 2. South 4. 2
OPERATING TRAIN #1							
26. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car	
				A. Spec. MoW Equip. Code 1		27. Was Equipment Attended? Code 1. Yes 2. No 1	
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 40 MPH R		31. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) e. Traffic k. Direct traffic control Code(s) f. Interlocking l. Yard limits g j N/A N/A N/A				31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
30. Trailing Tons (gross tonnage, excluding power units) 7601							
32. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded (yes/no)	
(1) First involved (derailed, struck, etc)		UP354634		29		no	
(2) Causing (if mechanical cause reported)		0		0		N/A	
		33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol Drugs N/A N/A					
		34. Was this consist transporting passengers? (Y/N) N					
35. Locomotive Units		a. Head End		Mid Train		Rear End	
		b. Manual		c. Remote		d. Manual c. Remote	
(1) Total in Train		3		0		0	
(2) Total Derailed		0		0		0	
36. Cars		a. Freight		b. Pass.		c. Freight d. Pass. e. Caboose	
(1) Total in Equipment Consist		47		0		58	
(2) Total Derailed		0		0		32	
37. Equipment Damage This Consist		796783		38. Track, Signal, Way, & Structure Damage		134343	
39. Primary Cause Code		H504		40. Contributing Cause Code		N/A	
Number of Crew Members				Length of Time on Duty			
41. Engineer/Operators 1		42. Firemen 0		43. Conductors 1		44. Brakemen 0	
45. Engineer/Operator Hrs 3 Mi 54		46. Conductor Hrs 3 Mi 54					
Casualties to:		47. Railroad Employees		48. Train Passengers		49. Other	
Fatal		0		0		0	
Nonfatal		0		0		0	
50. EOT Device? 1. Yes 2. No 1		51. Was EOT Device Properly Armed? 1. Yes 2. No 1		52. Caboose Occupied by Crew? 1. Yes 2. No 2			
OPERATING TRAIN #2							
53. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car	
				A. Spec. MoW Equip. Code N/A		54. Was Equipment Attended? Code 1. Yes 2. No N/A	
55. Train Number/Symbol N/A							
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A		58. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track				58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2007-35</u>	
57. Trailing Tons (gross tonnage, excluding power units) <div style="text-align: right;">0</div>		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s) <div style="display: flex; justify-content: space-around; font-size: small;"> <div>N/A</div> <div>N/A</div> <div>N/A</div> <div>N/A</div> <div>N/A</div> </div>	
						2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter <div style="text-align: right;">N/A</div>	
59. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)	
(1) First involved (derailed, struck, etc)		0		0		N/A	
(2) Causing (if mechanical cause reported)		0		0		N/A	
						60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. <div style="display: flex; justify-content: space-around; font-size: small;"> <div>Alcohol</div> <div>Drugs</div> </div> <div style="display: flex; justify-content: space-around; font-size: small;"> <div>N/A</div> <div>N/A</div> </div>	
						61. Was this consist transporting passengers? (Y/N) <div style="text-align: right;">N/A</div>	
62. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote	
(1) Total in Train		0		0		0	
(2) Total Derailed		0		0		0	
64. Equipment Damage This Consist		0		65. Track, Signal, Way, & Structure Damage		0	
						66. Primary Cause Code N/A	
						67. Contributing Cause Code N/A	
						Length of Time on Duty	
68. Engineer/Operators		69. Firemen		70. Conductors		71. Brakemen	
0		0		0		0	
Casualties to:		74. Railroad Employees		75. Train Passengers		76. Other	
Fatal		0		0		0	
Nonfatal		0		0		0	
						77. EOT Device? 1. Yes 2. No N/A	
						78. Was EOT Device Properly Armed? 1. Yes 2. No N/A	
						79. Caboose Occupied by Crew? 1. Yes 2. No N/A	
OPERATING TRAIN #3							
80. Type of Equipment Consist (single entry)		1. Freight train		4. Work train		7. Yard/switching	
		2. Passenger train		5. Single car		8. Light loco(s).	
		3. Commuter train		6. Cut of cars		9. Maint./inspect.car	
						A. Spec. MoW Equip. Code N/A	
						81. Was Equipment Attended? 1. Yes 2. No N/A	
						82. Train Number/Symbol N/A	
83. Speed (recorded speed, if available) R - Recorded E - Estimated N/A MPH		0		85. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking		g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	
						m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) <div style="display: flex; justify-content: space-around; font-size: small;"> <div>N/A</div> <div>N/A</div> <div>N/A</div> <div>N/A</div> <div>N/A</div> </div>	
84. Trailing Tons (gross tonnage, excluding power units) <div style="text-align: right;">0</div>						85a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter <div style="text-align: right;">N/A</div>	
86. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)	
(1) First involved (derailed, struck, etc)		0		0		N/A	
(2) Causing (if mechanical cause reported)		0		0		N/A	
						87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. <div style="display: flex; justify-content: space-around; font-size: small;"> <div>Alcohol</div> <div>Drugs</div> </div> <div style="display: flex; justify-content: space-around; font-size: small;"> <div>N/A</div> <div>N/A</div> </div>	
						88. Was this consist transporting passengers? (Y/N) <div style="text-align: right;">N/A</div>	
89. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote	
(1) Total in Train		0		0		0	
(2) Total Derailed		0		0		0	
91. Equipment Damage This Consist		0		92. Track, Signal, Way, & Structure Damage		0	
						93. Primary Cause Code N/A	
						94. Contributing Cause Code N/A	
						Length of Time on Duty	
95. Engineer/Operators		96. Firemen		97. Conductors		98. Brakemen	
0		0		0		0	
Casualties to:		101. Railroad Employees		102. Train		103. Other	
Fatal		0		0		0	
Nonfatal		0		0		0	
						104. EOT 1. Yes 2. No N/A	
						105. Was EOT Device Properly 1. Yes 2. No N/A	
						106. Caboose Occupied by Crew? 1. Yes 2. No N/A	
Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer. F. Bus J. Other Motor Vehicle Code A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative) N/A				111. Equipment 3. Train (standing) 6. Light Loco(s) (moving) Code 1. Train(units pulling) 4. Car(s) (moving) 7. Light(s) (standing) 2. Train(units pushing) 5. Car(s) (standing) 8. Other (specify in narrative) N/A			
108. Vehicle Speed (est. MPH at impact) N/A				112. Position of Car Unit in N/A			
109. geographical Code 1. North 2. South 3. East 4. West N/A							

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2007-35</u>	
110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A			
113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A			
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A			
114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A			
114c. State here the name and quantity of the hazardous materials released, if any. N/A							
115. Type 1. Gates 4. Wig Wags 7. Crossbucks 10. Flagged by crew Crossing 2. Cantilever FLS 5. Hwy. traffic signals 8. Stop signs 11. Other (spec. in narr.) Warning 3. Standard FLS 6. Audible 9. Watchman 12. None				116. Signaled Crossing (See instructions for codes)		117. Whistle 1. Yes 2. No 3. Unknown	
Code(s) N/A N/A N/A N/A N/A N/A N/A				N/A		N/A	
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A		119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown	
120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown				Code N/A		N/A	
121. Age 0		122. Driver's Gender 1. Male 2. Female		Code N/A		123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown	
124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop		4. Stopped on Crossing 5. Other (specify in narrative)		Code N/A		N/A	
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A		126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative) 2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed	
Casualties to: Killed Injured				0 0		127. Driver 1. Killed 2. Injured 3. Uninjured	
128. Was Driver in the Vehicle? 1. Yes 2. No				Code N/A		N/A	
129. Highway-Rail Crossing Users 0				130. Highway Vehicle Property Damage (est. dollar damage) 0		131. Total Number of Highway-Rail Crossing Users (include driver) 0	
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A		133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No	
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A		135. Locomotive Audible Warning Sounded? 1. Yes 2. No	
136. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A		N/A	

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

U.S. Department of Transportation
Federal Railroad Administration

FRA FACTUAL RAILROAD ACCIDENT REPORT

FRA File # HQ-2007-35

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC. INVOLVED.

3 cars derailed upright

CSXT 161674

CSXT 161507

CSXT 161280

CSXT 160015

ADK 19180

CSXT 172743

CSXT 160187

CSXT 173287

CSXT 160161

CSXT 160074

CSXT 161760

CSXT 160021

UP 560300

UP 369158

CSXT 160236

CSXT 172525

CSXT 161400

UP 560342

ADK 19198

CSXT 161270

CSXT 161693

CSXT 161274

CSXT 160116

UP 369154

15 Car Gap

8 Cars derailed parallel to track

CSXT 173069

NYC 278113

NYC 278049

NYC 277366

NYC 216659

CSXT 173219

CSXT 161389

UP 354634

County Rd 412

137. SYNOPSIS OF THE ACCIDENT

On June 10, 2007, at 4:14 a.m. (CST), a southbound Union Pacific freight train, MFWMX 09, derailed at UP Milepost 174.65 on the Ennis Subdivision of the Fort Worth Service Unit. This is a rural area located 5.1 miles north of Groesbeck, TX. Thirty-two cars of the 105 car train derailed, no hazardous cars were involved, nor were there any injuries. The twenty-ninth thru the sixtieth cars behind the three locomotives derailed, all were empty.

At the time of the accident it was dark and clear. The temperature was 71 degrees F.

The cost of the derailment is listed at \$931,126 (\$796,783 to equipment, \$134,343 to track)

The cause of the derailment was due to buffing or slack action excessive, train make-up, FRA cause code H504.

138. NARRATIVE

Circumstances Prior to the Accident:

The initial crew of train MFWMX 09 included a locomotive engineer and a conductor, who went on duty at 9:30 a.m. CST, June 9, 2007 at Fort Worth, TX. Fort Worth is a home terminal for both crew members. Both crew members had received more than the statutory off duty rest period prior to reporting for duty.

The train, which consisted of three locomotives and 106 freight cars, was scheduled to travel from Fort Worth, TX. to Laredo, TX.. The train received a Train Air Brake test at Fort Worth, TX. at 8:54 a.m. June 9, 2007 by qualified mechanical inspectors and no exceptions were taken. The train's EOT (UPRQ29534) was also inspected at Fort Worth at 8:54 a.m. June 9, 2007.

After departing Fort Worth the train proceeded south on the Midlothian Subdivision. A bad order car was set out at Bisbee Siding UP Milepost 40.10. Local train 45, which was following train MFWMX 09, observed the track out of alignment at UP Milepost 29.95, the crew on MFWMX 09 did not see any alignment irregularity prior to their passing over this location. Between UP Milepost 31 and UP Milepost 30, MFWMX had ascended a .98 percent grade and was descending a 1.07 percent grade. The track in this location is tangent. Local transportation officials conducted a download of Engine UP 4631, at the request of the Manager of Track Maintenance, and there was evidence of a run in of the rear of the train. The train was stopped by the Hot Box Detector at UP Milepost 6.5 on the Midlothian Subdivision for hot axles on the six rear cars. There was no exception taken when these cars were inspected by the conductor. The train then entered the Ennis Subdivision at Garrett Jct. UP Milepost 233.55. The train went into emergency at UP Milepost 229, and a bad order air hose was found and repaired by a local transportation official. The train then proceeded to UP Milepost 177.8, where the train was stopped because the crew had reached the maximum hours they could be on duty.

The relief crew for MFWMX 09 included an engineer and conductor. The crew went on duty at 12:20 a.m. CST at Hearne, TX. Hearne is a home terminal for both crew members. Both crew members had received more than the statutory off duty rest period, prior to reporting for duty. The train crew's assigned freight train consisted of three locomotives, 47 loaded and 58 empty cars of mixed types. The train was 6737 feet long and weighed 7601 tons.

According to the conductors report, the crew showed being on the train, located at milepost 177.8, at 4 a.m. CST.

As the Southward train approached the accident area, the locomotive engineer was seated at the controls on the West side of the leading locomotive. The conductor was seated on the East side of the leading locomotive.

The grade of the railroad at the point of derailment is level with a 0.36 percent descending grade as you approach this area from the north and a 1.14 percent ascending grade as you continue south from the point of derailment. The track in this area is tangent.

The railroad time table direction of the train was south. The geographic direction of the train was southwest. The Timetable

directions will be used throughout the report.

As indicated by Union Pacific RR Co. Dallas/Ft. Worth Area Timetable No. 2, the method of operation at milepost 174.6 of the Ennis Subdivision was TWC/ABS, Track Warrant Control and Automatic Block Signal.

The weather was reported as dark and clear. The temperature was 71 degrees F.

The Accident:

The crew proceeded southward from milepost 177.8 and gradually increased the speed of the train to 45 mph. The maximum authorized speed for this segment of track is 60 mph per Ennis Subdivision General Order No. 28.

The engineer was approaching a slow order at milepost 173.25, traveling about 45 mph, and placed the train in full dynamic brake. The speed of the train was reduced to 40 mph, but went into emergency application. Both speeds were recorded by the event recorder of the lead engine. The train then came to a smooth abrupt stop. When the air would not build up on the rear of the train, the conductor began to walk back and discovered the derailed cars. He continued to walk back toward the rear of the train and found 32 cars derailed, lines forty-six through seventy-seven on their consist.

Analysis:

The train was equipped with a speed indicator and an event recorder as required. The relevant event recorder data was downloaded by the Manager Train Operations at the accident site, and analyzed by the Manager Operating Practices. The train crew was administered a Post Accident Toxicology Test. Track geometry measurements were taken by the Director Track Maintenance and the Manager Track Maintenance. Investigating the cause of the derailment, it was determined that as the train proceeded southward, the head end was ascending a 1.14 percent grade and the rear of the train was still on a 0.36 percent descending grade. Upon examining the train consist it was noted that 37 of the rear 44 cars were loads, 51.5 percent of the train's tonnage, was behind 47 empty cars. 32 of the 47 empty cars derailed. The force of the loaded cars against the middle of the train caused excessive lateral forces, causing the rail to tip out and allowed the wheels of the UP 354634 to derail.

FRA uses an overall effectiveness rate of 77.5 as the baseline for fatigue analysis, which is equivalent to a blood alcohol content (BAC) of 0.05. At or above this baseline, we do not consider fatigue as probable for any employee. Software sleep settings vary according to information obtained from each employee. If an employee does not provide sleep information, FRA uses default software settings.

FRA obtained fatigue related information, including a 10-day work history, for 1 employee involved in this accident, the engineer of MFWMX 09. While the fatigue analysis indicated that this employee was operating at a fatigue rating of 67%, FRA does not believe fatigue was a contributing factor in this accident.

Conclusions:

Toxicology Tests for both crew members had negative test results. Track geometry measurements were within FRA Standards. The locomotive engineer was in compliance with all applicable railroad operating and train handling requirements. The relevant event recorder data showed identical train speed indications when the train was put into dynamic brake, both on the track alignment problem on the Midlothian Sub and the derailment on the Ennis Subdivision. When the train went into full dynamic brake, the rear of the train, which consisted of the majority of the loads, ran in on the middle of the train, which were all empty cars.

Probable Cause and Contributing Factors

Based on the information from the derailment investigation by the FRA and the previous incident that occurred with MFWMX