



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2006-13***


***Union Pacific (UP)
Yukon, Oklahoma
March 7, 2006***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2006-13</u>	
1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP]				1a. Alphabetic Code UP		1b. Railroad Accident/Incident No. 0306WH005	
2. Name of Railroad Operating Train #2 N/A				2a. Alphabetic Code N/A		2b. Railroad Accident/Incident N/A	
3. Name of Railroad Responsible for Track Maintenance: N/A				3a. Alphabetic Code UP		3b. Railroad Accident/Incident No. N/A	
4. U.S. DOT_AAR Grade Crossing Identification Number 596844H				5. Date of Accident/Incident Month Day Year 03 07 2006		6. Time of Accident/Incident 09:47: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM	
7. Type of Accident/Incident (single entry in code box)							
1. Derailment		4. Side collision		7. Hwy-rail crossing		10. Explosion-detonation	
2. Head on collision		5. Raking collision		8. RR grade crossing		11. Fire/violent rupture	
3. Rear end collision		6. Broken Train collision		9. Obstruction		12. Other impacts	
						13. Other (describe in narrative) 07	
8. Cars Carrying HAZMAT 0		9. HAZMAT Cars Damaged/Derailed 0		10. Cars Releasing HAZMAT 0		11. People Evacuated 0	
						12. Division Wichita	
13. Nearest City/Town Yukon				14. Milepost (to nearest tenth) 503.7		15. State Abbr Code N/A OK	
16. County CANADIAN							
17. Temperature (F) (specify if minus) 68 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1	
21. Track Name/Number Single main				22. FRA Track Code Class (1-9, X) 4		23. Annual Track Density (gross tons in millions) 5.00	
						24. Time Table Direction Code 1. North 3. East 3	
OPERATING TRAIN #1							
25. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching		A. Spec. MoW Equip. Code		26. Was Equipment Attended? Code	
2. Passenger train 5. Single car 8. Light loco(s).		3. Commuter train 6. Cut of cars 9. Maint./inspect.car		1		1. Yes 2. No 1	
27. Train Number/Symbol RCKL C07							
28. Speed (recorded speed, if available) Code R - Recorded 47 MPH R E - Estimated		30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits				30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
29. Trailing Tons (gross tonnage, excluding power units) 5948							
31. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded (yes/no)	
(1) First involved (derailed, struck, etc)		N/A		1		no	
(2) Causing (if mechanical cause reported)		N/A		N/A		N/A	
						32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	
						Alcohol Drugs N/A N/A	
						33. Was this consist transporting passengers? (Y/N) N	
34. Locomotive Units		a. Head End		Mid Train		Rear End	
		b. Manual		c. Remote		d. Manual c. Remote	
(1) Total in Train		2		0		0	
(2) Total Derailed		2		0		0	
35. Cars		a. Freight		b. Pass.		c. Freight d. Pass. e. Caboose	
(1) Total in Equipment Consist		48		0		0	
(2) Total Derailed		31		0		0	
36. Equipment Damage This Consist		1625060		37. Track, Signal, Way, & Structure Damage		329010	
38. Primary Cause Code		M303		39. Contributing Cause Code		N/A	
Number of Crew Members				Length of Time on Duty			
40. Engineer/Operators N/A		41. Firemen N/A		42. Conductors 1		43. Brakemen 1	
44. Engineer/Operator Hrs 3 Mi 17		45. Conductor Hrs 3 Mi 17					
Casualties to:		46. Railroad Employees		47. Train Passengers		48. Other	
Fatal		0		0		1	
Nonfatal		N/A		0		0	
49. EOT Device? 1. Yes 2. No 1		50. Was EOT Device Properly Armed? 1. Yes 2. No 1					
51. Caboose Occupied by Crew? 1. Yes 2. No						2	
OPERATING TRAIN #2							
52. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching		A. Spec. MoW Equip. Code		53. Was Equipment Attended? Code	
2. Passenger train 5. Single car 8. Light loco(s).		3. Commuter train 6. Cut of cars 9. Maint./inspect.car		N/A		1. Yes 2. No N/A	
54. Train Number/Symbol N/A							
55. Speed (recorded speed, if available) Code R - Recorded 0 MPH N/A E - Estimated		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track				57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

Page 2 of 5

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.
HQ-13-
2006.jpg



109. SYNOPSIS OF THE ACCIDENT

An eastbound Union Pacific freight train, collided with a loaded sand truck, at a rail/highway grade crossing, on March 7, 2006, at 09:47 a.m. The accident occurred within the City of Yukon, Oklahoma, at mile post 503.7, on the Oklahoma City Subdivision, of the Dallas / Ft. Worth Area, Wichita Service Unit.

The site of the accident is located within the city limits of Yukon, Oklahoma.

The driver of the highway vehicle was fatally injured. The loaded sand truck, was completely destroyed. The three crewmen of Union Pacific Train, RKCLC07, received multiple injuries, none of them life threatening. Both of the lead and pulling locomotives were up-ended, derailed and destroyed. The head thirty one cars were also derailed.

At the time of the accident, it was daylight and clear, with strong winds out of the South at approximately 23 miles per hour. The temperature was 68 degrees fahrenheit.

The accident was caused by failure of the highway vehicle, to yield to a train, at a rail/highway crossing. According to the Oklahoma Department of Public Safety, the driver of the highway vehicle, was in violation of statute; 11-702a, of the Oklahoma Vehicle Laws, Failure to properly stop at a railroad crossing.

Total estimated monetary damages were, \$1,828,085.00

Investigations and inquiries, revealed that there was not a camera, nor any related photographic equipment located on either of the locomotives for purposes filming events, of which the locomotive and or train, was involved in.

110. NARRATIVE

Circumstances Prior to the Accident

Union Pacific Train RCKLC-07

The crew, consisting of a Locomotive Engineer, Conductor and Brakeman, were called for duty at Chickasha, Oklahoma, on March 7th 2006, for 06:30 a.m., CDT. Their assignment was; Union Pacific (UP) train RCKLC-07. All crew members had received their required off duty time prior to reporting for this duty period.

Union Pacific train RCKLC-07, consisted of two locomotives, and forty eight loads of limestone rock, no empties, with 5948 trailing tons. The required air brake tests and inspections had been conducted on their train, prior to departure.

The crew received their required documentation and departed Chickasha, Oklahoma at 6:32 a.m., en route to Oklahoma City.

The entire crew was positioned on the lead and controlling Locomotive. UP 1977. The Engineer was seated on the right side of the locomotive, at the controls, operating the train. The Conductor was seated in the rear of two seats, on the left side of the locomotive, the Brakeman was seated in the front seat, also on the left side.

The train was traveling geographically eastward, on tangent and level track. The weather was clear, and windy, with good visibility. The trip had been uneventful. There are no visible sight restrictions, as would be seen from a locomotive, approaching Richland Road rail/highway crossing near Yukon, Oklahoma.

Highway Vehicle - 2002 International Dump Truck

The highway vehicle was a 2002 International dump truck, license number X90186. The gross vehicle weight was 54,000 pounds. There was one passenger in the vehicle, the driver. The vehicle was traveling geographically south, at an estimated speed of 20 mph, just prior to impact. There had been no visual confirmation that the driver attempted to stop before occupying the rail/highway crossing.

Richland road is tangent, level and has two designated directional lanes, running north and south, with a fully blacktopped surface. The rail/highway crossing is in excellent condition and is also composed of blacktop skirting, with a concrete center and rail approaches. It is equipped with crossbucks only. There are double advance warning signs for the crossing, in both directions. The posted speed on Richland Road at this location is 40 mph. Approaching the crossing from the north, the view is unrestricted in either direction.

The Accident

Union Pacific Train RCKLC-07

Traveling geographically eastward and approaching mile post 503.82, the Engineer began blowing the locomotive horn, in anticipation of transversing the highway crossing at Richland Road. The speed of the train was recorded at 47 miles per hour, recorded.

As the train approached the crossing, the engineer observed the highway vehicle approaching from the North, and continued to blow the locomotive horn and ring the bell.

Approximately four seconds prior to impact, it became apparent to the Engineer, that the highway vehicle was not going to stop. Approximately 216 feet prior to occupying the crossing, the engineer applied an emergency application of the train brakes, still continuing to sound the horn and bell. The highway vehicle continued southward, occupied the crossing and was struck by Union Pacific train RCKLC-07, at 9:47a.m.

This action fatally injured the 50 year old driver of the highway vehicle, Both locomotives, and the following thirty one loaded rock cars in the train derailed, resulting in non-fatal injuries to the train crewmen.

The Engineer was medi-flighted to OU Medical Center, where he underwent extensive back surgery. The Conductor and Brakeman were also taken to OU Medical center for treatment of minor injuries and observations.

Highway Vehicle - 2002 International Dump Truck

The highway vehicle was loaded with sand, at Schwarz Redi-Mix, 1115 feet north of the rail/highway crossing. The vehicle then left the quarry, and proceeded South on Richland road. It entered the rail/highway crossing, did not yield to the on-coming Union Pacific Train RCKLC-07.

Analysis

Due to the damage to both locomotives, the only tests conducted were wheel measurements taken in conjunction with WRE Recorder Data Analysis Systems on the lead and controlling locomotive, UP 1977.

Information gleaned from this data, reflects that the crew of Union Pacific train RCKLC-07 were within the posted speed for this location and had followed required protocols and procedures prior to and at the time of impacting the highway vehicle.

There are no active warning devices at this crossing. Also, due to the fact that this is dark territory, there is not an active track signal system, The last whistle board approaching from the west is 1,320 feet from the crossing. Two southbound advanced warning signs are located at 521 and 368 feet respectively, north of the rail/highway crossing

Adequate crossing protection in Canadian County, is the responsibility of the cities and municipalities, who have geographical jurisdiction, at that location. The Union Pacific Railroad had recently petitioned the City of Yukon, to install stop signs at the rail/highway crossing, on Richland Road. The City of Yukon had not acted on the request.

The Office of the Chief Medical Examiner, Board of Medicolegal Investigations, Oklahoma City, Oklahoma, conducted post accident toxicological examinations and tests on the remains of the driver of the highway vehicle. The results were negative.

Conclusion

It is therefore concluded, that the accident, derailment and subsequent fatal injury to the driver of the highway vehicle, was caused by the driver not stopping, but occupying a rail/highway crossing and being struck by an oncoming train.

Probable Cause

The probable cause was a failure of the driver of the highway vehicle to yield to on oncoming freight train.

Contributing Factors

There were no contributing factors

Report Discrepancies

HQ-13-2006

Wherein the Union Pacific's FRA Form F 6180.54, states in item number 17, the temperature was 60+ degrees ferinheight, the officially documented temperature at that location, at 09:53 a.m., was 68 degrees fahrenheit.

Therefore FRA's Factual Accident Report, should be deemed correct.