



***Federal Railroad Administration  
Office of Safety  
Headquarters Assigned  
Accident Investigation Report  
HQ-2006-20***


***Long Island Railroad (LI)  
Queens, New York  
April 6, 2006***

***Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.***

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2006-20</u>	
1. Name of Railroad Operating Train #1 Long Island Rail Road [LI ]			1a. Alphabetic Code LI		1b. Railroad Accident/Incident No. EQ20060402		
2. Name of Railroad Operating Train #2 Long Island Rail Road [LI ]			2a. Alphabetic Code LI		2b. Railroad Accident/Incident EQ20060402		
3. Name of Railroad Responsible for Track Maintenance: Long Island Rail Road [LI ]			3a. Alphabetic Code LI		3b. Railroad Accident/Incident No. EQ20060402		
4. U.S. DOT_AAR Grade Crossing Identification Number			5. Date of Accident/Incident Month Day Year 04 06 2006		6. Time of Accident/Incident 08:12:00 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM		
7. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction
					10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts		13. Other (describe in narrative) 04
8. Cars Carrying HAZMAT 0		9. HAZMAT Cars Damaged/Derailed N/A		10. Cars Releasing HAZMAT N/A		11. People Evacuated 0	
12. Division System							
13. Nearest City/Town Jamaica			14. Milepost (to nearest tenth) 9.0		15. State Abbr Code N/A NY		16. County QUEENS
17. Temperature (F) (specify if minus) 45 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1	
21. Track Name/Number Track #8 Hall			22. FRA Track Class (1-9, X) Code 2		23. Annual Track Density (gross tons in millions) N/A		24. Time Table Direction Code 1. North 3. East 3
OPERATING TRAIN #1							
25. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car	
						A. Spec. MoW Equip. Code 2	
26. Was Equipment Attended?		1. Yes 2. No		Code 1		27. Train Number/Symbol LI22	
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 5 MPH E		30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits		30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		0	
29. Trailing Tons (gross tonnage, excluding power units) 0							
31. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded (yes/no)	
(1) First involved (derailed, struck, etc)		N/A		1		yes	
(2) Causing (if mechanical cause reported)		0		0		N/A	
						32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	
						Alcohol Drugs 0 0	
						33. Was this consist transporting passengers? (Y/N) Y	
34. Locomotive Units		a. Head End		Mid Train		Rear End	
				b. Manual c. Remote		d. Manual c. Remote	
(1) Total in Train		1		0 0		0 0	
(2) Total Derailed		0		0 0		0 0	
35. Cars		a. Freight		b. Pass.		c. Freight d. Pass. e. Caboose	
(1) Total in Equipment Consist		0		7		0 0 0	
(2) Total Derailed		0		0		0 0 0	
36. Equipment Damage This Consist 153690		37. Track, Signal, Way, & Structure Damage 0		38. Primary Cause Code H221		39. Contributing Cause Code N/A	
Number of Crew Members				Length of Time on Duty			
40. Engineer/Operators N/A		41. Firemen 0		42. Conductors 1		43. Brakemen 0	
44. Engineer/Operator Hrs 3 Mi 31		45. Conductor Hrs 3 Mi 31					
Casualties to:		46. Railroad Employees		47. Train Passengers		48. Other	
Fatal		0		0		0	
Nonfatal		N/A		0		0	
49. EOT Device? 1. Yes 2. No 2		50. Was EOT Device Properly Armed? 1. Yes 2. No N/A		51. Caboose Occupied by Crew? 1. Yes 2. No N/A			
OPERATING TRAIN #2							
52. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car	
						A. Spec. MoW Equip. Code 2	
53. Was Equipment Attended?		1. Yes 2. No		Code 1		54. Train Number/Symbol LI710	
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 12 MPH R		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track		57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable			

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2006-20</u>	
56. Trailing Tons (gross tonnage, excluding power units) <div style="text-align: right;">0</div>		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s) <div style="display: flex; justify-content: space-around; font-size: small;"> <div>f</div> <div>N/A</div> <div>N/A</div> <div>N/A</div> <div>N/A</div> </div>	
						2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter <div style="text-align: right;">0</div>	
58. Principal Car/Unit (1) First involved (derailed, struck, etc) (2) Causing (if mechanical cause reported)		a. Initial and Number <div style="text-align: center;">LI7466</div>	b. Position in Train <div style="text-align: center;">1</div>	c. Loaded(yes/no) <div style="text-align: center;">yes</div>	59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. <div style="display: flex; justify-content: space-around; font-size: small;"> <div>Alcohol</div> <div>Drugs</div> </div> <div style="display: flex; justify-content: space-around; font-size: small;"> <div>0</div> <div>0</div> </div>		
		<div style="text-align: center;">0</div>	<div style="text-align: center;">0</div>	<div style="text-align: center;">N/A</div>	60. Was this consist transporting passengers? (Y/N) <div style="text-align: right;">Y</div>		
61. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote	62. Cars	Loade a. Freight b. Pass.	Empty c. Freight d. Pass.
							e. Caboose
(1) Total in Train	<div style="text-align: center;">1</div>	<div style="text-align: center;">0</div>	<div style="text-align: center;">0</div>	<div style="text-align: center;">0</div>	(1) Total in Equipment Consist	<div style="text-align: center;">0</div>	<div style="text-align: center;">7</div>
(2) Total Derailed	<div style="text-align: center;">0</div>	<div style="text-align: center;">0</div>	<div style="text-align: center;">0</div>	<div style="text-align: center;">0</div>	(2) Total Derailed	<div style="text-align: center;">0</div>	<div style="text-align: center;">0</div>
63. Equipment Damage This Consist		64. Track, Signal, Way, & Structure Damage		65. Primary Cause Code		66. Contributing Cause Code	
<div style="text-align: center;">1311820</div>		<div style="text-align: center;">0</div>		<div style="text-align: center;">H221</div>		<div style="text-align: center;">N/A</div>	
Number of Crew Members				Length of Time on Duty			
67. Engineer/Operators	68. Firemen	69. Conductors	70. Brakemen	71. Engineer/Operator	72. Conductor		
<div style="text-align: center;">1</div>	<div style="text-align: center;">0</div>	<div style="text-align: center;">1</div>	<div style="text-align: center;">0</div>	Hrs <div style="text-align: center;">7</div> Mi <div style="text-align: center;">5</div>	Hrs <div style="text-align: center;">7</div> Mi <div style="text-align: center;">5</div>		
Casualties to:	73. Railroad Employees	74. Train Passengers	75. Other	76. EOT Device?		77. Was EOT Device Properly Armed?	
Fatal	<div style="text-align: center;">0</div>	<div style="text-align: center;">0</div>	<div style="text-align: center;">0</div>	1. Yes 2. No <div style="text-align: center;">2</div>		1. Yes 2. No <div style="text-align: center;">N/A</div>	
Nonfatal	<div style="text-align: center;">1</div>	<div style="text-align: center;">0</div>	<div style="text-align: center;">0</div>	78. Caboose Occupied by Crew? 1. Yes 2. No <div style="text-align: right;">N/A</div>			
Highway User Involved				Rail Equipment Involved			
79. Type C. Truck-Trailer. F. Bus J. Other Motor Vehicle A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)				83. Equipment 3. Train (standing) 6. Light Loco(s) (moving) 1. Train(units pulling) 4. Car(s)(moving) 7. Light(s) (standing) 2. Train(units pushing) 5. Car(s)(standing) 8. Other (specify in narrative)			
<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>				<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>			
80. Vehicle Speed (est. MPH at impact)		81. Direction geographical 1. North 2. South 3. East 4. West		84. Position of Car Unit in Train <div style="text-align: center;">N/A</div>			
<div style="text-align: center;">N/A</div>		<div style="text-align: center;">N/A</div>					
82. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				85. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User			
<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>				<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>			
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?				86b. Was there a hazardous materials release by			
1. Highway User 2. Rail Equipment 3. Both 4. Neither				1. Highway User 2. Rail Equipment 3. Both 4. Neither			
<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>				<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>			
86c. State here the name and quantity of the hazardous materials released, if any. <div style="text-align: center;">N/A</div>							
87. Type of Crossing Warning		1. Gates 4. Wig Wags 7. Crossbucks 10. Flagged by crew 2. Cantilever FLS 5. Hwy. traffic signals 8. Stop signs 11. Other (spec. in narr.) 3. Standard FLS 6. Audible 9. Watchman 12. None		88. Signaled Crossing Warning (See instructions for codes)		89. Whistle Ban	
<div style="text-align: right;">Code(s)</div>		<div style="text-align: center;">N/A</div>		<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>		<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>	
90. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach		<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>		91. Crossing Warning Interconnected with Highway Signals 1. Yes 2. No 3. Unknown		92. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown	
				<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>		<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>	
93. Driver's Age	94. Driver's Gender 1. Male 2. Female	<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>	95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown		<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>	96. Driver 1. Drove around or thru the Gate 4. Stopped on Crossing 2. Stopped and then Proceeded 5. Other (specify in narrative) 3. Did not Stop	
<div style="text-align: center;">N/A</div>						<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>	
97. Driver Passed Standing Highway Vehicle 1. Yes 2. No 3. Unknown		<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>		98. View of Track Obscured by (primary obstruction) 1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative) 2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed		<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>	
101. Casualties to Highway-Rail Crossing Users		Killed	Injured	99. Driver Was 1. Killed 2. Injured 3. Uninjured		100. Was Driver in the Vehicle? 1. Yes 2. No	
		<div style="text-align: center;">N/A</div>	<div style="text-align: center;">N/A</div>	<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>		<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>	
				102. Highway Vehicle Property Damage (est. dollar damage)		103. Total Number of Highway-Rail Crossing Users (include driver)	
				<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>		<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>	
104. Locomotive Auxiliary Lights? 1. Yes 2. No				105. Locomotive Auxiliary Lights Operational? 1. Yes 2. No			
<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>				<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>			
106. Locomotive Headlight Illuminated? 1. Yes 2. No				107. Locomotive Audible Warning Sounded? 1. Yes 2. No			
<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>				<div style="text-align: right;">Code</div> <div style="text-align: center;">N/A</div>			

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.  
Hall Side  
Swipe2.jpg



## 109. SYNOPSIS OF THE ACCIDENT

An eastbound LI Train collided with the side of another eastbound LI train at Jamaica Station, on April 6, 2006, at 8:12 a.m. The accident occurred in Jamaica, NY, at LI Milepost 9.0, on the LI Main Line.

Train No. 22 consisted of eight Multiple Unit (MU) passenger cars. The consist had four M3 type cars (two in the lead and two trailing) with four M1 cars in the middle. Train No. 22 departed its initial terminal, Penn Station NY, at 7:30 a.m, en route to Babylon. While waiting to depart Jamaica Station from Track No. 8 at 8:10 a.m, the engineer stated that he received a signal from his conductor to proceed. The engineer was unable to recall the signal displayed for his train on signal 66L, a dwarf signal located at the east end of the platform on Track No. 8 at Jamaica Station. The LI block operator stated that no signal was displayed for Train No. 22 on Track No. 8.

Train No. 710 consisted of eight M7 type MU passenger cars and departed Jamaica Station from Track No. 7 at the same time, en route to Hempstead. The block operator stated that signal 62L was displayed for Train No.710 to proceed.

Train No. 22 collided with the side of the first car of Train No. 710, approximately two car lengths east of the platform at Jamaica Station. Before Train No. 710 came to a stop, damage had been done to cars 7466-65, 7452-51, and 7176-75. The accident occurred within Hall Interlocking at the junction of Tracks 7 and 8 at movable point frogs 55 and 57, which were lined for Train No. 710's route.

The signal system within Jamaica Station does not include cab signals. The LI Signal Department initiated a twenty-four hour watch on signal 66L after the accident. Within Hall Interlocking relays were tested for compliance with 49 CFR 236.106, grounds were checked for compliance with 49 CFR 236.107, and cables were tested for insulation resistance for compliance with 49 CFR 236.108. The results of these tests indicated all apparatus to be in compliance with Federal regulations.

The accident was caused by failure of the locomotive engineer of Train No. 22 to comply with the stop signal displayed on signal 66L.

## 110. NARRATIVE

## Circumstances Prior to the Accident

The crew of train 22 consisted of an engineer, conductor, assistant conductor, and two collectors. The crew was working Job 177, with a reporting time of 4:39am on April 6, 2006. The crew reported at Jamaica, located in Queens, NY, after receiving more than the statutory off duty rest period. Train 22 was the crew's third train in their daily assignment. The train was traveling eastbound to Babylon, NY.

Train 22 consisted of eight M1/M3 type multiple unit passenger cars. The consist was as follows: 9776-75, 9728-27, 9080-79, 9940-39.

The engineer was seated at the controls of car 9776. The rest of the crew was scattered throughout the train attending to the passengers.

The crew of train 710 consisted of an engineer, conductor, assistant conductor, and one collector. The crew was working Job 154, and reported at 1:07am on April 6, 2006. The crew reported at Flatbush, located in Brooklyn, NY, after receiving more than the statutory off duty rest period. Train 710 was the crew's fifth train in their daily assignment. The train was traveling eastbound to Hempstead, NY.

Train 710 consisted of eight M7 type multiple unit cars. The consist was as follows: 7466-65, 7452-51, 7176-75, 7124-23.

Train 22 and Train 710 had just completed a station stop at Jamaica Station. Train 22 utilized track 8 while Train 710 utilized track 7. Jamaica Station has high platforms and there are no vision obstructions at the accident site. The railroad timetable direction of both train 22 and 710 was east. The geographic direction was also east.

## The Accident

Train 710 departed track 7 at Jamaica Station at 8:11 am, following a station stop. The train received an aspect to proceed on 62L signal from the block operator at Hall Tower. The train proceeded eastbound and the lead (7466) unit was east of track switch no. 59 when the impact occurred. Train 710 was traveling at 12 mph at the moment of impact.

Train 22 departed Jamaica Station at 8:12 am, following a station stop. The engineer passed a stop signal on 66L, located at the east end of the platform at Jamaica Station. The train proceeded east, where at approximately 160 feet past the signal, it sideswiped the south side of train 710. Train 22 was traveling at 12 mph at the moment of impact.

Train 22 suffered extensive damage to lead unit 9776. Repair cost was estimated to be \$153,690. Train 710 suffered side sill, component, and structural damage to car numbers 7451, 7452, 7465, and 7466. Total damage to the cars was estimated to be \$1,311,820.

The weather was clear and there were no obstructions impeding the view of the engineer of Train 22.

## Analysis and Conclusions

## Analysis

During an interview with the engineer of Train 22, he stated that he couldn't remember the aspect on signal 66L. He received two buzzes on the train intercom from the train crew indicating that the doors were closed following the station stop and that the engineer could proceed when the signal was received. Signal 66L was not displayed for Train 22 as Signal 62L was displayed for Train 710 on track no. 7.

A 24 hour signal watch was placed on signal 66L with all aspects recorded and determined to be correct. Additionally, testing on the signal circuits pertaining to 66L were performed. These tests included 49CFR Part 236.106 (relays), 107 (grounds), and 108 (insulation resistance). All tests proved the signal system to be functioning as intended.

Drug and alcohol testing on the train crews of both train 710 and 22 were negative.

#### Conclusion

The testing of the signal system proved that there was no failure of signal 66L. The engineer of Train 710 received an aspect to proceed on signal 62L. With 62L displayed, mechanical locking in the interlocking machine would prevent the block operator from physically displaying signal 66L. The testing of the signal system proved that system integrity was intact.

#### Probable Cause and Contributing Factors

The FRA found that the collision occurred because the engineer failed to comply with the stop indicator of signal 66L.