

Federal Railroad Administration Office of Safety Headquarters Assigned Accident Investigation Report HQ-2006-42

> Norfolk Southern Lemoyne, AL June 1, 2006

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

DEPARTMENT O FEDERAL RAILRO	OF TRA OAD A	ANSPORT DMINIST	FATI RAT	ON ION	FRA FA	ACTUA	AL RA	ILR	ROAD A	ACC	IDENT I	REPO	RT	1	FRA Fi	le #	<u>HQ-200</u>	6-42	2	
1.Name of Railroad Op Norfolk Southern C	1a. Alphabetic Code 1 NS					1b. 1	b. Railroad Accident/Incident No. 25365													
2.Name of Railroad Op	2a.	2a. Alphabetic Code					2b. Railroad Accident/Incident													
N/A	N/A						N/A													
3.Name of Railroad Re	3a. Alphabetic Code						Railroad A	ccident	t/Inci	dent No.										
Norfolk Southern C	NS						25365													
4. U.S. DOT_AAR Gra	5. I	5. Date of Accident/Incident 6.						cident/l	Incide	ent										
					727807V				Month Day Year 06 01 2006					11:40: 🗸 AM 🏼 PM						
7. Type of Accident/In	ndicent	1. Derail	ment		4. Side collision				7. Hwy-rail crossing 10. Explosio					n-detonation 13. Other						
(single entry in code	e box)	2. Head of	on coll	ision	sion 5. Raking collision				. RR grade	cros	sing 11.	Fire/vie	olent rupt	ent rupture (describe in						
		3. Rear e	nd col	lision	sion 6. Broken Train collision				9. Obstruction 12. Other im					pacts 07					07	
8. Cars Carrying		9. HAZMA	AT Ca	rs	10. Cars Releasir					1	11. People				12. Division			1		
HAZMAT 14	HAZMAT 14 Damaged/Derailed				1 TAZMAT				0 Evacuated					0			Alabama	ı		
					14 Milepost				15 State											
13. Nearest City/Town	1	Ax	is		(to nearest te				8.2MB	15.	Abbr N/A	Code		. County	MOBILE					
17. Temperature (F)		18. Visit	oility	(sin	(single entry) Code 19. '			/eather (single en			ry)	de	20. Typ	be of Track				Code		
(specify if minus)	(specify if minus) 1. Dawn			3.E	Dusk 1				. Clear 3. Rain 5.S			5.Sleet			1. Main 3. 3					
90	F	2.	Day	4.1	Dark		. Clo	udy 4. F	og	6.Snow	1	2. Ya	. Yard 4. Indust		stry		I			
21. Track Name/Number					22. FRA Track				Code	23.	3. Annual Track Density			24. Tim	e Table Direction				Code	
Ma					Class (1-9, X) (gross tons in millions)							6.3	1. North 3. East					2		
							OPER		ING TR	AIN	#1									
25 Type of Equipmen	st 1	Eroight tr	in	4 W	ork train 7	Vord/ou	itohing		Space Mo	WE	min Coda	126 W	/as Equir	ment (¹ oda	27 7	Troin Nur	nhar	Sumbol	
Consist (single ent	Light loc	co(s).	A	. spec. Mo	JW LA	Equip. Code 20. Was E			ided?			27. Train Number/Symbo								
3. Commuter train 6. Cut of cars 9. Maint/inspect.car 1 1. Yes 2. No 1 A89A40																				
28. Speed (recorded s	peed, if	available)	Cod	e 30	. Method(s)	of Operati	on (ente	r code(s)	that	apply)			30a. Rem	otely C	ontro	lled Loco	moti	ive?	
R - Recorded a. ATCS g. Automatic block m. Special instructions 0 = Not a4e Southly to Wrester												Willed								
E - Estimated	n. Curren	t of t	raffic	C	1 = Remote control portable															
29. Trailing Tons (o	pross to	nnage			. Auto trair 1 Cab	1 stop 1 i	. Time ta Track w	able/t /arrar	rain orders	so.ł n(Positive train		2 = Remote control tower $3 = Remote control$							
excluding power	units)	iniuge,			e Traffic k Direct t				raffic control Code(s)			ify in na (s)	transmitter - more than one			nan one				
	1	955		f	f. Interlocking 1.Yard lin				ts i N/A N/A				N/A N/A remote control transmitter					0		
21 D 10 // .		<u>x</u> 1	1.53			·		r 1	1		N/A N	/A N/	A N/A						0	
(1) First investor d		a. Initial	and N	umber	D. Positic	on in Traii		Load	ed(yes/no)	-32	enter the	employ number	ee(s) teste that were	ed for drug positive i	g/alcoho n	ol use	, Alcohol		Druge	
(1) First involved (derailed, struck, etc	c)		N/A			1			no		the appro	priate b	DX.	positive			N/A		N/A	
(2) Causing (if mech	hanical	1	N/A			I/A			NI/A	3	33. Was this	consist	transport	ing passen	gers? (Y/N)	10/11			
cause reported)					1							loade				N				
34. Locomotive Units		a. Head End	b. M	Mid ' anual	Frain c. Remote	d. Manua	l c. Rei	mote	35. Car	rs		а	. Freight	b. Pass.	c. Frei	ight	d. Pass.	e. (Caboose	
(1) Total in Train		1		0	0	0	0		(1) Total	l in E	quipment C	onsist	8	0	2		0		0	
(2) Total Derailed	L	1		0	0	0	0		(2) Tota	l Dera	ailed		3	0	2	2	0		0	
36. Equipment Damag	ge		+	37. Tr	ack, Signal. V	Way,	- <u>!</u>		38. Prim	narv (Cause	[39. Cont	ributins	g Cau	se	I		
This Consist	1	36600		&	Structure Da)	Code	308	Code			1	N/A	A						
	I	Numbe	r of C	rew M	v Members				Length o					of Time on Duty						
40. Engineer/ 41. Firemen				42. Conductors 43. Brakemen					44. Engineer/Operator					45. Conductor						
Operators N/A	Operators N/A N/A			1			1				Hrs 3 Mi			40		lrs	3	Mi	40	
Casualties to: 4	46. Railı	road Emplo	yees 47. Train Passengers				Other		49. EOT Device?					50. Was EOT Device Properly A					ned?	
Fatal		0			0	0		1. Y	1. Yes 2. No 1											
								51. Caboose Occupied by Crew?					· · ·							
Nonfatal	N/A			0			1		1. Yes				2. No						N/A	
						0	PERAT	ΓIN	G TRAIN	N #2										
52. Type of Equipment 1. Freight train 4. Work train 7. Yard/switching A. Spec. MoW Equip. Code 53. Was Equipment Code 54. Train Number/Symbol																				
Consist (single entry) 2. Passenger train					5. Single car 8. Light loco(s).				A			ttended?	uea?			N/	4			
55 Speed (1 1			c u airi	0. Cu	Mathe 1	Maint./in	spect.ca	I Conto	r anda(c)	that	0		1. Yes	2. No 2	otaly C	ontro	lled Loca	mot	ivo?	
R - Recorded								0 = Not a remotely control of the second							ontrolled					
E - Estimated	a ł	. AICS). Auto train (nt of t	of traffic n. Other than main track					1 = Remote control portable											
I		1																		

DEPARTMENT FEDERAL RAILF	OF TRA ROAD AI	NSPORT OMINIST	TATIO TRATI	ON ION	FRA FA	CTUAL	RAILR	OAD AC	CIE	DENT F	REPO	ORT	F	RA File #	<u>HQ-200</u>	<u>6-42</u>	
56. Trailing Tons (gross tonnage, excluding power units)					c. Auto train stop i. Time table/tr d. Cab j.Track warran e. Traffic k. Direct traffic f. Inteclecking l. Yord limits				in orders o. Positive train control control p. Other (Specify in narrative) control <u>Code(s)</u>					2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter			
58 Principal Car/Unit a Initial and Nu				umber	mber b Position in Train c Load				$\begin{bmatrix} J & [N/A] & [N/A] & [N/A] \\ \end{bmatrix}$								
(1) First involved					0.10310	$\frac{(yes/no)}{29}$ S9. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in <u>Alc</u>							Alcohol	Drugs			
(derailed, struck, etc) SHPX2 20898				3		1		no	the appropriate box.					N/A			
(2) Causing (if mechanical cause reported) 0						N/A]	N/A	60.	. Was this	s consi	st transporti	ng passen	N			
61. Locomotive Units	\$	a. Head End b. Mar			Train c. Remote	Rea d. Manual	r End c. Remote	62. Cars				Loa a. Freight	pty d. Pass.	e. Caboose			
(1) Total in Train		0	0		0	0	0	(1) Total ii	ı Equi	pment Co	onsist	0	0	7	0	0	
(2) Total Deraile	Total Derailed 0		0 0		0	0	(2) Total Derailed				0	0	2	0	0		
63. Equipment Damage 6 This Consist 17800					ack, Signal, ' Structure Da	Way, mage	0	65. Primar Code	i5. Primary Cause 66. Contributing Cause Code M308					use	N/A		
		Numbe	r of Ċı	ew Me	mbers	-						Length of 7	Time on D	uty			
67. Engineer/ Operators N/	68. Firemen 6 J/ N/A			69. Co	nductors N/A	70. Bra	kemen N/A	71. Engin	perator 0	Mi	0	72. Con	ductor Hrs	0	Mi 0		
Casualties to:	73. Railr	oad Emplo	oyees	74. Trai	in Passenger	s 75. Othe	75. Other		evice	?			e Properly	Armed?			
Fatal		0			0		0		es se Oc	2. No		N/A	1.	Yes	2. No	N/A	
Nonfatal		0			0		0		1. 1	Yes	y ciew	2. No				N/A	
		er Invo	olved			Rail Equipment Involved											
79. Type C. Truck-	Code	83. Equipment 3.Train (standing) 6.Light Loco(s) (moving)															
A. Auto D. Pick-U B. Truck E. Van	arrative)	1.Train(units pulling) 4.Car(s) (moving) 7.Light(s) (standing) 2.Train(units pushing) 5.Car(s) (standing) 8.Other (specify in narrative)							g) narrative)	1							
80. Vehicle Speed	geographi	cal)	Code	Code 84. Position of Car Unit in Train							,	•					
(est. MPH at in	outh 3.East	4.West	4 C- 1-	85 Circum	85. Circumstance												
1.Stalled on Cros	ng 3.M	loving Over	Crossing	1. Rail Equipment Struck Highway User													
4. Trapped 86a. Was the highw		Code	2. Rail Ec	luipm here a	hazardo	k by H	ighway Use	e by			C. d.						
in the impact tr	erials?			code	1 11:-1		J	D-:1 E		2 D-4	4 No. taba		Code				
1. Highway User	2. Rail E	Equipment	3. I	Both	4. Neither		3	I. High	way t	Jser 2.	Rail E	quipment	3. Both	4. Neither	r	4	
soc. State here the ha	ine and qu	lantity of t	ne naz	ardous	materials re	leased, 11 ai	N/A										
87. Type of 1.Ga Crossing 2.Ca	s ïc signa	7.Crossl als 8.Stop s	oucks 10. igns 11.	Flagged by Other (spec	crew . in narr.)	88. S (S	ignaled C ee instruc	crossin ctions f	g Warning for codes)	Code	89. Whis 1. Ye	tle Ban s	Code				
Warning 3.Sta	Code(s) 03 06 07				9.Watch	$\frac{12}{N/4}$	None	NI/A					N/A	2. No 3. Un	known	2	
90. Location of Warn	ing	06	07		N/A Code	91. Crossin	IN/A Ig Warning I	Interconnected Code 92. Crossing Illuminated by Street						Code			
1. Both Sides 2. Side of Vehicl	with H 1.	lighway Sig Yes	gnals	als Lights or Special Lights 1. Yes													
3. Opposite Side of Vehicle Approach					1	2.	No Unknown		2 2. No 3. Unk					nown			
93. Driver's 94. Driver's Gender Code 9					iver Drove E	ehind or in	ain Code	, 9	6. Driver		1	<u> </u>	Code				
Age 1. Male and Struck 60 2. Female 1. Yes						No	by Second T 3. Unknown	2 3. Did not Stop 2 3. Did not Stop								g	
97. Driver Passed St	f Track Obsc	ured by (primary obs	struction)							,	Code					
Highway Vehicle 1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative) 2. Structure 2. Structure 1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative)																	
1. res 2, No 3, Unknown 2 2. Standing Kailroad Equipment 4, Topography 6. Highway Vehicle 8. Not obstructed 101. Casulties to Highway-Rail 99. Driver Was Code 100. Was Driver in the Vehicle?													8 Code				
Crossing Users Killed					Injured	1. Killed 2	2.Injured 3.	Uninjured		2		1. Ye	es	2. No		1	
0					1	102. Highw	vay Vehicle	Property Damage 103. Total Number of Highway-Rail Crossing 1 (include driver) 1								ing Users	
104. Locomotive Aux		(USL U	Code	105. Locomotive Auxiliary Lights Operational?						1	Code						
1. Yes		2. No)				1	1 1. Yes 2. No								1	
106. Locomotive Headlight Illuminated?							Code	107. Locomotive Audible Warning Sounded?							Code		
1. Yes)				1	1. Yes 2. No								1		

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED. HQ-2006-42 sketch.jpg



109. SYNOPSIS OF THE ACCIDENT

On June 1, 2006, at 11:40 a.m. Central Daylight Time (CDT), southbound Norfolk Southern Railway (NS) freight Train A89A401 struck a westbound tractor-trailer (tanker) at a public highway-rail grade crossing in Axis, Alabama (AL). The accident occurred at milepost (MP) 128.2MB on the 3-B South Subdivision of the NS Alabama Division. The method of operation in the accident area is Track Warrant Control.

The impact derailed the locomotive and the first through fifth head cars on the train and two rail cars standing in an adjacent storage track. All derailed cars contained hazardous materials, but no cars were breached and there was no release of materials.

The tractor separated from the trailer on impact. The tractor wrapped around the front of the locomotive and became lodged under the front snowplow and end sheet. The trailer was shoved to the east side of the main track and dragged about 200 feet before becoming wedged between the train and cars standing in the Salco Storage Track. The trailer contained Sulfuric Acid, but there was no puncture of the tank and no release of product. The impact ripped the fuel tanks from the tractor resulting in a fire that consumed the tractor and burned the west side of the locomotive. The fire was quickly extinguished by local fire personnel. There were no evacuations of nearby businesses or residents.

The train crew and tractor driver received minor injuries and were taken to local hospitals where they were treated and released.

Estimated track damage is \$8,000 and equipment damage is \$53,800. The tractor-trailer was destroyed at an estimated replacement cost of \$80,000 for the tractor and \$40,000 for the trailer.

At the time of the accident, the weather was clear with a temperature of 90°F.

The accident was caused by the failure of the truck driver to stop clear of the crossing and yield the right-of-way to the approaching train.

110. NARRATIVE

Circumstances Prior to the Accident

The crew of NS Train A89A401 consisted of a locomotive engineer, conductor, and brakeman. All crew members went on duty at 8 a.m., CDT, June 1, 2006, at the NS Mobile Yard in Mobile, AL. Mobile is the home terminal for all crew members, and all members received more than the statutory off duty period prior to reporting for duty.

NS Train A89A401 consisted of lead and controlling locomotive NS 8929, three loaded cars of mixed freight, and 18 empty cars. It was 1,260 feet long and weighed 770 tons. Train A89A401 is a local road switcher scheduled to work various industries between North Mobile Yard, MP 146.0MB, and Lemoyne, AL, MP 128.9MB, and return. The train received a Class I air brake test by NS mechanical personnel and departed North Mobile Yard at 8:53 a.m.

Train A89A401 had just finished servicing U. S. Amines Industry, MP 127.0MB, and was heading south to the Lemoyne Storage Track, MP 129.0MB. Approaching the accident area, the locomotive engineer was seated at the controls on the west side of the locomotive, the conductor and brakeman were seated on the east side.

This area of the railroad is tangent for two miles to the point of the accident and two miles beyond. Salco Road is tangent with the grade practically level.

NS timetable and geographic direction is north and south. Timetable direction is used throughout this report.

The Accident

NS Train A89A401

NS Train A89A401 was operating cab forward at the authorized speed of 37 miles per hour (mph) as it approached the Salco Road crossing. The engineer began sounding the locomotive horn at the whistle board and all train crew members said the view of the crossing was unobstructed. The engineer, conductor, and brakeman observed the tractor-trailer slowly approach the crossing from the east side. The brakeman said the tractor-trailer stopped on the storage track, clear of the main track, then started easing over the crossing. When the train was about 150 feet north of the crossing, the engineer realized the tractor-trailer was not going to stop. He made an emergency air brake application and continued sounding the locomotive horn until about 75 feet before impact.

The tractor-trailer was struck on the right side, between the tractor cab and trailer. The fuel tank on the tractor exploded on impact consuming the tractor and engulfing the west side of the locomotive. The tractor wrapped around the front snowplow and end sheet of the locomotive and was carried south, in front of the train, about 555 feet until the train stopped. The trailer broke away from the tractor and was dragged about 200 feet between the Salco Storage Track and the east side of the train, resulting in the derailment of the two north cars in the storage track.

The train was operating at 37 mph when the collision occurred. The speed was recorded by the event recorder on Locomotive NS 8929. The maximum authorized speed in the accident area is 49 mph, as designated in the current NS Alabama Division Timetable No. 15.

After the train stopped, the engineer's side window and door were engulfed in flames. The conductor attempted to open the door in the nose of the locomotive, but it would not open more than six inches. The brakeman, conductor, and engineer jumped out the window on the east side of the locomotive. The conductor went to the front of the locomotive and helped the driver out of the burning tractor cab. The train crew and driver walked/ran to a private crossing, U. S. Fibers, about 75 yards south of the stopped train. The conductor used his cell phone to call the NS Chief Dispatcher and the 3-B South Operations Manager. The engineer called 911 from his cell phone and the locomotive radio before he jumped from the locomotive window.

Two NS mechanical employees arrived on the scene about 12:10 p.m., followed by the Creola, AL Police Chief and the Saraland, AL Emergency Medical Services (EMS). Units from the Saraland, Mobile, and U. S. Amines Industry Fire Departments arrived shortly thereafter and extinguished the fires on the tractor, locomotive, and along the west side of the NS right-of-way. The NS operations manager and assistant operations manager arrived on the scene at 12:30 p.m. as the train crew was being placed in the ambulance. The EMS transported all train crew members to the Springhill Medical Center in Mobile and the vehicle driver to the USA Hospital in Mobile. The Creola Police Chief took statements from the vehicle driver and train crew, but did not file a report because the accident was not within his jurisdiction. An AL Highway Patrol Officer arrived on the scene, but did not make a report because according to the officer, it was a private crossing.

Highway Vehicle

The motor vehicle was a 2006 tractor-trailer owned by Penske Leasing, Inc. and leased by American Road Lines, Moon Township, Pennsylvania. It was driven by a 60 year-old male who had just departed Akzo Nobel Chemical after obtaining a load of Sulfuric Acid. The tractor-trailer was traveling west on Salco Road, which runs east to west between Akzo Nobel Chemical and U. S. Highway 43. The driver said he saw the crossing lights flashing and stopped, but he did not see the train. He thought the crossing lights were malfunctioning and began driving over the crossing at an estimated speed of 2 mph.

Description of the Accident Site

The NS railroad approaching the Salco Road crossing consists of a single main track extending north and south. A storage track, Salco Storage, located east of the main track also crosses Salco Road. The main track is tangent for about two miles north of the crossing and a considerable distance beyond. There is a 0. 04-percent ascending grade approaching the crossing. Southbound trains approaching the crossing have an unobstructed view.

Salco Road is a two-lane asphalt road that extends east to west from Akzo Nobel Chemical to U. S. Highway 43, crossing the NS railroad at a 90-degree angle. The crossing is rubber and asphalt 32 feet in length by 22 feet in width. NS records show the crossing as private, but the Alabama Mobile County Public Works Department and the Federal Railroad Administration (FRA) list the crossing as public.

The crossing is equipped with standard flashing lights, audible bell, crossbucks, and advanced warning signs on both sides of the crossing. The advanced warning sign for westbound vehicle traffic is located about 122 feet from the flashing light mast, and the flashing light mast is located about 24 feet from the main track. There are no pavement markings approaching the crossing. The sight distance for westbound vehicle traffic looking north is about 2,000 feet. The sight distance looking south is restricted when cars are in the siding, but the NS has marked the rail so cars are not placed closer than 100 feet south of the crossing, which improves visibility.

Analysis and Conclusions

Analysis

Whistle board signs were displayed in both directions approaching the crossing. The engineer said he began sounding the locomotive horn near the whistle board and continued to sound it until about 75 feet from impact. Two witnesses employed by Akzo Nobel Chemical said the train horn was being sounded prior to the collision. One of the witnesses also said she observed the crossing lights flashing and heard the crossing bells ringing prior to the collision.

Locomotive NS 8929 derailed and sustained damage to the front snowplow, end sheet, left and right handrails and steps, uncoupling lever, MU cable, continuous barrier, ditch lights, and headlights. The west side of the locomotive also sustained fire and smoke damage. The locomotive was equipped with headlights, auxiliary lights, and an audible warning device as required by 49 CFR Part 229, Railroad Locomotive Safety Standards. All devices were working as intended prior to the collision.

The five head cars behind the locomotive derailed, but remained upright. Each of the cars sustained varying degrees of damage. The two north cars in the Salco Storage Track derailed and sustained damage.

The highway vehicle was destroyed. The tractor was consumed by fire and the trailer was damaged to the extent that it could not be repaired.

The active warning devices at the crossing were inspected and tested by a NS Signal Maintainer at the time of the accident. The crossing signals were also inspected and tested by an FRA Signal and Train Control Inspector the day following the accident. No defects were noted during either of the inspections and tests, and all devices operated as intended.

No toxicological tests were performed on members of the train crew or the vehicle driver. No city, county, or state law enforcement agencies formally investigated and filed an accident investigation report.

Probable Cause

The FRA concluded that the probable cause of the accident was the failure of the motor vehicle driver to stop clear of the crossing and yield the right-of-way to the approaching train.

#