

# Federal Railroad Administration Office of Safety Headquarters Assigned Accident Investigation Report HQ-2005-05

Union Pacific (UP)
Bayport, Texas
January 8, 2005

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.


FEDERAL RAILRO					FRAF	ACTUA	L RA	ILR	ROAD A	.CC1	IDENT F	REPOR	Т		FRA Fi	ile#]	HQ-200	<u>05-5</u>	
1.Name of Railroad Ope	rui i irpinuoene code					1b. 1	b. Railroad Accident/Incident No.												
UNION PACIFIC RA	UP						0105HO008												
2.Name of Railroad Operating Train #2									•					2b. Railroad Accident/Incident					
N/A  3.Name of Railroad Responsible for Track Maintenance:									N/A					N/A					
· ·	•					30.1	3b. Railroad Accident/Incident No.												
Union Pacific RR Co. 4. U.S. DOT_AAR Grad	UP					6 Т	ime of A	0105H		nt									
4. 0.5. DOI_/I/IR GIAC	3.1	5. Date of Accident/Incident  Month   Day   Year					6. Time of Accident/Incident												
									01 08 2005					03:30: ☐ AM 🗸 PM					
7. Type of Accident/Indicent 1. Derailment 4. Side collision									7. Hwy-rail crossing 10. Explosion-detonation 13. Other										
(single entry in code box) 2. Head on collision 5. Raking collision 3. Rear end collision 6. Broken Train collisio									8. RR grade crossing 11. Fire/violent rupture (describe in narrative) 9. Obstruction 12. Other impacts 01									01	
8. Cars Carrying HAZMAT 13		). HAZMA Damaged/I		3	10. Cars Releasin HAZMAT			2		1. People Evacuated			0	12. Div	vision Houston				
13. Nearest City/Town					14. Milepost			41- \			5. State Abbr Code			16. County					
	Seabrook				(to nearest			enun)	6.7		N/A   TX				Н	HARRIS			
17. Temperature (F)		18. Visib	•	· · · · · · · · · · · · · · · · · · ·				Veather (single entry)						20. Type of Tr			ack		
	(specify if minus) 1. Dawn 72 F 2. Day					3.Dusk 4.Dark 2				1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow				1. Main 3. Sid 2. Yard 4. Ind					4
21. Track Name/Number					22. FRA Trac			0000			23. Annual Track Density			24. Tin	ne Table Direction			(	Code
Seabr. In				d. Lead0572 Class (1-9,				()	(gross tons in millions) 0					1. North 3. East					2
							OPER	ΑT	ING TRA	IN#	<b>#</b> 1								
25. Type of Equipment		Freight tra				. Yard/swi	_	A	. Spec. Mo	W Eq	uip. Code		Equip	ment (	Code	27. T	rain Nu	mber/S	Symbol
Consist (single entry) 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect									1.4					Yes 2. No   1 LHU					
28. Speed (recorded spe					Method(s)				er code(s)	that	annly)	1.	103	30a. Ren	notely C	ontrol			ve?
R - Recorded	ccu, ii a	(variable)	Code		ATCS	•	. Autom				pecial instru	ctions		0 = Not					
E - Estimated 5 MPH   E   b. Auto train control h. Curr								t of t	traffic		1 = Remote control portable								
c. Auto train stop i. Time											2 = Remote control tower								
29. Trailing Tons (gross tonnage, d. Cab j.Track excluding power units)										(Speci	tive)	(ye) 3 = Remote control transmitter - more than one							
e. Tramc K. Dire									ic control	ı —	Code	1			control			La	
3810 f. Interlocking 1. Yard  31. Principal Car/Unit a. Initial and Number b. Position in Train									n N/A N/A N/A N/A N/A remote control dansimiter 0  led(yes/no)   32. If railroad employee(s) tested for drug/alcohol use,										
(1) First involved		a. Illitiai t	ina rvan	11001	0.10311				cu(yes/110)	- 32.	enter the number that were			,		Alcohol		rugs	
(1) First involved N/A (derailed, struck, etc)				2				]	N/A the appropriate box							F	0	+-	0
(2) Causing (if mechanical 0					0				N/A 33. Was this			consist tra	nsporti	ing passer	ng passengers? (Y/N			i	N
cause reported)  34. Locomotive Units a. Head			N	Mid Haili			ar End		35. Cars				Lo	ade		Empty		Τ	
(1) T-4-1 in Tin			b. Man	Manual c. Remote			d. Manual c. Ren				n Equipment Consist		reight	b. Pass.			l. Pass.	e. C	aboose
(1) Total in Train		2			-	0			` '		• •	onsist	24	0	20		0		0
(2) Total Derailed  36. Equipment Damage		1	0		0	0	0		(2) Total				3	0		)	0		0
This Consist		85428	37		ck, Signal, ' tructure Da	•	41952	2	38. Prima Code	ary C	ause .	T212		39. Con	tributing	g Caus	e	N/A	
This Consist	image								gth of Time on Duty										
40. Engineer/	41. Fire			rew Members  42. Conductors   43. Brakeme			kemen		44. Engineer/Operator					45. Conductor					
Operators N/A	,,,,,,,,	0							Hrs 2 Mi						Н	Irs	2	Mi	30
Casualties to: 46	5. Railr	oad Emplo	yees 47	47. Train Passengers 48. Other					49. EOT Device?					50. Was	EOT D	evice	Properly	y Arm	ed?
Fatal		0 0			0	0			1. Yes 2. No 2					1.	Yes	2	. No		2
Nonfatal		N/A	J/A 0		0	0			51. Caboose Occupied by Crew? 1. Yes			. No   2					2		
l I						OI	PERAT	ΓIN	G TRAIN	J #2								1	
52. Type of Equipment	1.	Freight tra	in 4	l. Wor	rk train 7	. Yard/swit					uip. Code	53. Was	Equip	ment (	Code	54 T	rain Nu	nber/S	Symbol
Consist (single entry) 2. Passenger train 5. Single car 8. Light							ard/switching A. Spec. MoW Equip. C ght loco(s).					Attended?				54. Train Number/Symbol			
	3.	Commuter	train 6	5. Cut	of cars 9	. Maint./ins	spect.ca	r			N/A	1.	Yes	2.110	N/A		N/		
55. Speed (recorded spe	eed, if a	available)	Code	57.	Method(s)	of Operation	on (	ente	nter code(s) that apply)					57a. Remotely Controlled Locomotive?					
								atic block m.Special instructions n. Other than main track						0 = Not a remotely controlled					
E - Estimated 0		MPH	N/A	b.	Auto train	control h	. Curren	t of t	traffic	п. О	mei man m	ані паск		1 = Rem	ote con	trol po	ortable		

Form FRA F 6180.39 (11/06) Page 1 of 5

DEPARTME FEDERAL R						FRA F	ACTUA	L RAILE	ROAD AC	CID	ENT REP	ORT	F	RA File #	HQ-200	<u>5-5</u>					
56. Trailing Tons (gross tonnage, excluding power units)  C. Auto train stop d. Cab e. Traffic f. Interlocking							j, k	Time table/t Track warrand Direct traff Yard limits	nt control I	o. Othe	tive train conter (Specify in Code(s)	narrative)	transmitter - more than one								
58. Principal Car/Unit a. Initial and Number b. Posi							ion in Trai	n c. Load	ded(yes/no)	59. It	f railroad emp	e,									
(1) First involved (derailed, struck, etc)							N/A	enter the number that were positive in Alcoho													
(2) Causing (if mechanical cause reported)							0		N/A	60.	N/A										
61. Locomotive Units a. Head End b. Mar				Mid 7			ear End	62. Cars			Lo a. Freight	ade b. Pass.	Em c. Freight		e. Caboose						
(1) Total in Train			0			0	0 0			n Equip	pment Consist	<u> </u>	0	0	0	0					
(2) Total Derailed 0				0	0	0	0	(2) Total D	Deraile	erailed 0			0 0 0								
	Equipment Damage This Consist 0					ck, Signal, Structure D		0	65. Primar Code	65. Primary Cause Code    N/A   Code   Code						N/A					
			Numb	er of C	rew Me	mbers						Length of	Time on D	uty							
67. Engineer/ Operators		58. Firei	men 0		69. Co	nductors 0	70. Bi	akemen 0	71. Engine	eer/Op Hrs	oerator 0 M	li 0	72. Con	ductor Hrs	Mi 0						
Casualties to	. 73	. Railro	ad Emp	ovees	74. Trai	n Passenge	rs 75. Ot	her	76. EOT D	evice?	?		77. Was	Armed?							
Fatal			0	-5		0 0				1. Yes 2. No N/A 1. Yes 2						2. No   N/A					
Nonfatal									78. Caboo		cupied by Cre					N/A					
Tromula	0 0 0 Highway User Involved						0		1. Y		2. No	. T	1								
79 Type			nigiiv	vay U	sei ilivo	nveu		Rail Equipment Involved  83. Equipment Cod													
C. Tı	79. Type C. Truck-Trailer. F. Bus J. Other Motor Vehicle										3.Train (standing) 6.Light Loco(s) (moving)										
A. Auto D. Pi						N/A	1.Train(units pulling) 4.Car(s) (moving) 7.Light(s) (standing)														
B. Truck E. Va	. Motoro			r (spec. in		Code	2.Train(units pushing) 5.Car(s) (standing) 8.Other (specify in narrative) N/A  84. Position of Car Unit in Train														
80. Vehicle Speed 81. Direction geographical) Code (est. MPH at impact) 0 1.North 2.South 3.East 4.West N/A										0											
82. Position		1.110	7tii 2.50	, ddi	1.11030	Code	85. Circumstance														
Stalled on Crossing 2.Stopped on Crossing 3.Moving Over Crossing     Trapped									Rail Equipment Struck Highway User     Rail Equipment Struck by Highway User												
86a. Was the h				olved		Code	86b. Was there a hazardous materials release by														
-		-				4. Neither		N/A	1. High	way U	Jser 2. Rail	Equipment	3. Both	4. Neither	:	N/A					
	1. Highway User 2. Rail Equipment 3. Both 4. Neither N/A 1. Flighway User 2. Rail Equipment 3. Both 4. Neither N/A 86c. State here the name and quantity of the hazardous materials released, if any.  N/A																				
87. Type of				g Wag				0.Flagged by 1.Other (spec			Signaled Crossing Warning Code 89. Whistle Ban Code 1. Yes										
***								2.None		(30	ce mon ucholls	ioi coucs)		2. No							
Code(s)	N/A	N	J/A	N/	Α	N/A N/A N/A N/A 3. Unknown						known	N/A								
1. Both Sides with								Highway Si					22. Crossing Illuminated by Street Lights or Special Lights								
2. Side of venter ripproduct								l. Yes 2. No		ı		1. Yes 2. No		, I							
3. Opposite Side of Vehicle Approach						N/A		. Unknown	N/A 3. Unknown						N/A						
93. Driver's 94. Driver's Gender Code 95. Driver Drove Behind or									1 Danier and a street the Catalana and a second						Code						
Age 0	2 Famala					was Strucl 2. No	k by Second ' 3. Unknown	n <sub>I</sub>	2 Channel and then Decembed on Crossing												
								(primary ob	(primary obstruction)												
Highway Ve		OW-	N/A			nanent Stru			ng Train 5. Vegetation 7. Other (specify in narrative) graphy 6. Highway Vehicle 8. Not obstructed N/A												
101. Casulties to Highway-Rail					99. Drive	<u> </u>	удгарпу б.	rugnw	Code			Code									
Crossing Users			Killed			njured		r was l 2.Injured 3.	Uninjured		N/A	100. Was Driver in the Vehic 1. Yes 2. No				N/A					
			0		$\top$			way Vehicle	Property Da	Property Damage			103. Total Number of Highway-Rail Cros								
104. Locomotive	e Auxilia	rv Ligh	ıts?				(est.	dollar damaş Code	i i	motivo	: Auxiliary Lig				0	Code					
1. Ye		,	2. N	o				N/A		Yes		2. No				N/A					
106. Locomotive Headlight Illuminated?								Code	107. Locomotive Audible Warning Sounded?						Code						
1. Yes 2. No							N/A		1. Yes 2. No						N/A						

Form FRA F 6180.39 (11/06) Page 2 of 5

 $108.\,\,\mathrm{DRAW}\,\,\mathrm{A}\,\,\mathrm{SKETCH}\,\,\mathrm{OF}\,\,\mathrm{ACCIDENT}\,\,\mathrm{AREA}\,\,\mathrm{INCLUDING}\,\,\mathrm{ALL}\,\,\mathrm{TRACKS},\mathrm{SIGNALS},\mathrm{SWITCHES},\mathrm{STRUCTURES},\mathrm{OBJECTS},\mathrm{ETC.},\mathrm{INVOLVED.}\,\,\mathrm{HQ-05-}\,\,\mathrm{2005.jpg}$ 



Form FRA F 6180.39 (11/06) Page 3 of

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

### FRA FACTUAL RAILROAD ACCIDENT REPORT

FRA File # HQ-2005-5

### 109. SYNOPSIS OF THE ACCIDENT

On January 8, 2005, at 3:30 P.M. Central Daylight Time (CDT) a Southbound Union Pacific Railroad (UP) Local Switching Job LHU26-08 with 50 cars derailed one (1) locomotive and three (3) cars at Milepost 6.7 on UP's Houston Service Unit Seabrook Industrial Lead, near Seabrook, Texas. All three of the derailed tank cars were loaded with Hydrogen Peroxide. Two of the derailed cars were turned over and each spilled approximately 50 gallons of product. The released product was on fire but was extinguished by the Pasadena Volunteer Fire Department upon their arrival. The Fire Department initiated a "shelter in place" alert for nearby residents. The "shelter in place" order was lifted at 5:33 p.m.. In addition, Texas State Highway 146 which parallels the tracks was shut down until 11:38 p.m.. There were no injuries to the train crew or area residents.

The second locomotive sustained damages totaling \$25,000 and the rail cars sustained damages totaling \$60,428. Track damage totaled \$41,952.

At the time of the accident it was daylight and clear. The temperature was 72 degrees F.

The accident was caused by a twelve (12) inch horizontal split head in the rail.

### 110. NARRATIVE

### Circumstances Prior to the Accident

The crew of local UP LHU26-08 included a locomotive engineer, a conductor, a student conductor, and a brakeman. They first went on duty at 1 p.m. CDT, January 8, 2005, at the UP Strang Yard in La Porte, Texas. This was the home terminal for all crew members, and all received more than the statutory off duty period, prior to reporting for duty.

The tour of duty began when they pulled two locomotives off of the FMC Lead, and gathered up a number of cars that were scheduled for distribution in and around various local Industries. At one point, while comming south from the Navigation Lead with 50 cars, the crew was in the process of stopping as they approached the derailment area. The conductor and another crew member were riding the end of the 50 car cut and the locomotive engineer was seated at the controls of the leading locomotive and intending to stop to let the crew member off the engine.

In this area of the railroad there are no curves. There are three hand throw switches in the area of the accident. The grade is practically level with an elevation of 23.6 feet above sea level. Texas Highway 146 runs parallel to the tracks in area.

The railroad timetable direction of the train was south. The geographic direction was southeast. Timetable directions are used throughout this report.

### The Accident

### Train UP LHU26-08

The local switching job was being operated at an estimated speed of five (5) mph approaching the accident area. According to the engineer he was slowing the train to a stop so the LHU26-8's conductor, student conductor and brake man riding the cut of cars could get off to begin switching operations after they pulled the rear of their train clear of the Navigation Industrial Lead switch. The engineer looking out his window noticed the second unit falling to his left. The train then experienced an undesired emergency train air brake application. When the train came to a complete stop, the crew saw that they had one locomotive and two loaded tank cars derailed and lying on their sides. The conductor notified UP's Manager of Yard Operations about the derailment at 3:30 p.m. The maximum authorized speed for this train was 10 mph, as designated in the current UP Timetable No. 3 dated March 30, 2003.

The second unit, UP 190, struck the broken rail derailing it and landing on its side. The first two tank cars from the second locomotive (FMLX 17035, FMLX 17027) derailed and landed on their sides. The third car (FMLX 20034) had a set of trucks derailed but remained upright on the tracks. All three cars derailed were loaded Hydro Peroxide tank cars. According to UP's Regional Manager of Chemical Transportation and Safety, the two tank cars that were resting on their sides leaked 50 gallons of product and the released product was on fire which the Pasadena Volunteer Fire Department extinguished. The source of the released product was from the "stone" vents located on the tops of the tank cars. The locomotive spilled 1,200 gallons of diesel fuel from its fuel cap. The fuel from the locomotive was removed from the ditches with vacuum trucks and was completed on January 17, 2005.

An off-duty Pasadena Volunteer Firefighter heard the accident and notified his station. At 3:56 p.m. the Pasadena Volunteer Fire Department dispatched a response team who applied a "shelter in place" protection for residence around the surrounding area. It was lifted at 5:33 p.m. after the spill was isolated and all derailed equipment was placed upright. Texas Highway 146 was also closed to all vehicular traffic until 11:38 p.m.

The conductor reported the accident to UP's Manager of Yard Operations on duty at 3:30 p.m.

Analysis and Conclusions

Analysis

Form FRA F 6180.39 (11/06) Page of 5

# DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

## FRA FACTUAL RAILROAD ACCIDENT REPORT

FRA File # HQ-2005-5

The railroad conducted a rail test for internal defects on the Seabrook Industrial Lead on March 29, 2004 which is not required by Federal Standards for class 1 track. The test discovered two defects between mile post 0.2 and 1.7. The railroad relayed the rail that year with Continuous welded rail from mile post 0.0 to mile post 3.2. The location of the service failed rail was not in the relay. The defect was a twelve inch horizontal split head in a 90 lb. section of rail that was rolled in Ohio during 1920.

### Conclusions

The railroad was in compliance with their own, and applicable Federal standards. The train crew members were the only witnesses to the accident.

### Probable Cause

The FRA determined that the probable cause of the derailment was a horizontal spit head measuring 12 inches that broke from the parent rail as the lead locomotive unit traversed across the rail. The service failed rail then caused the second locomotive unit and the first and second tank cars to derail and fall onto their sides. The third car from the second locomotive unit had it's leading set of trucks derailed but remained upright.

Form FRA F 6180.39 (11/06) Page 5 of 5