



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2005-21***


***BNSF (BNSF)/Fort Worth & Western (FWW)
Dublin, Texas
March 6, 2005***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2005-21</u>		
1. Name of Railroad Operating Train #1 BURLINGTON NORTHERN SANTA FE CORPORATION			1a. Alphabetic Code BNSF		1b. Railroad Accident/Incident No. TX0305101			
2. Name of Railroad Operating Train #2 N/A			2a. Alphabetic Code N/A		2b. Railroad Accident/Incident N/A			
3. Name of Railroad Responsible for Track Maintenance: BNSF Rwy Co. [BNSF]			3a. Alphabetic Code BNSF		3b. Railroad Accident/Incident No. N/A			
4. U.S. DOT_AAR Grade Crossing Identification Number			5. Date of Accident/Incident Month Day Year 03 06 2005		6. Time of Accident/Incident 04:16: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM			
7. Type of Accident/Incident (single entry in code box)								
1. Derailment		4. Side collision		7. Hwy-rail crossing		10. Explosion-detonation		
2. Head on collision		5. Raking collision		8. RR grade crossing		11. Fire/violent rupture		
3. Rear end collision		6. Broken Train collision		9. Obstruction		12. Other impacts		
						13. Other (describe in narrative) 01		
8. Cars Carrying HAZMAT 7		9. HAZMAT Cars Damaged/Derailed 4		10. Cars Releasing HAZMAT 1		11. People Evacuated 0		
						12. Division SYSTEM		
13. Nearest City/Town DUBLIN			14. Milepost (to nearest tenth) 89.3		15. State Abbr Code N/A TX		16. County ERATH	
17. Temperature (F) (specify if minus) 59 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 3		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1		
21. Track Name/Number MAIN			22. FRA Track Code Class (1-9, X) 3		23. Annual Track Density (gross tons in millions) 1.153		24. Time Table Direction Code 1. North 3. East 4	
OPERATING TRAIN #1								
25. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching		A. Spec. MoW Equip. Code 1		26. Was Equipment Attended? Code 1. Yes 2. No 1		
2. Passenger train 5. Single car 8. Light loco(s).		3. Commuter train 6. Cut of cars 9. Maint./inspect.car				27. Train Number/Symbol HALTB AR306		
28. Speed (recorded speed, if available) Code R - Recorded 34 MPH R E - Estimated		30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits				30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0		
29. Trailing Tons (gross tonnage, excluding power units) 9803								
31. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded (yes/no)		
(1) First involved (derailed, struck, etc)		N/A		56		no		
(2) Causing (if mechanical cause reported)		0		0		N/A		
						32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.		
						Alcohol 0 Drugs 0		
						33. Was this consist transporting passengers? (Y/N) N		
34. Locomotive Units		a. Head End		Mid Train		Rear End		
		b. Manual		c. Remote		d. Manual c. Remote		
(1) Total in Train		3		0		0		
(2) Total Derailed		0		0		0		
						35. Cars		
						a. Freight b. Pass. c. Freight d. Pass. e. Caboose		
						(1) Total in Equipment Consist 78 0 26 0 0		
						(2) Total Derailed 18 0 1 0 0		
36. Equipment Damage		37. Track, Signal, Way, & Structure Damage		38. Primary Cause Code		39. Contributing Cause Code		
This Consist 472391		113000		H504		T205		
Number of Crew Members				Length of Time on Duty				
40. Engineer/Operators N/A		41. Firemen 0		42. Conductors 1		43. Brakemen 0		
						44. Engineer/Operator Hrs 6 Mi 45		
						45. Conductor Hrs 6 Mi 45		
Casualties to:		46. Railroad Employees		47. Train Passengers		48. Other		
Fatal		0		0		0		
Nonfatal		N/A		0		0		
						49. EOT Device? 1. Yes 2. No 1		
						50. Was EOT Device Properly Armed? 1. Yes 2. No 1		
						51. Caboose Occupied by Crew? 1. Yes 2. No N/A		
OPERATING TRAIN #2								
52. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching		A. Spec. MoW Equip. Code N/A		53. Was Equipment Attended? Code 1. Yes 2. No N/A		
2. Passenger train 5. Single car 8. Light loco(s).		3. Commuter train 6. Cut of cars 9. Maint./inspect.car				54. Train Number/Symbol N/A		
55. Speed (recorded speed, if available) Code R - Recorded 0 MPH N/A E - Estimated		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track				57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable		

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2005-21</u>	
56. Trailing Tons (gross tonnage, excluding power units) <div style="text-align: right;">0</div>		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s) <div style="display: flex; justify-content: space-around; font-size: small;"> <div>N/A</div> <div>N/A</div> <div>N/A</div> <div>N/A</div> <div>N/A</div> </div>	
						2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter <div style="text-align: right;">N/A</div>	
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)	
(1) First involved (derailed, struck, etc)		0		0		N/A	
(2) Causing (if mechanical cause reported)		0		0		N/A	
						59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	
						<div style="display: flex; justify-content: space-around; font-size: small;"> <div>Alcohol</div> <div>Drugs</div> </div> <div style="display: flex; justify-content: space-around; font-size: small;"> <div>N/A</div> <div>N/A</div> </div>	
						60. Was this consist transporting passengers? (Y/N) <div style="text-align: right;">N/A</div>	
61. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote	
(1) Total in Train		0		0		0	
(2) Total Derailed		0		0		0	
						62. Cars	
						a. Freight b. Pass. c. Freight d. Pass. e. Caboose	
						(1) Total in Equipment Consist	
						0	
						(2) Total Derailed	
						0	
63. Equipment Damage This Consist		0		64. Track, Signal, Way, & Structure Damage		0	
						65. Primary Cause Code	
						N/A	
						66. Contributing Cause Code	
						N/A	
Number of Crew Members				Length of Time on Duty			
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen	
0		0		0		0	
						71. Engineer/Operator	
						Hrs 0 Mi 0	
						72. Conductor	
						Hrs 0 Mi 0	
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other	
Fatal		0		0		0	
Nonfatal		0		0		0	
						76. EOT Device?	
						1. Yes 2. No N/A	
						77. Was EOT Device Properly Armed?	
						1. Yes 2. No N/A	
						78. Caboose Occupied by Crew?	
						1. Yes 2. No N/A	
Highway User Involved				Rail Equipment Involved			
79. Type				83. Equipment			
C. Truck-Trailer. F. Bus J. Other Motor Vehicle Code				3. Train (standing) 6. Light Loco(s) (moving) Code			
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian				1. Train(units pulling) 4. Car(s)(moving) 7. Light(s) (standing)			
B. Truck E. Van H. Motorcycle M. Other (spec. in narrative) N/A				2. Train(units pushing) 5. Car(s)(standing) 8. Other (specify in narrative) N/A			
80. Vehicle Speed (est. MPH at impact) 0				81. Direction geographical Code			
				1. North 2. South 3. East 4. West N/A			
82. Position Code				84. Position of Car Unit in Train			
1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing				0			
4. Trapped N/A							
85. Circumstance Code				86a. Was there a hazardous materials release by			
1. Rail Equipment Struck Highway User				Code			
2. Rail Equipment Struck by Highway User				N/A			
86b. Was there a hazardous materials release by				Code			
1. Highway User 2. Rail Equipment 3. Both 4. Neither				N/A			
86c. State here the name and quantity of the hazardous materials released, if any. <div style="text-align: center;">N/A</div>							
87. Type of Crossing Warning		1. Gates 4. Wig Wags 7. Crossbucks 10. Flagged by crew		88. Signaled Crossing Warning Code		89. Whistle Ban Code	
2. Cantilever FLS 5. Hwy. traffic signals 8. Stop signs 11. Other (spec. in narr.)		3. Standard FLS 6. Audible 9. Watchman 12. None		(See instructions for codes)		1. Yes 2. No 3. Unknown N/A	
Code(s) N/A N/A N/A N/A N/A N/A							
90. Location of Warning Code		91. Crossing Warning Interconnected with Highway Signals Code		92. Crossing Illuminated by Street Lights or Special Lights Code			
1. Both Sides		1. Yes		1. Yes			
2. Side of Vehicle Approach		2. No		2. No			
3. Opposite Side of Vehicle Approach N/A		3. Unknown		3. Unknown			
93. Driver's Age		94. Driver's Gender Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train Code		96. Driver Code	
0		1. Male 2. Female N/A		1. Yes 2. No 3. Unknown N/A		1. Drove around or thru the Gate 4. Stopped on Crossing	
						2. Stopped and then Proceeded 5. Other (specify in narrative) N/A	
						3. Did not Stop	
97. Driver Passed Standing Highway Vehicle Code		98. View of Track Obscured by (primary obstruction) Code		7. Other (specify in narrative)			
1. Yes 2. No 3. Unknown N/A		1. Permanent Structure 3. Passing Train 5. Vegetation		2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle		8. Not obstructed N/A	
101. Casualties to Highway-Rail Crossing Users		Killed Injured		99. Driver Was Code		100. Was Driver in the Vehicle? Code	
		0 0		1. Killed 2. Injured 3. Uninjured N/A		1. Yes 2. No N/A	
				102. Highway Vehicle Property Damage (est. dollar damage) 0		103. Total Number of Highway-Rail Crossing Users (include driver) 0	
104. Locomotive Auxiliary Lights?		Code		105. Locomotive Auxiliary Lights Operational? Code			
1. Yes 2. No		N/A		1. Yes 2. No		N/A	
106. Locomotive Headlight Illuminated?		Code		107. Locomotive Audible Warning Sounded? Code			
1. Yes 2. No		N/A		1. Yes 2. No		N/A	

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.
 DRM-21-2005.jpg



109. SYNOPSIS OF THE ACCIDENT

On Sunday, March 6, 2005, at 4:16 PM CST, while moving westbound in rain, BNSF mixed freight train H-ALTBAR-3-06, engine BNSF 5051 experienced a strong run-in and then an undesired emergency application of the train air brakes, derailling nineteen cars and destroying a bridge. There were no injuries but one tank car released hazardous materials. No evacuation was called. The cause of the derailment was train make-up. There was an empty flat car in the middle of the 9803 ton train that incurred excessive buff force which forced the car off the track.. Contributing cause was defective cross ties at the sight of the derailment that allowed the excessive force to turn over the rail on the outside of the curve.

110. NARRATIVE

The derailment occurred on the single main track of the Fort Worth and Western Railroad, Dublin Subdivision, at MP 89.3, Dublin, Erath County, Texas. Method of operation is TWC, and maximum speed is 40 MPH for freight trains with a temporary 25 mph restriction between MP 91.3 and MP 91.5. FWWR Timetable No.3 dated March 9, 2003 was in effect. The profile of the main track at MP 89.3 is undulating, with 3 degree 48 minute curve to the right on a descending grade that varies from 1.25% to 1.00% to 1.25% to 1.10% to 1.25% traveling westbound. The weather was raining and 59 degrees.

BNSF Railway Texas Division freight train H-ALTBAR-3-06 (BNSF 5051 West), which operates between Alliance Yard and Sweetwater, Tx. over the FWWR Dublin Division, consisted of three units and 104 cars, with train weight totaling 9803 tons and a length of 6474 feet.

The crew on duty at the time of the accident consisted of a locomotive engineer and a conductor. The engineer was hired July 18, 1994 as a welder, promoted to conductor April 9, 1998, and engineer April 18, 2003, his last rules test was June 14, 2004, and his last efficiency test was December 20, 2004. The conductor was hired March 20, 1969 as a welder and promoted to conductor April 9, 1998, his last rules test was March 25, 2004, and his last efficiency test was February 28, 2005. The crew was operating on a line that they were qualified on but did not regularly run over. Also, both the engineer and conductor stated that they normally operated manifest and inter-modal trains and were not as familiar operating heavy mixed freight trains.

They both were on duty at Alliance Yard on Sunday, March 6, 2005 at 9:30 AM after statutory rest of 17 hours and 30 minutes for the engineer and 70 hours and 45 minutes for the conductor. Their work orders included notification that the train had received a Class 1 Inspection and Air Brake Test at Alliance at 9:45 AM March 6, 2005.

H-ALTBAR-3-06 departed from Alliance Yard at 10:45 AM CST and traveled west on the Dublin Subdivision without incident. The train possessed a track warrant from MP 3 (at the north end of the Dublin Sub) to Ricker (at the south end) on the main track. As the train approached Dublin the engineer was seated at the controls and the conductor was seated on the opposite side of the controlling unit.

The engineer stated that he was moving at 28 mph in throttle position Dynamic 6 as the head end of the train crested a hill and approached a lefthand curve. He moved to Dynamic 8, and then set 6 lbs of air as the train entered a righthand curve descending the 1.25% grade onto a bridge where the grade eases to 1.00%. After the remainder of the train crested the hill it continued to gain speed so he set 3 more lbs of air and then felt a strong run-in. After a second run-in the air brakes went into emergency and the train stopped approximately 1/4 mile further. The speed at the time of derailment was recorded at 34 mph.

The conductor walked back along the train to assess the situation and discovered that the 56th car from the engine had derailed and the rail was torn up. The rear of the train was not immediately visible. He continued toward the rear and found that the 56th through 74th cars were derailed and the bridge at the bottom of the dip was destroyed. There were no injuries but one tank car containing crude oil was leaking.

The engineer and conductor stated that they queried the trainmaster at Alliance about the train's makeup when reviewing their paperwork and pointed out the empty flat car placed in the middle of the train with the heaviest cars placed toward the rear. They were told that the computer generated train profile showed that the train was approved to go. The empty flat car was BNSF 231045 and was reported on the consist at 82 tons. Closer inspection reveals that the empty container car consists of three platforms - in effect three empty cars weighing 27 tons each - coupled to eleven auto rack cars equipped with sliding draw heads, that are followed by thirty-three more heavy cars weighing 4069 tons at the rear of the train.

The train list shows the following from front to rear:

3 Locomotives - 6 axle 4400hp each

37 loads and 20 empties 4685 tons
1 empty container flat car 82 tons
44 loads and 3 empties 5037 tons.

In effect, the train was made up as follows:

3 -6 axle locomotives 13,200 hp
37 loads and 20 empties 4685 tons
1 platform 27 tons
1 platform 27 tons
1 platform 27 tons
44 loads and 3 empties 5037 tons

Both the engineer and conductor involved in the derailment were drug and alcohol tested and both employees returned negative results.

Factors contributing to the accident were:

1) Train Makeup: an empty flat car was placed as the 56th car in the 9803 ton train with 44 loaded cars weighing 5037 tons placed behind. My inspection shows that empty flat car BNSF 231045 is a three platform double stack container car and each platform rides on it's own wheels. It is in effect three 27 ton flat cars for train handling purposes. This car was followed by eleven tri-level auto rack cars that provided excessive slack action whenever the train increased or decreased speed. This, coupled to the fact that 27 cars placed further to the rear weighed between 100 to 141 tons created a whiplash effect while operating on the undulating terrain. Had this been considered, the train should have been made up with the empty flat car placed further back in the train.

2) Excessive slack action due to eleven auto rack cars with sliding drawheads in middle of heavy train placed 57 through 67 made train handling on the undulating terrain extremely difficult.

3) Train handling: a train of this weight and length with the heaviest weight on the rear could better have been operated utilizing the train air brake and not relying as heavily on the dynamic brake. The resistance from the head end created by increasing dynamic braking while on a downgrade caused the heavy rear end of the train to compress the sliding draw heads on the eleven auto racks and increased the buff forces that were applied against the lighter flat car and pushed the car off the track on the curve. Train air braking could have prevented the degree of force pushing against the flat car by retarding the forward advance of the rear of the train through applying and releasing the train air brake.

4) Crew qualifications: The engineer had twenty-five months' service as an engineer and was not regularly used on this territory or on this type of train. Additionally, the engineer incurred two efficiency test failures for excessive speed during the past nine months; one for exceeding maximum timetable speed and one for exceeding a temporary speed restriction. At the time of the accident the engineer was attempting to reduce his train speed from 28 mph to 25 mph to comply with a temporary speed restriction two miles ahead.

The FRA determined that the cause of the accident was determined by BNSF to be H504 excessive buffing or slack action due to train make-up. Contributing cause was defective or missing cross ties, T205.