



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2005-25***

***Union Pacific (UP)
Wellington, Missouri
April 2, 2005***


Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2005-25</u>	
1. Name of Railroad Operating Train #1 UNION PACIFIC RAILROAD COMPANY			1a. Alphabetic Code UP		1b. Railroad Accident/Incident No. 0405SL001		
2. Name of Railroad Operating Train #2 N/A			2a. Alphabetic Code N/A		2b. Railroad Accident/Incident N/A		
3. Name of Railroad Responsible for Track Maintenance: Union Pacific RR Co. [UP]			3a. Alphabetic Code UP		3b. Railroad Accident/Incident No. 0405SL001		
4. U.S. DOT_AAR Grade Crossing Identification Number			5. Date of Accident/Incident Month Day Year 04 02 2005		6. Time of Accident/Incident 05:45: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM		
7. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction
					10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts		13. Other (describe in narrative) 01
8. Cars Carrying HAZMAT 0		9. HAZMAT Cars Damaged/Derailed 0		10. Cars Releasing HAZMAT 0		11. People Evacuated 0	
						12. Division St Louis	
13. Nearest City/Town Wellington			14. Milepost (to nearest tenth) 254.7		15. State Abbr Code N/A MO		16. County LAFAYETTE
17. Temperature (F) (specify if minus) 55 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 1		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1	
21. Track Name/Number Single Main			22. FRA Track Code Class (1-9, X) 4		23. Annual Track Density (gross tons in millions) 84		24. Time Table Direction Code 1. North 3. East 3
OPERATING TRAIN #1							
25. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car	
						A. Spec. MoW Equip. Code 1	
						26. Was Equipment Attended? 1. Yes 2. No 1	
						27. Train Number/Symbol QNPW XP1	
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 36 MPH R		30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits		30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		0	
29. Trailing Tons (gross tonnage, excluding power units) 8496							
31. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded (yes/no)	
(1) First involved (derailed, struck, etc)		N/A		43		yes	
(2) Causing (if mechanical cause reported)		0		0		N/A	
						32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	
						Alcohol Drugs 0 0	
						33. Was this consist transporting passengers? (Y/N) N	
34. Locomotive Units		a. Head End		Mid Train		Rear End	
		b. Manual		c. Remote		d. Manual c. Remote	
(1) Total in Train		2		0		0	
(2) Total Derailed		0		0		0	
						35. Cars	
						a. Freight b. Pass. c. Freight d. Pass. e. Caboose	
						(1) Total in Equipment Consist 68 0 11 0 0	
						(2) Total Derailed 8 0 10 0 0	
36. Equipment Damage		This Consist 561847		37. Track, Signal, Way, & Structure Damage 66692		38. Primary Cause Code T221	
						39. Contributing Cause Code N/A	
Number of Crew Members				Length of Time on Duty			
40. Engineer/Operators N/A		41. Firemen 0		42. Conductors 1		43. Brakemen 0	
						44. Engineer/Operator Hrs 2 Mi 45	
						45. Conductor Hrs 2 Mi 45	
Casualties to:		46. Railroad Employees		47. Train Passengers		48. Other	
Fatal		0		0		0	
Nonfatal		N/A		0		0	
						49. EOT Device? 1. Yes 2. No 1	
						50. Was EOT Device Properly Armed? 1. Yes 2. No 1	
						51. Caboose Occupied by Crew? 1. Yes 2. No N/A	
OPERATING TRAIN #2							
52. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars		7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car	
						A. Spec. MoW Equip. Code N/A	
						53. Was Equipment Attended? 1. Yes 2. No N/A	
						54. Train Number/Symbol N/A	
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track		57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable			

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2005-25</u>			
56. Trailing Tons (gross tonnage, excluding power units) 0		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A	
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	
(1) First involved (derailed, struck, etc)		0		0		N/A		Alcohol N/A	
(2) Causing (if mechanical cause reported)		0		0		N/A		Drugs N/A	
60. Was this consist transporting passengers? (Y/N)		N/A							
61. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote		62. Cars	
(1) Total in Train		0		0		0		(1) Total in Equipment Consist	
(2) Total Derailed		0		0		0		(2) Total Derailed	
63. Equipment Damage This Consist		0		64. Track, Signal, Way, & Structure Damage		0		65. Primary Cause Code N/A	
66. Contributing Cause Code		N/A							
Number of Crew Members				Length of Time on Duty					
67. Engineer/Operators 0		68. Firemen 0		69. Conductors 0		70. Brakemen 0		71. Engineer/Operator Hrs 0 Mi 0	
72. Conductor Hrs 0 Mi 0									
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?	
Fatal		0		0		0		1. Yes 2. No N/A	
Nonfatal		0		0		0		77. Was EOT Device Properly Armed? 1. Yes 2. No N/A	
78. Caboose Occupied by Crew?		N/A							
1. Yes 2. No									
Highway User Involved					Rail Equipment Involved				
79. Type C. Truck-Trailer. F. Bus J. Other Motor Vehicle A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative) Code N/A					83. Equipment 3. Train (standing) 6. Light Loco(s) (moving) 1. Train(units pulling) 4. Car(s)(moving) 7. Light(s) (standing) 2. Train(units pushing) 5. Car(s)(standing) 8. Other (specify in narrative) Code N/A				
80. Vehicle Speed (est. MPH at impact) 0					81. Direction geographical 1. North 2. South 3. East 4. West Code N/A				
82. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped Code N/A					84. Position of Car Unit in Train 0				
85. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User Code N/A					86a. Was there a hazardous materials release by Code N/A				
86b. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither Code N/A					1. Highway User 2. Rail Equipment 3. Both 4. Neither Code N/A				
86c. State here the name and quantity of the hazardous materials released, if any. N/A									
87. Type of Crossing 1. Gates 4. Wig Wags 7. Crossbucks 10. Flagged by crew 2. Cantilever FLS 5. Hwy. traffic signals 8. Stop signs 11. Other (spec. in narr.) Warning 3. Standard FLS 6. Audible 9. Watchman 12. None Code(s) N/A N/A N/A N/A N/A N/A					88. Signaled Crossing Warning (See instructions for codes) Code N/A				
89. Whistle Ban 1. Yes 2. No 3. Unknown Code N/A									
90. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach Code N/A					91. Crossing Warning Interconnected with Highway Signals 1. Yes 2. No 3. Unknown Code N/A				
92. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown Code N/A									
93. Driver's Age 0		94. Driver's Gender 1. Male 2. Female Code N/A		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown Code N/A		96. Driver 1. Drove around or thru the Gate 4. Stopped on Crossing 2. Stopped and then Proceeded 5. Other (specify in narrative) 3. Did not Stop Code N/A			
97. Driver Passed Standing Highway Vehicle 1. Yes 2. No 3. Unknown Code N/A		98. View of Track Obscured by (primary obstruction) 1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative) 2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed Code N/A							
101. Casualties to Highway-Rail Crossing Users		Killed 0		Injured 0		99. Driver Was 1. Killed 2. Injured 3. Uninjured Code N/A		100. Was Driver in the Vehicle? 1. Yes 2. No Code N/A	
102. Highway Vehicle Property Damage (est. dollar damage)		0							
103. Total Number of Highway-Rail Crossing Users (include driver)		0							
104. Locomotive Auxiliary Lights? 1. Yes 2. No Code N/A					105. Locomotive Auxiliary Lights Operational? 1. Yes 2. No Code N/A				
106. Locomotive Headlight Illuminated? 1. Yes 2. No Code N/A					107. Locomotive Audible Warning Sounded? 1. Yes 2. No Code N/A				

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

HQ-25-
2005
Sketch.jpg



109. SYNOPSIS OF THE ACCIDENT

On April 2, 2005, at 5:45 a.m. CST, an eastbound Union Pacific (UP) freight train, Train Symbol QNPWXP-1, derailed 18 cars of its 79-car train (cars 43 through 60 from the head end). The derailment occurred on single main track, in Lafayette County, approximately 1-1/2 miles west of Wellington, Missouri, at milepost (MP) 254.7, on the UP's, St. Louis Service Unit, River Subdivision.

The derailment resulted in \$421,925 damage to equipment, and \$66,692 damage to track, signal and structures.

At the time of the accident, it was clear and dawn. The temperature was 55 degrees Fahrenheit.

The probable cause of the derailment was a broken rail that occurred as a vertical split head.

110. NARRATIVE

The following information was obtained from an investigation that was conducted by the Federal Railroad Administration.

Circumstances Prior to the Accident

The crew of Train Symbol QNPWXP-1, consisting of a locomotive engineer and a conductor, went on duty in Kansas City, Missouri, at 3:00 a.m., CST, on April 2, 2005, after receiving their statutory off duty rest period. The crew was scheduled to operate from Kansas City to Jefferson City, Missouri.

Their assigned freight train consisted of two locomotives, 68 loaded, and 11 empty cars. It was 5,020 feet in length and weighed 8,496 tons. The train originated at North Platte, Nebraska. The train received its initial terminal train air brake test on April 1, 2005, 6:15 a.m. CST, in North Platte.

As the eastbound train approached the accident area, the engineer was seated at the controls on the south side of the locomotive. The conductor was seated across from the engineer on the north side of the locomotive cab.

In the area the derailment occurred, the track was tangent with a 0.42-percent descending grade.

The Accident

At the time the accident occurred, the train was being operated at 36 miles per hour (mph). This speed was recorded by the event recorder on the lead locomotive, the UP 2297. The maximum operating speed for this freight train was 50 mph, as designated in the current UP Timetable Special Instructions items No. 2A and No. 2B, in effect 0001 Sunday, April 6, 2003.

The crew members stated that just after they had gone across a bridge at milepost 254.6, they felt, what they both described as a slight tug. They then experienced an undesired train air brake emergency application. Upon inspection of their train, it was discovered that 18 cars of their 79 car train had derailed (cars 43 through 60 from the head end).

There were no injuries to any person as a result of this derailment and no evacuation was necessary.

Analysis

The last internal rail defect inspection was conducted on February 28, 2005. This test was performed by UP DC-13. No defects were noted in the area where the derailment occurred. The UP, at the time of the derailment, was performing internal rail defect inspections on a 45 day cycle.

The last hi-rail visual track inspection was conducted on March 31, 2005. There were no defects noted in the immediate area of the accident on the UP Track Inspection Record.

The last geometry test was conducted on November 22, 2004. This test was conducted by the UP's geometry test vehicle, car No. EC-4. The strip chart from the test vehicle for that day revealed no abnormalities in the area of the accident.

The 25-ft. section of south rail on the ballast deck bridge at Milepost No. 254.7 contained a vertical crack through the ball of the rail extending into the gage corner of the web. The crack extended throughout the 25-ft. section of rail. The rust on the web of the rail along the crack indicated a defective condition, along with the darkened area of the tread portion of ball where vertical contact was not made due to the ball starting to separate. At the point of derailment a 15-foot section of ball

broke off and subsequently derailed 18 cars.

The crew members of Train Symbol QNPWXP-1 were FRA mandatory, post accident, toxicologically tested. The test results obtained from the FRA Alcohol and Drug Control Program Manager were negative.

Conclusion

The UP was in compliance with their own applicable internal rules and standards, both operationally and those associated with track, as well as applicable Federal requirements.

Probable Cause

The probable cause of the derailment was a vertical split head rail (broken rail). The split head appeared to have grown rapidly from the light orange rust throughout the cracks and the internal visual inspection of the break. The FRA concurs with the findings.