



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2005-40***

***Burlington Northern Santa Fe (BNSF)
Casselton, North Dakota
May 5, 2005***


Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2005-40</u>					
1. Name of Railroad Operating Train #1 BNSF Rwy Co. [BNSF]			1a. Alphabetic Code BNSF		1b. Railroad Accident/Incident No. TC0505104						
2. Name of Railroad Operating Train #2 N/A			2a. Alphabetic Code N/A		2b. Railroad Accident/Incident N/A						
3. Name of Railroad Responsible for Track Maintenance: BNSF Rwy Co. [BNSF]			3a. Alphabetic Code BNSF		3b. Railroad Accident/Incident No. TC0505104						
4. U.S. DOT_AAR Grade Crossing Identification Number			5. Date of Accident/Incident Month 05 Day 05 Year 2005		6. Time of Accident/Incident 02:15: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM						
7. Type of Accident/Incident (single entry in code box) 1. Derailment 4. Side collision 7. Hwy-rail crossing 10. Explosion-detonation 13. Other (describe in narrative) 2. Head on collision 5. Raking collision 8. RR grade crossing 11. Fire/violent rupture 3. Rear end collision 6. Broken Train collision 9. Obstruction 12. Other impacts <div style="text-align: right;">01</div>											
8. Cars Carrying HAZMAT 0		9. HAZMAT Cars Damaged/Derailed 0		10. Cars Releasing HAZMAT 0		11. People Evacuated 0					
12. Division Twin Cities											
13. Nearest City/Town Cassleton			14. Milepost (to nearest tenth) 28.5		15. State Abbr Code N/A ND		16. County CASS				
17. Temperature (F) (specify if minus) 77 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1					
21. Track Name/Number Main 2			22. FRA Track Class (1-9, X) Code 4		23. Annual Track Density (gross tons in millions) 62.18		24. Time Table Direction Code 1. North 3. East 4				
OPERATING TRAIN #1											
25. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching A. Spec. MoW Equip. Code		26. Was Equipment Attended? Code 1. Yes 2. No 1		27. Train Number/Symbol GEDU KAL90					
28. Speed (recorded speed, if available) Code R - Recorded 36 MPH R E - Estimated		30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits e N/A N/A N/A N/A				30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0					
29. Trailing Tons (gross tonnage, excluding power units) 14912											
31. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded (yes/no)					
(1) First involved (derailed, struck, etc)		N/A		59		yes					
(2) Causing (if mechanical cause reported)		0		0		N/A					
						32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.					
						<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:50%;">Alcohol</td> <td style="width:50%;">Drugs</td> </tr> <tr> <td style="text-align: center;">0</td> <td style="text-align: center;">0</td> </tr> </table>		Alcohol	Drugs	0	0
Alcohol	Drugs										
0	0										
						33. Was this consist transporting passengers? (Y/N) N					
34. Locomotive Units		a. Head End		Mid Train		Rear End					
		b. Manual		c. Remote		d. Manual c. Remote					
(1) Total in Train		3		0		0					
(2) Total Derailed		0		0		0					
						35. Cars					
						a. Freight b. Pass. c. Freight d. Pass. e. Caboose					
						(1) Total in Equipment Consist 107 0 0 0 0					
						(2) Total Derailed 25 0 0 0 0					
36. Equipment Damage		This Consist 1111439		37. Track, Signal, Way, & Structure Damage 419312		38. Primary Cause Code T109					
						39. Contributing Cause Code N/A					
Number of Crew Members				Length of Time on Duty							
40. Engineer/Operators N/A		41. Firemen 0		42. Conductors 1		43. Brakemen 0					
						44. Engineer/Operator Hrs 1 Mi 45					
						45. Conductor Hrs 1 Mi 45					
Casualties to:		46. Railroad Employees		47. Train Passengers		48. Other					
Fatal		0		0		0					
Nonfatal		N/A		0		0					
						49. EOT Device? 1. Yes 2. No 1					
						50. Was EOT Device Properly Armed? 1. Yes 2. No 1					
						51. Caboose Occupied by Crew? 1. Yes 2. No N/A					
OPERATING TRAIN #2											
52. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching A. Spec. MoW Equip. Code		53. Was Equipment Attended? Code 1. Yes 2. No 1		54. Train Number/Symbol N/A					
		2. Passenger train 5. Single car 8. Light loco(s).									
		3. Commuter train 6. Cut of cars 9. Maint./inspect.car									
55. Speed (recorded speed, if available) Code R - Recorded 0 MPH E E - Estimated		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track				57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable					

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2005-40</u>											
56. Trailing Tons (gross tonnage, excluding power units)		0		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s) p N/A N/A N/A N/A		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		0					
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.									
(1) First involved (derailed, struck, etc)		Weed 1		1		yes						Alcohol 0		Drugs 0			
(2) Causing (if mechanical cause reported)		0		0		N/A		60. Was this consist transporting passengers? (Y/N)						N/A			
61. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote		62. Cars		Loade a. Freight b. Pass.		Empty c. Freight d. Pass.		e. Caboose			
(1) Total in Train		0		0 0		0 0		(1) Total in Equipment Consist		1 0		0 0		0 0			
(2) Total Derailed		0		0 0		0 0		(2) Total Derailed		1 0		0 0		0 0			
63. Equipment Damage This Consist		150000		64. Track, Signal, Way, & Structure Damage		0		65. Primary Cause Code		T109		66. Contributing Cause Code		N/A			
Number of Crew Members								Length of Time on Duty									
67. Engineer/Operators		1		68. Firemen		0		69. Conductors		1		70. Brakemen		0			
71. Engineer/Operator		Hrs 7 Mi 15		72. Conductor		Hrs 7 Mi 15		76. EOT Device?		1. Yes 2. No 2		77. Was EOT Device Properly Armed?		1. Yes 2. No N/A			
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		78. Caboose Occupied by Crew?		1. Yes 2. No		N/A					
Fatal		0		0		0											
Nonfatal		1		0		0											
Highway User Involved								Rail Equipment Involved									
79. Type C. Truck-Trailer. F. Bus J. Other Motor Vehicle A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)								83. Equipment 3. Train (standing) 6. Light Loco(s) (moving) 1. Train(units pulling) 4. Car(s)(moving) 7. Light(s) (standing) 2. Train(units pushing) 5. Car(s)(standing) 8. Other (specify in narrative)									
80. Vehicle Speed (est. MPH at impact) 0								81. Direction geographical 1. North 2. South 3. East 4. West									
82. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped								85. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User									
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?								86b. Was there a hazardous materials release by									
1. Highway User 2. Rail Equipment 3. Both 4. Neither								1. Highway User 2. Rail Equipment 3. Both 4. Neither									
86c. State here the name and quantity of the hazardous materials released, if any. N/A																	
87. Type of Crossing 1. Gates 4. Wig Wags 7. Crossbucks 10. Flagged by crew 2. Cantilever FLS 5. Hwy. traffic signals 8. Stop signs 11. Other (spec. in narr.) Warning 3. Standard FLS 6. Audible 9. Watchman 12. None								88. Signaled Crossing Warning (See instructions for codes)				89. Whistle Ban 1. Yes 2. No 3. Unknown					
Code(s) N/A N/A N/A N/A N/A N/A												N/A					
90. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach								Code N/A				91. Crossing Warning Interconnected with Highway Signals 1. Yes 2. No 3. Unknown					
								Code N/A				92. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown					
93. Driver's Age 0		94. Driver's Gender 1. Male 2. Female		Code N/A		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown		Code N/A		96. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop		4. Stopped on Crossing 5. Other (specify in narrative)		Code N/A			
97. Driver Passed Standing Highway Vehicle 1. Yes 2. No 3. Unknown								Code N/A				98. View of Track Obscured by (primary obstruction) 1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative) 2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed					
101. Casualties to Highway-Rail Crossing Users								Killed 0		Injured 0		99. Driver Was 1. Killed 2. Injured 3. Uninjured		Code N/A		100. Was Driver in the Vehicle? 1. Yes 2. No	
												102. Highway Vehicle Property Damage (est. dollar damage)		0		103. Total Number of Highway-Rail Crossing Users (include driver)	
104. Locomotive Auxiliary Lights? 1. Yes 2. No								Code N/A				105. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A	
106. Locomotive Headlight Illuminated? 1. Yes 2. No								Code N/A				107. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A	

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

HQ40sketc
h.jpg



109. SYNOPSIS OF THE ACCIDENT

A westbound BNSF Railway Company (BNSF) freight train derailed on May 5, 2005, at 2:15 p.m., CDT. The derailment occurred west of Casselton, North Dakota, on Main 2 track, at milepost 28.5, on the Twin Cities Division, KO Subdivision.

The train consisted of three locomotives and 107 loaded grain cars. The 56th car in the consist derailed as it passed over the Red River Valley & Western Railroad Company junction switch and a general derailment of the following 24 cars ensued. The first car that derailed went north toward Main 1 track and struck a weed spray truck, contracted by BNSF and owned by "Right A Way Applicators" (RAW). The RAW spray truck was on Main 1 track.

There were no injuries to the train crew. The operator and passenger of the spray truck were transported to a hospital in Fargo, North Dakota, approximately 25 miles to the east. The operator was admitted for minor injuries and released the same day. The passenger sustained minor injuries and was not admitted to the hospital.

There was a small amount of weed poison and diesel fuel spilled from the spray truck. There were no evacuations.

The railroad estimated that there was track damage of \$419,312 and equipment damage of \$1,111,439.

The contractor (RAW) estimated damages of \$150,000 to their spray truck.

At the time of the accident it was 77 °F and clear.

The probable cause of the accident was "track alignment irregular (buckled/sunkink)".

110. NARRATIVE

The following information was obtained from an investigation that was conducted by the Federal Railroad Administration.

Circumstances Prior to the Accident

The crew of Train Symbol G-EDUKAS9-03 included a locomotive engineer and a conductor. They first went on duty at 12:30 p.m., CDT, May 5, 2005, at the Dilworth, Minnesota Yard, the away from home terminal for the crew. The home terminal for the engineer and the conductor is Minot, North Dakota. Prior to reporting for duty, both received a required statutory off-duty period.

Their assigned freight train consisted of three locomotives, 107 loaded cars, 14,912 trailing tons, and was 6,623 feet in length. It was a grain train traveling from Dilworth, Minnesota, to Minot, North Dakota, a distance of 254.2 miles.

When westbound train, G-EDUKAS9-03, got to milepost 20.2, the dispatcher had the train cross over from Main 1 track to Main 2 track because the weed spray truck was working on Main 1 track.

As the train approached the accident area, the locomotive engineer was seated at the controls on the right (north) side of the leading locomotive. The conductor was seated on the left (south) side.

Approaching the accident site from the east traversing westward both main tracks are tangent for several miles and tangent for several miles beyond the accident location. There is a right hand number 20 turnout at the Point of Derailment (POD). The turnout is the junction for the Red River Valley & Western Railroad Company (RRVW). The track at this location turns to the south. The derailment occurred on a trailing point movement through the switch of the turnout. The grade in the area of the accident is virtually level.

In the accident area, trains operate on double main tracks under the authority of a Traffic Control System(TCS). Other than train movements, such as the spray truck, operation on the main tracks are under the authority of Track and Time. The BNSF System Special Instructions No.10, effective April 3, 2005 and BNSF Twin Cities Division Timetable No.1, effective January 20, 2002, authorizes a maximum speed of 60 mph, FRA Class 4 track. Because of a derailment at the same location on December 30, 2004, a temporary 40 mph speed restriction, FRA class 3, was in place. The timetable and geographic direction the train was traveling was west.

After completing an off duty period, a BNSF track inspector reported for duty at Fargo, North Dakota, on May 5, 2005. The employee was instructed to provide on track protection for the RAW weed spray truck from Fargo (milepost 7) to Surrey Junction (milepost 31.1). He was also instructed to inspect the track section on both main tracks between the same limits. The RAW truck was contracted to spray the track section between these limits.

The track inspector received main track authority on Main 1 track from the BNSF dispatcher in Fort Worth, Texas, then placed his hi-rail truck on the track ahead of the weed spray truck for westbound movement. The track inspector had come to a stop at milepost 28.6 and the RAW weed spray truck was coming to a stop 200 feet behind him when the accident occurred.

The Accident

The locomotive engineer stated the trip was uneventful approaching the accident site. He also stated that there were no problems with the operation of the train. While approaching, and at the time the accident occurred, the train was being operated at 36 mph. This speed was recorded on the lead locomotive event recorder.

According to the train crew the accident occurred at approximately 2:15 p. m., CDT.

The locomotive engineer first became aware of the derailment after a train induced emergency brake application occurred. When the crew felt the brake application, they looked back and saw a cloud of dust.

After coming to a stop, the conductor notified the dispatcher that the train had derailed. The track inspector immediately called the train crew on the radio and advised them that the derailed cars had struck the spray truck. The conductor then instructed the dispatcher to call an ambulance.

Further examination of the scene noted that 25 cars had derailed. The initial point of derailment was at milepost 28.5 at the Red River Valley & Western Railroad Company junction switch. The derailment happened on Main 2 track. The first car derailed struck the RAW weed spray truck on Main 1 track. The driver of the spray truck was trapped inside the cab of the truck for approximately one hour.

Cass County Sheriff's Department, Casselton Ambulance Service, and Casselton Fire Department responded to the accident. Life Flight Service was activated at the request of the Casselton Fire Department, but was not used. After the driver was extricated from the truck he was transported by ambulance to Merritt Care Center in Fargo, North Dakota, where he was treated for minor injuries and released. The passenger in the RAW weed spray truck was examined by Emergency Medical Technicians from the Casselton Fire Department then transported in an ambulance to the same hospital. Having received only minor scrapes and bruises, the passenger was not admitted to the hospital.

All of the 25 derailed cars contained soy beans. There was a small amount of weed poison and a small amount of diesel fuel spilled from the truck as a result of the accident. There were no evacuations.

Analysis and Conclusion

FRA Post Accident Toxicology Testing, as required under Title 49 CFR, Part 219, Subpart C, was conducted on the train crew. The results were negative.

An inspection of the data print out from the locomotive event recorder indicated no unusual events related to train handling.

On December 30, 2004, there had been a previous derailment on Main 2 track at milepost 28.5, caused by a journal (roller bearing) failure from overheating. As a result of that derailment there were 11 (39 foot) track panels installed on Main1 track. In addition, there were 26 (39 foot) track panels installed on Main 2 track. There is not a record of the actual or estimated amount of rail added in this derailment location. BNSF engineering officials estimate the total length of the track panels placed in the derailment area was 1040 feet on Main 2 track. The 136 lb. track panels were installed on December 31, 2004. BNSF engineering officials estimate that the temperature when the panels were installed was approximately 15 °F.

On February 15, 2005, a number 20 turnout was installed at milepost 28.5 on Main 2 track, connecting it to the Red River Valley & Western Railroad Company main track. This turnout was installed in the section of track where the derailment panels had been installed on December 31, 2004. The length of the turnout installed was 252 feet in length and was 136 lb. rail. There is not a record of rail added or removed when the turnout was placed. The track foreman stated that there was no rail added, but it was agreed upon by him and the roadmaster that the rail needed to be adjusted (rail removed) at a later date. The track foreman stated he thought he came back later and adjusted the rail at this location. There is no record of his activity as required by BNSF CWR procedures.

The turnout was surfaced twice by a surfacing crew immediately after it was installed. The track foreman, surfacing crew foreman, and surfacing equipment operator each stated that every time the switch area of the turnout was surfaced the stock rails would rise out of the switch plates, allowing for inadequate securement of the stock rails. They also stated that they had a hard time getting the stock rails placed back in the switch plates, which suggests there was too much rail in the track section. The surfacing crew foreman stated that he recorded the temperature on the day of surfacing day as 38°F.

On February 17, 2005, a BNSF welder made a thermite weld on the north rail just west of the switch on Main 2 track. He showed on the BNSF "Combined Rail Adjustment Report" that one-quarter inch of rail was added at this location.

On May 1, 2005, a BNSF track inspector inspected Main 2 track. He traversed the track with a hi-rail truck during the inspection. On May 3, 2005, the track inspector again inspected Main 2 track but did not traverse it. On May 05, 2005, while traversing Main 1 track, the track inspector conducted an inspection of Main 2 track. This was the last inspection prior to the derailment which occurred shortly after. All inspections revealed no defective conditions in the area of the derailment.

On May 02, 2005, a surfacing crew surfaced the track section on both ends of the number 20 turnout at milepost 28.5. The surfacing crew foreman stated that he just surfaced the approaches to the switch. He did not surface the switch area, because he feared that the stock rails might rise out of the switch plates as they did during the two previous times that surfacing was conducted. The surfacing crew foreman placed a 25 mph slow order at this location for two tonnage trains after it was surfaced, per BNSF policy. After the two tonnage trains operated the slow order was raised to 40 mph.

According to the BNSF Engineering Instructions Chapter 6, Rail, revised November 1, 2004, in Table 6-3 on page 6-17, the neutral temperature of the rail where the above activity took place, was drastically lowered from 90 °F (BNSF standards) to 15 °F. On December 31, 2004, when the 1040 feet was installed on Main 2 track, about 5-3/4 inches of rail was added. On February 15, 2005, when the turnout panel was installed on Main 2 track, one-half inch of rail was added. On February 17, 2005, a thermite weld was made on the north rail at this location, adding one-quarter inch of rail. On May 5, 2005, when the derailment occurred, the air temperature was 77 °F. There was approximately 4-1/4 inches too much rail in the track at this location for this temperature.

When the stock rails rose out of the switch plates each time it was disturbed by surfacing, should have been an indication that there was too much rail in the track section.

Probable Cause

The fra determined that the probable cause of the derailment was "track alignment irregular (buckled/sunkink)" at the switch location of the turnout, milepost 28.5 on Main 2 track. The BNSF's failure to follow their own CWR procedures for maintaining the neutral temperature of the rail and the recording of rail added or removed from the main line may have been a contributing factor.