

Federal Railroad Administration Office of Safety Headquarters Assigned Accident Investigation Report HQ-2005-42

Burlington Northern Santa Fe (BNSF) Hannibal, Missouri May 12, 2005

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

DEPARTMENT FEDERAL RAILR	OF TRA ROAD A	ANSPORT ADMINIST	ΓΑΤΙ ΓRAT	ON 'ION	FRA FA	ACTUA	AL RA	ILR	OAD A	CCI	DENT R	EPOR'	Г	Ι	FRA Fi	le # 1	HQ-200	<u>15-42</u>	
1.Name of Railroad C	1a. Alphabetic Code					1b. 1	1b. Railroad Accident/Incident No.												
2.Name of Railroad C	2a	BINSF   2a. Alphabetic Code   2					b. Railroad Accident/Incident												
N/A 3.Name of Railroad R	3a.	Alphabeti	3b. 1	N/A 3b. Railroad Accident/Incident No															
N/A	N/A						N/A												
4. U.S. DOT_AAR G	5. E	Date of Acc Month	6. T	. Time of Accident/Incident															
					063902D				05 12 2005					01:15: AM 🖌 PM					
7. Type of Accident/I	ndicent	1. Derail	ment		4. Side collision				Hwy-rail	crossi	ng 10.	-deton	detonation 13. Other (describe in						
(single entry in coo	le box)	2. Head of 3. Rear e	nd col	llision	10n5. Raking collisionsion6. Broken Train collision				o. KK grade crossing       11. Fire/violen         9. Obstruction       12. Other impation					rupture (deserve in narrative) cts 07					
8. Cars Carrying 9. HAZMAT Cars					10. Cars Releasir					11	1. People				12. Division			07	
HAZMAT 10		Damaged/	Derail	ed	0	HAZMA	Т		0	E	Evacuated			0	Springfield			d	
13. Nearest City/Tow	'n				14. Milepost					15. S	. State Abbr Code			. County					
		Hanr	nibal				icarest u	1	19.83		N/A	MO			MARION				
17. Temperature (F) (specify if minus)	if vif minus) 18. Visibility				gle entry) Jusk	Code	19. W	Veath	her (single e		ntry)			20. Typ	ck Siding		Code		
(speen) in minus) 67	67 F 2. Day			4.1	Dark	2	2	. Clou	udy 4. Fo	og	6.Snow	2	2 2.		Yard 4. Industry		g try	1	
21. Track Name/Number						22. FRA	Track	0	Code 23. Annual Track			k Density		24. Time Table Direction			tion Fast	Code	
		Si	ngle N	Aain T	rack	2 millio						4	7		1. Notur 5. East				
							OPER	ATI	NG TRA	AIN #	1			•					
25. Type of Equipme	A.	Spec. Mo	W Eq	uip. Code	26. Was Atte	Equipment Code 27. Train Number/Synded?					nber/Symbol								
Consist (single of	r	1 1.					es 2. No 1 HNTW												
28. Speed (recorded speed, if available)     Code     30. Method(s) of Operation     (enter code(s) that apply)     30a. Remotely Controlled L       4. The second speed is a speed of the second speed is												led Loco	motive?						
E - Estimated	1. Curren	it of ti	raffic		1 = Remote control portable														
29. Trailing Tons (gross toppage d Cob									rain orders	s o. Po	ositive train	control		2 = Remote control tower 3 = Remote control					
excluding power	e. Traffic	j k	. Direct	traffi	fic control Code(s)				transmitter - more than one										
		820	5	f	f. Interlocking	; 1	.Yard lin	nits		f	N/A N/	A N/A	N/A	remote o	control	transm	nitter	0	
31. Principal Car/Unit	t	a. Initial	and N	umber	b. Positio	on in Train	n c. l	Loade	ed(yes/no)	32.	If railroad e	employee(	s) teste	d for drug	/alcoho	l use,			
(1) First involved (derailed, struck, etc) N/A					1				N/A		the approp	riate box.	it were	positive i			Alcohol N/A	Drugs N/A	
(2) Causing (if mechanical 0					0				N/A 33. Was this consist					ng passen	gers? (Y	//N)		l N	
cause reported) 34. Locomotive Units a. Head					Train	Re	ear End		35 Car	-e			Lo	ade		Empt	у		
		End	b. M	anual	c. Remote	d. Manua	l c. Rei	mote	55. Cai			a. F	reight	b. Pass.	c. Frei	ght d	. Pass.	e. Caboose	
(1) Total in Train	1	2		0	0	0	0		(1) Total	l in Eq	uipment Co	nsist	53	0	63		0	0	
(2) Total Deraile	d	0		0	0	0	0		(2) Total	l Derai	iled		0	0	0		0	0	
36. Equipment Damage				37. Tr	ack, Signal, V	Vay,	0.0		38. Primary Cause				39. Contributing Cause Code . NI/A						
This Consist	mage	0.0	Length of Time on Duty								IN/A								
40. Engineer/	41. Firemen 4			42. Conductors 43. Brak			akemen	44. Engineer/Operator				45. Conductor							
Operators N/A		0			1				Hrs 8			Mi 15			Н	rs	8	Mi 15	
Casualties to:	46. Rail	road Emplo	oyees	47. Tra	ain Passenger		49. EOT	Devic	ce?		50. Was EOT Device Properly Armed?								
Fatal		0			0		0		1. Yes 2. No					1.	Yes	2	. No	1	
Nonfatal		N/A			0		0		1. Yes			22 Ciew?	2. No					N/A	
						0	PERAT	ΓINC	G TRAIN	N #2								1	
52. Type of Equipment 1. Freight train 4. Work train 7. Yard/switching A. Spec. MoW Equip. Code 53. Was Equipment Code 54. Train Number/Symbol																			
Consist (single entry) 2. Passenger train 3. Commuter train					ngle car 8.	r	Atten					2. No N/A N/A			A				
55. Speed (recorded	speed, if	available)	Cod	le   57	. Method(s)	of Operati	on (	enter	r code(s)	that a	apply)	1.	103	57a. Rem	otely C	ontrol	led Loco	motive?	
R - Recorded	. ATCS	g	g. Autom	atic b	block m.Special instructions					0 = Not a remotely controlled									
E - Estimated	U	MPH	IN/A	ł	o. Auto train o	control h	n. Curren	t of ti	raffic	n. Ot	noi ulali illa	in u ack		1 = Rem	ote cont	rol po	rtable		

DEPARTMENT FEDERAL RAILF	OF TRAI	NSPOR' DMINIS'	ΓΑΤΙ ΓRAT	ON ION	FRA FA	ACTUAI	LRAILR	.OAD AC	CII	DENT I	REPO	ORT	F	RA File #	<u>HQ-200</u>	<u>5-42</u>		
56. Trailing Tons (gross tonnage, excluding power units)					Auto train Cab Traffic	ain orders o. Positive train control t control p. Other (Specify in narrative) c control Code(s)					2 = Remo 3 = Remo transmit							
0				f.	Interlocking	g 1.Y	ard limits		N/A	A N/A 1	N/A	N/A N/A	remote c	N/A				
58. Principal Car/Unit a. Initial and Nu				Jumber	b. Positi	on in Train	c. Load	led(yes/no)	59.	If railroad	emplo	oyee(s) teste	/alcohol us					
(1) First involved 0 (derailed, struck etc)						0		N/A	/A enter the number that were the appropriate box.					Alcohol				
(2) Causing (if mechanical								NT / A	60 Was this consist transporting passengers? (V/N)							10/1		
cause reported)						0		N/A										
61. Locomotive Units		a. Head End b. Mar			Mid Train anual c. Remote		r End c. Remote	62. Cars				Lo a. Freight	ade b. Pass.	Em c. Freight	pty d. Pass.	e. Caboose		
(1) Total in Train 0		0	0	0	0	(1) Total in	in Equipment Consist			0	0	0	0	0				
(2) Total Deraile	:d 0		0 0		0	0	(2) Total Derailed				0	0	0	0	0			
63. Equipment Damage 6 This Consist 0					ack, Signal, Structure Da	Way, image	0	65. Primar Code	i5. Primary Cause 66. Contributing Cause Code N/A Code				use	N/A				
		Numbe	er of C	rew Me	mbers				Length of Time on Duty									
67. Engineer/ Operators N/	ngineer/ 68. Firemen 0 Operators N/ N/A				nductors N/A	70. Bra	kemen N/A	71. Engineer/Operator Hrs 0 Mi					72. Con	Mi 0				
A Casualties to:	73. Railro	oad Empl	oyees	74. Tra	in Passenge	rs 75. Oth	er	76. EOT Device?					77. Was	Armed?				
Fatal		0			0		0	1. Y	'es	2. No	<u> </u>	N/A	1.	Yes	2. No	N/A		
Nonfatal		0			0		0	78. Caboo	ose O 1.	ccupied by Yes	y Crew	r? 2. No	2. No					
						Rail I	Equipment	Involved	1									
79. Type								Code 83. Equipment										
A. Auto D. Pick-Up B. Truck E. Van	narrative)	1.Train(units pulling)   4.Car(s) (moving)     2.Train(units pushing)   5.Car(s) (standing)     8.Other (specify in narrative)									1							
80. Vehicle Speed	ical)	Code	Code 84. Position of Car Unit in Train															
(est. MPH at in	4.West	Code	Code 85. Circumstance								Code							
1.Stalled on Cros	Crossing	1. Rail Equipment Struck Highway User																
4. Trapped 86a. Was the highway user and/or rail equipment involved							Code	2. Rail Ec	luipn here	a hazardo	k by H	erials releas	e by			I		
in the impact tr		Code									Code							
1. Highway User	2. Rail E	quipmen	t 3.	Both	4. Neither	1 1:0	2	1. High	way	User 2.	Rail E	quipment	3. Both	4. Neithei	r	4		
soc. State here the nat	me and qu	antity of	the ha	zardous	materials re	eleased, 11 a	ny. N/A											
87. Type of 1.Gat Crossing 2.Cat	bucks 10. signs 11.	.Flagged by .Other (spec	crew . in narr.)	88. S	Signaled C See instru	Crossin ctions	g Warning for codes)	Code	89. Whis 1. Ye	tle Ban s	Code							
Warning 3.Standard FLS 6.Audible					9.Watel	hman 12.	.None						1	2. No 3. Un	known			
Code(s) 01		02	03	5	06	N/A	N/A	Interconnected Code 92 Crossing Illuminated by Stract							2			
90. Location of Warn 1. Both Sides	with I	ig warning Highway Sig	gnals	ea	Code	Lights or Special Lights					Code							
2. Side of Vehicl	1. 2	Yes No		I			1. Yes 2. No											
5. Opposite side of Venicle Approach					1	3.		2		3. Unkn	own	1						
93. Driver's 94. Driver's Gender Code Age 1. Male					iver Drove I d Struck or	Behind or ir was Struck	n Front of Tr by Second 7	ain Code Frain		96. Driver 1. Drove	e arour	id or thru th	e Gate 🛛	4. Stopped	on Crossin	Code g		
51 2. Female 2				1.	Yes 2	2	2. Stopped and then Proceeded   5. Other (specify in narrative)     2   3. Did not Stop											
97. Driver Passed Standing Code 98. View of Track Obscured by							(primary ob	struction)			-	0.1				Code		
1. Yes 2. No 3. Unknown   2   2. Standing Railroad Equipment   4. Topography   6. Highway Vehicle   8												. Otner (s . Not obstru	pecity in n cted	arrative)		8		
101. Casulties to Highway-Rail Crossing Users Killed Injured 99. Dri						99. Driver	Was Code 100. Was Driver in the V						e Vehicle?		Code			
						1. Killed 102. Highv	2.Injured 3. way Vehicle	Uninjured Property Da	mage	3		1. Ye 103. Total I	es Number of	2. No Highwav-	Rail Cross	I ing Users		
	6	(est. d	dollar damage) 1500 (include driver) 48								48	J						
104. Locomotive Aux	iliary Ligl	hts?	0			1	Code	105. Locor	notiv V-	e Auxilia	ry Ligł	nts Operatio	nal?			Code		
106. Locomotive Hea		Code	1. 107. Locor	1 es notiv	e Audible	Warn	2. INO	d?			Code							
1. Yes 2. No							1	1.	1. Yes 2. No							1		



108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED. HQ-42-2005

## 109. SYNOPSIS OF THE ACCIDENT

On May 12, 2005, at approximately 1:15 p.m. CDT, westbound BNSF freight Train Symbol HNTWMEM1-11A collided with a school bus at a highway-rail grade crossing. The accident occurred in Hannibal, Missouri, at BNSF Milepost (MP) 119.83, on the BNSF Hannibal Subdivision.

The school bus driver and 47 passengers survived the impact with minor injuries sustained by 6 of the students. The school bus was struck in the driver's side rear corner and sustained minor damage of approximately \$1,500. There were no injuries to the train crew. The leading locomotive sustained minor damage of about \$200, and there was no derailment.

At the time of the accident it was daylight, overcast, and the temperature was 67 °F.

The accident was caused by failure of the school bus driver to completely clear the crossing ahead of the train's arrival. According to the Missouri State Highway Patrol, the driver was in violation of the Missouri highway traffic laws for "driving through the crossing without sufficient space".

## 110. NARRATIVE

The following information was obtained from an investigation that was conducted by the Federal Railroad Administration.

Circumstances Prior to the Accident

The crew of freight Train Symbol HNTWMEM1-11A included a locomotive engineer, conductor, and brakeman. They first went on duty at 5 a.m., CDT, May 12, 2005, at the BNSF depot at West Quincy, Missouri. This was the home terminal for all crew members, and all had received 14 hours and 30 minutes off duty time prior to reporting for duty. This is more than the required statutory off-duty period.

Their assigned freight train was scheduled to travel to Memphis, Tennessee, with cars to be added and removed at West Quincy. The train had received an initial terminal train air brake test and departed Northtown, Minnesota, at 12:09 p.m. CDT, on May 11, 2005. Northtown is located near Minneapolis, Minnesota.

The train was being operated by a crew working their regular local road switching job. Their assignment was to set out and pick up a block of cars at West Quincy, MP136, and proceed to the Ashburn Siding, MP 104.3. After switching was completed, their assigned freight train consisted of 2 locomotives, 53 loads, and 63 empty cars of several varieties. It was 7,142 feet long and weighed 8,205 tons.

As the westbound train approached the accident site, the locomotive engineer was seated at the controls on the right side of the leading locomotive. The conductor was seated on the left side of the lead locomotive, and the brakeman was seated in the center.

In this area of the railroad there are, in succession, a 2-degree curve to the right followed by a tangent of about 1,500 feet, a 2-degree 30-minute curve to the left followed by a tangent of about 350 feet leading up to the point of the accident. There is a descending grade of .48 percent between MP 120.5 and MP 119.83. In the area of highway-rail grade crossing DOT No. 063902D, Center Street, the road is tangent and the grade is practically level.

The railroad timetable direction of the train was west. The geographic direction was south. Timetable directions are used throughout this report when referencing the train, however, geographic direction is applied to the school bus, which was eastbound.

#### The Accident

### Train Symbol HNTWMEM1-11A

The train was being operated at 25 mph approaching the accident area. The train crew's view of the crossing was unobstructed. Nearing the accident site, the conductor jumped from his seat and yelled for the engineer to make an emergency application of the train brakes because they were going to hit a bus. The engineer simultaneously initiated an emergency train air brake application. The train had slowed to 21 mph when the collision occurred. Both speeds were recorded by the event recorder of the controlling locomotive. The maximum authorized speed for this train was 25 mph, as designated in the current BNSF Timetable No. 5.

#### **Highway Vehicle**

The school bus, which originated at Wentzville, Missouri, with 47 passengers, was traveling eastbound on Center Street, arriving at the Mississippi riverfront tourist parking lot at Hannibal, Missouri. A rubber-tired tour trolley operated around it and stopped short of providing the bus enough room to clear the tracks. The bus driver then attempted to enter the parking lot by driving left of the trolley and between the crossing warning devices and a stone pillar located in the northeast

# FRA FACTUAL RAILROAD ACCIDENT REPORT

quadrant of the highway-rail grade crossing. The bus driver was unable to turn sharply enough to operate between the two and stopped, fouling the BNSF tracks.

When the approaching train caused the crossing lights, gates, and bell to activate, the school bus driver was unable to clear the tracks. The train impacted the driver's side rear corner of the bus, shoving it clear of the tracks. The train continued approximately 640 feet and stopped about 4 car lengths beyond the next highway-rail grade crossing at Broadway Street.

After the train stopped, the locomotive engineer stayed on the locomotive to establish communications with the train dispatcher. The conductor walked back to Center Street and cut the train to allow emergency personnel across the highway-rail grade crossing.

A Missouri Highway Patrolman arrived on the scene at 1:26 p.m. Emergency responders arrived at approximately the same time. After they coordinated the emergency response, the school bus passengers were examined for injuries. The highway patrolman then interviewed the train crew. There were no injuries to railroad personnel.

A BNSF roadforeman of engines was dispatched to the scene from West Quincy at 1:24 p.m. and arrived at approximately 2 p.m. He ascertained the condition of the train and track structure. There was no hazardous materials involvement and only minor damage to the lead locomotive. The local BNSF trainmaster responded to the site from Ft. Madison, Iowa and arrived at 3 p.m. He interviewed the crew, discussed the situation with the highway patrolman, and compiled the railroad accident report. The train crew was then released at 4:50 p.m., due to emotional trauma.

All the children were taken to Hannibal Regional Hospital for evaluation with six of the children treated for minor injuries. One child was held overnight for observation after having fainted due to an apparent anxiety attack.

# Analysis

The school bus driver was a 51-year-old female, fully trained and qualified, with a total of 4 months experience driving a bus. The other school bus occupants consisted of 14 adults and 33 children.

The highway-rail grade crossing is equipped with warning lights, gates, and a bell. There are no advanced warning signs, and no pavement markings at this crossing.

The railroad has a whistle post in place about 1,600 feet east of the crossing. All three train crew members said the locomotive engineer began sounding the whistle when the train neared this post. This was later validated by analysis of the event recorder data.

The active warning device control bungalow was locked upon arrival of the BNSF signal maintainer and the keys were given to the local police. At approximately 4 p.m. the BNSF manager of signals arrived. He and other BNSF signal personnel tested the crossing and found it to be functioning as intended. A Missouri Department Of Transportation signal and train control inspector was present at the time of testing and confirmed the crossing was working as intended.

The lead locomotive was equipped with headlights, auxiliary lights, and the audible warning device as required by Federal regulations. These devices were tested in the presence of the trainmaster and functioned as intended. The devices were in full compliance with Federal requirements.

The locomotive was equipped with a speed indicator and an event recorder. The relevant event recorder data was downloaded by the roadforeman of engines at the accident site and analyzed. The analysis disclosed that the locomotive engineer was in compliance with all applicable railroad operating and train handling requirements. FRA reviewed the results of this analysis and concurred with these conclusions.

## Conclusions

The railroad was in full compliance with their own and all applicable Federal standards. The school bus driver admitted to mis-judging the left turn and placing the bus in a position that was difficult to maneuver. The school bus driver had only been operating a bus for 4 months. Based on the facts of this investigation, the driver improperly stopped on the highway/rail grade crossing. A contributing factor was the driver's inattention, by driving through the crossing without sufficient space to clear the crossing.

Probable Cause & Contributing Factors

The FRA determined that the primary cause to be M304 - Highway user cited for violations of highway grade crossing traffic laws.