

Federal Railroad Administration Office of Safety Headquarters Assigned Accident Investigation Report HQ-2005-44

> Union Pacific (UP) Owyhee, Idaho May 20, 2005

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

DEPARTMENT OF TRANSPORTATION FRA FACTUAL RAILROAD ACCIDENT REPORT FRA File # HQ-2005-44 FEDERAL RAILROAD ADMINISTRATION FRA FACTUAL RAILROAD ACCIDENT REPORT FRA File # HQ-2005-44															
1.Name of Railroad Opera	ting Train #1				1a. Alphabeti	1b. 1	Railroad Accident/Incident No.								
Union Pacific RR Co. [U 2.Name of Railroad Operat	JP] ting Train #2				2a. Alphabeti	c Code		2b. R	0505PC003 Railroad Accident/Incident						
N/A		- M			2- 41-1-1-1-1	N/A		21- 1	D - 11 1 - A	N/A	T				
3.Name of Railroad Respon	nsible for Trac	k Mainte	nance:		3a. Alphabeti	c Code		3b. 1	Railroad A	osospec	Incident No.				
4. U.S. DOT_AAR Grade	Crossing Ident	ification	Number		5. Date of Ac	cident/Incident		6. T	ime of Ac	cident/Ir	ncident				
	Month 05	Day	Year	5											
7. Type of Accident/Indice	ent 1. Deraili	ollision		7. Hwy-rail	crossing 10	0. Explos	ion-deton	12.45. V Ministry The Indetonation 13. Other							
(single entry in code bo	x) 2. Head o	n collisio	on 5. Raking	g collision	I 	8. RR grade	crossing 1	1. Fire/vi	olent rupt	ure	(descri narrati	ibe in ive)	I		
Com Coming	3. Rear er	nd collisi	on 6. Broker	n Train co	Delessin	9. Obstructio	on li	12. Other impacts					01		
HAZMAT 2	9. HAZMA Damaged/I	maged/Derailed 0			T.	0	Evacuated	Evacuated			12. Divi	sion Pocatello S	ervice		
13. Nearest City/Town				14. Mile (to r	epost nearest te	enth)	15. State Abb	5. State Abbr Code							
	na				432.5	N/A	Ц П				ADA				
(specify if minus)	Temperature (F)18. Visibility(single end(specify if minus)1. Dawn3. Dusk			Code	19. W	Veather (sing) . Clear 3. R	er (single entry) ar 3. Rain 5.Sleet			20. Type of Track			Code		
52 F 2. Day			4.Dark	4	2	. Cloudy 4. F	og 6.Snow		2	2. Ya	řard 4. Industry		1		
21. Track Name/Number	n Track	22. FRA Clas	Track s (1-9, X	Code () 5	23. Annual Tr (gross tor millions)	ack Dens 1s in	sity 52.47	24. Tim	me Table Direction Code 1. North 3. East 4						
					OPER	ATING TRA	AIN #1								
25. Type of Equipment	1. Freight tra	un 4	. Work train 7.	Yard/swi	itching	A. Spec. Mo	W Equip. Cod	le 26. V	Vas Equip	oment (Code 2	27. Train Nu	imber/Symbol		
Consist (single entry)	 Passenger Commute 	train 5 r train 6	. Single car 8. . Cut of cars 9.	o(s).	r	1	A	ttended?	nded? . Yes 2. No 1 IG3SE-						
28. Speed (recorded speed, if available) Code 30. Method(s) of Operation (enter code(s) that apply) 30a. Remotely												ntrolled Loc	5 comotive?		
R - Recorded	MDH	D	 a. ATCS b. Auto train of 	. Autom . Curren	atic block t of traffic	k	0 = Not a 4 control portable								
E - Estimated 05	МРП	к 	c. Auto trair	. Time ta	ble/train orders	l	2 = Remote control tower								
29. Iraning Ions (gross excluding power unit	s tonnage, ts)	Track w	traffic control	p. Other (Spe Cod	cify in na le(s)	rrative)	ative) 3 = Remote control transmitter - more than one								
	4057	Yard lin	nits	e N/A	N/A N/	A N/A	remote control transmitter N/A								
31. Principal Car/Unit	a. Initial a	and Num	ber b. Positio	on in Trair	1 c. l	Loaded(yes/no)	32. If railroa	d employ	ee(s) teste	ed for drug	/alcohol	use,	_		
(1) First involved (derailed_struck_etc)		N/A	3	37		yes	enter the	ter the number that were appropriate box.			n	Alcoho	Drugs		
(2) Causing (if mechani	ical	0		0		N/A	33. Was thi	is consist	transporti	ing passen	gers? (Y	/N)			
cause reported)		0		Re	or End	IN/A		I I C				Empty	N		
34. Locomotive Units	. Locomotive Units a. Head End b. M		lid Train al c. Remote	d. Manua	1 c. Rei	35. Car	s	ı	a. Freight	b. Pass.	c. Freig	ght d. Pass.	e. Caboose		
(1) Total in Train	3	0	0	0	0	(1) Total	in Equipment (Consist	100	0	0	0	0		
(2) Total Derailed	0	0	0	0	0	(2) Total	Derailed		41	0	0	0	0		
36. Equipment Damage	901664	37.	. Track, Signal, V	Way,	22154	38. Prim	ary Cause	Į		39. Cont	ributing	Cause			
This Consist	821004		& Structure Da	23154	-8 Code	Code T215 Code N/A									
40. Engineer/ 41.	2. Conductors	43. Bra	akemen	44. Engi	Lengui oi	45. Conductor									
Operators N/A 0			1 0				Hrs 6	45		Hr	s 6	Mi 45			
Casualties to: 46. F	Railroad Emplo	yees 47.	Train Passenger	s 48. C	Other	49. EOT		50. Was EOT Device Properly Armed?							
Fatal	0		0		0	1. Yes 2. No 1				1.	Yes	2. No	1		
Nonfatal	N/A		0	0	91. Cab	2. No				N/A					
OPERATING TRAIN #2															
52. Type of Equipment 1. Freight train 4. Work train 7. Yard/switching A. Spec. MoW Equip. Code 53. Was Equipment Code 54. Train Number/Symbol															
Consist (single entry)	 Passenger Commuter 	train 5.	Cut of cars 9.	Light loce	u(s). spect.cai	r	N/A		uended?	2. No N	J/A	N	/A		
55. Speed (recorded speed	l, if available)	Code	57. Method(s)	of Operati	on (enter code(s)		57a. Remotely Controlled Locomotive?							
R - Recorded a. ATCS g. Auto						atic block	k	0 = Not a remotely controlled							
E - Estimated 0	MPH	IN/A	b. Auto train o	control h	. Curren	t of traffic	n. Outer thall I	nam traci	n.	I = Rem	ote contr	oi portable			

DEPARTMENT FEDERAL RAI	Γ OF TRA LROAD A	ANSPOR Adminis	TATI	ION FION	FRA FA	ACTUA	L RAILR	OAD AC	CIE	DENT I	REPO	ORT	F	RA File #	<u>HQ-200</u>	5-44	
56. Trailing Tons (gross tonnage, excluding power units)				C d e	. Auto train . Cab . Traffic	n stop i. j.] k.	Time table/t Frack warran Direct traffi	rain orders of the control of the co	p. Posi p. Oth	itive train er (Spec Code	i contro ify in n (s)	ol arrative)	2 = Remo 3 = Remo transmit remote c	N/A			
58. Principal Car/Unit a. Initial and Nu				I. Number	h. Posit	g I.1		led(ves/no)	1N/A	f railroad		VA IVA	d for drug				
(1) First involved			united	0.1030	0		(yCS/110)	- 59.1	enter the	numb	er that were	positive i	Drugs				
(derailed, struck, etc)						•		N/A		the appro	opriate	box.		N/A			
(2) Causing (if mechanical cause reported) 0					0		60. Was this consist transporting passengers? (Y/N)							N/A			
61. Locomotive Un	its	a. Head End	b. N	Mid Ianual	Train c. Remote	Rea d. Manual	ar End	62. Cars L a. Freight			Lo a. Freight	ade b. Pass.	Err c. Freight	npty d. Pass.	e. Caboose		
(1) Total in Tr	(1) Total in Train 0			0	0	0	0	(1) Total in Equipment Consist $0 \qquad 0 \qquad 0$					0	0			
(2) Total Dera	iled	0		0	0	0	0	(2) Total D	Deraile	railed 0			0	0	0	0	
63. Equipment Damage 6 This Consist 0					ack, Signal, Structure Da	Way, amage	0	65. Primar Code	65. Primary Cause Code N/A Code						luse	N/A	
	1 10 101	Numb	per of C	Crew Mo	embers	1 = 0 = 0		Length of Time on Duty									
67. Engineer/ Operators 0	68. Fi	0 69			9. Conductors 7 0		0	71. Engineer/Operator 72. Conductor Hrs 0 Hrs 0						0	Mi 0		
Casualties to:	73. Rail	road Emp	loyees	74. Tra	4. Train Passengers 7		ier	76. EOT Device? 77. Was EOT Device Pr						e Properly	Armed?		
Fatal		0			0		0	1. Y	1. Yes 2. No N/A 1. Yes 2. No								
Nonfatal		0	0 0					/8. Caboo	78. Caboose Occupied by Crew?								
		High	way U	ser Inv	olved						Rail I	Equipment	Involved	1		1	
79. Type C. Truch	icle	Code	Code 83. Equipment 3.Train (standing) 6.Light Loco(s) (moving)														
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)							N/A 2.Train(units publing) 4.Car(s) (moving) 7.Light(s) (standing) a.Train(units pushing) 5.Car(s) (standing) 8.Other (specify in narrative)								N/A		
80. Vehicle Speed 81. Direction geographical)								N/A 84. Position of Car Unit in Train									
(est. MPH at impact) ~ 1.North 2.South 3.East 4.Wes							Code	85. Circun	85. Circumstance								
1.Stalled on Crossing 2.Stopped on Crossing 3.Moving Over Crossi							N/A	1. Rail Ed	quipm	ent Struc	k High	way User					
4. Trapped 86a. Was the highway user and/or rail equipment involved							Cada	2. Rail Ed	86b. Was there a hazardous materials release by								
in the impact transporting hazardous materials?							Code		1 Highway Hear 2 Dail Ferrimment 2 Dath 4 Meiter								
1. Highway Use	r 2. Rail	Equipme	nt 3.	Both	4. Neither	1 1 1	N/A	1. High	iway t	Jser 2.	Rail E	quipment	3. Both	4. Neithe	r	N/A	
soc. State here the	name and q	luantity of	the ha	izardous	materials re	eleased, 11 a	ny. N/A										
87. Type of Crossing 1.Gates 4.Wig Wags 7.Crossbucks 2.Cantilever FLS 5.Hwy. traffic signals 8.Stop signs							.Flagged by .Other (spec	crew . in narr.)	88. S (S	ignaled C ee instru	Crossin ctions	g Warning for codes)	Code	89. Whis 1. Ye	tle Ban s	Code	
warning 3.Standard FLS 6.Audible					9.Wate	hman 12	.None	27/1						2. No 3. Un) Iknown	NI/A	
Code(s) N	N/A	N/A	N/	A	N/A Coda	N/A 91 Crossi	N/A	N/A Interconnect	ed	Code	92 (Trossing Illi	 uminated b	v Street		N/A	
1. Both Sides 2. Side of Vehicle Approach							Highway Sig Yes	gnals	cu	Code	Lights or Special Lights 1. Yes						
3. Opposite Side of Vehicle Approach					N/A	2.	. No Unknown	N/A 2. No					own	N/A			
93. Driver's 94. Driver's Gender Code 9					iver Drove	ain Code 96. Driver							Code				
Age 1. Male 0 2. Female N/A					and Struck or was Struck by Second T1. Yes2. No3. Unknown				rain 1. Drove around or thru the Gate 4. Stopped on Crossing 2. Stopped and then Proceeded 5. Other (specify in narrative)							Ig	
97. Driver Passed Standing Code 98. View of Track Obscured b						cured by	(primary obstruction)								Code		
Highway Vehic	cle			1. Per	manent Stru	cture	3. Passing Train 5. Vegetation 7. Other (specify in narrative)									N/A	
1. 105 2. 100 5. Ohnown 2. Standing Kanfold Equit 101. Casulties to Highway-Rail 99. Dri							r Was Code 100. Was Driver in the Vehicle?							Code			
Crossing Users Killed				ed	Injured	Uninjured N/A 1. Yes 2. No							N/A				
0 0 102.						102. High (est. c	tway Vehicle Property Damage 103. Total Number of Highway-Rail dollar damage) 0 (include driver)						Rail Cross 0	ing Users			
104. Locomotive A	uxiliary Li	ghts?		1		(Code	105. Locor	motive	e Auxilia	ry Ligł	nts Operatio	nal?			Code	
1. Yes 2. No							N/A	1. Yes 2. No						N/A			
1 Ves 2 No						I	Code N/A	107. Locomotive Audible Warning Sounded?						Code N/A			
1. 105		1.	1. ICS 2. NO							11/A							



108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED. HQ-44 Sketch.jpg

109. SYNOPSIS OF THE ACCIDENT

On May 20, 2005, at 12:45 a.m. (MDT), a westbound Union Pacific Railroad Company (UP) intermodal freight train Symbol, IG3SE-15, derailed. The accident occurred on the UP's Pocatello Service Area, Nampa Subdivision, on a single main track at milepost 432.5, located about 13 miles east of Kuna, Idaho. A total of 41 loaded articulated container platforms derailed.

There was no release of hazardous material and no injuries to the train crew employees.

The total estimated damage was \$1,053,192 (\$ 821,664 for equipment, \$186,770 for track, and \$44,778 for signal).

At the time of the accident it was dark, the weather was cloudy, with a temperature of 52° F.

The probable cause of this accident was a pair of corresponding broken joint bars; which broke due to transverse defects.

110. NARRATIVE

The following information was obtained from an investigation that was conducted by the Federal Railroad Administration.

Circumstances Prior to the Accident

The crew of train IG3SE-15 consisted of a locomotive engineer and conductor. Following a statutory off duty period, they reported for duty at their designated home terminal, Pocatello, Idaho, on May 19, 2005, at 6 p.m. (MDT), to operate the train, west, to Nampa, Idaho, a distance of 242.6 miles.

The train, designated as an extended haul train, consisted of 3 locomotives, 100 loaded articulated container platforms, 0 empties, weighed 4,057 trailing tons, and was 6,688 feet in length. The train consist was equipped with an armed 2-way end of train device, and received a Class I air brake test on May 18, 2005, at 9:20 a.m., in North Platte, Nebraska.

The crew boarded the train and departed Pocatello on May 19, 2005, at 7 p.m., and proceeded west without incident.

As the train approached the accident site, the locomotive engineer was seated in the cab at the controls located on the right (north) side of the leading locomotive. The conductor was seated opposite the engineer on the left (south) side of the cab in the front seat.

Approaching the accident site from the east to west, the track is tangent nine tenths of a mile in length from milepost 431.6 to the point of the accident and two miles beyond. The track grade in the accident area is 0.50 percent descending.

In the accident area, trains operate on a single main track under the authority of a Traffic Control System. The Union Pacific Railroad, Portland Area, Timetable No. 2, effective 0001 Sunday, October 29, 2000, authorizes a maximum train speed of 70 mph for freight trains. The timetable and geographic direction the train was traveling, was west.

The Accident

According to the engineer and conductor, the trip was uneventful as the train approached the accident area. They felt a tug on the train, then a short surge forward. A train line induced emergency brake application (TIE) occurred and the train slowed to a stop. While approaching, and at the time the accident occurred, the train was being operated at a speed of 63 mph as indicated by the printout of the event recorder from the lead locomotive UP3863.

They became aware of the derailment after the train stopped and the conductor walked toward the rear of the train to investigate. The conductor contacted the engineer and advised him that platforms were derailed and piled up on each side of the right of way. After receiving the report from the conductor, the engineer notified the dispatcher that their train was derailed.

No emergency response personnel were called to the accident and there were no injuries or casualties.

A total of 41 platforms, positioned 37th through 77th behind the locomotive consist, were derailed to the north and south of the track structure at various angles to the roadbed. The derailed platforms were loaded with 79 empty intermodal containers.

As result of the derailment, 2,100 feet of track and the signal located at milepost 432.8 was damaged.

FRA FACTUAL RAILROAD ACCIDENT REPORT

The piont of derailment (POD) occurred at milepost 432.5 on single main track.

Analysis

This accident met Title 49 CFR, Part 219, Subpart C, Post Accident Toxicological Testing criteria. The UP tested both the engineer and conductor under the FRA post accident toxicological testing requirements. The results of the tests were negative.

An inspection of the data printout from the leading locomotive event recorder indicated no unusual events which could contribute to the cause of the accident. According to the print out, at 12:45 a.m., a train line induced emergency brake application occurred.

Four days prior to the accident, on May 16, 2005, a UP track inspector inspected the track in the area of the accident and noted no defective conditions. This was the last documented FRA required inspection performed prior to the accident.

An equipment inspection was made, and no condition was found that could have contributed to the cause of the accident. Lateral marks and indentations across the tread of the wheels were observed on the right number three wheel of the leading locomotive and on 19 other wheels on several of the trailing platforms and located on wheels to the north side of the train. The marks are indicative of striking the end of a rail head.

Post accident examination of the track structure disclosed a pair of corresponding broken joint bars installed on the north rail at milepost 432.5. Each joint bar had a transverse defect, about 3/4 of an inch in diameter, located near the middle, and progressing from the bottom outside edge toward the top and center of each bar. Each bar appeared to have experienced a catastrophic failure as result of weakening from the transverse defect. The receiving rail for westbound traffic at the joint bar connection showed signs of battering.

An independent investigator was contracted by UP to determine the cause. The investigator concluded that the cause of the accident was due to broken joint bars.

Conclusion

Lateral marks and indentations were found across the tread of the wheels on the right number three wheel of the leading locomotive and on 19 other wheels on the north side of the train. The receiving rail for westbound traffic at the joint bar connection at the POD showed signs of battering. Broken joint bars at that location each had a transverse defect and appeared to have experienced a catastrophic failure as result of weakening from the defect. An independent investigator determined the cause to be broken rail joint bars.

Probable Cause

The FRA determined that the probable cause of this accident was a pair of corresponding broken joint bars; which broke due to transverse defects.