



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2005-46***

***CSX Transportation (CSX)
Cumberland, Maryland
May 30, 2005***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2005-46</u>		
1. Name of Railroad Operating Train #1 CSX Transportation [CSX]			1a. Alphabetic Code CSX		1b. Railroad Accident/Incident No. 000012692			
2. Name of Railroad Operating Train #2 CSX Transportation [CSX]			2a. Alphabetic Code CSX		2b. Railroad Accident/Incident 000012692			
3. Name of Railroad Responsible for Track Maintenance: CSX Transportation [CSX]			3a. Alphabetic Code CSX		3b. Railroad Accident/Incident No. 000012692			
4. U.S. DOT_AAR Grade Crossing Identification Number			5. Date of Accident/Incident Month Day Year 05 30 2005		6. Time of Accident/Incident 01:30:00 <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM			
7. Type of Accident/Incident (single entry in code box)								
1. Derailment		4. Side collision		7. Hwy-rail crossing		10. Explosion-detonation		
2. Head on collision		5. Raking collision		8. RR grade crossing		11. Fire/violent rupture		
3. Rear end collision		6. Broken Train collision		9. Obstruction		12. Other impacts		
						13. Other (describe in narrative) 04		
8. Cars Carrying HAZMAT 0		9. HAZMAT Cars Damaged/Derailed 0		10. Cars Releasing HAZMAT 0		11. People Evacuated 0		
						12. Division BALTIMORE		
13. Nearest City/Town CUMBERLAND			14. Milepost (to nearest tenth) 175.9		15. State Abbr Code N/A MD		16. County ALLEGANY	
17. Temperature (F) (specify if minus) 65 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 2		
21. Track Name/Number CLASS 2 TRACK (W02)			22. FRA Track Code Class (1-9, X) 1		23. Annual Track Density (gross tons in millions) 0.0		24. Time Table Direction Code 1. North 3. East 3	
OPERATING TRAIN #1								
25. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching		A. Spec. MoW Equip. Code 7		26. Was Equipment Attended? Code 1. Yes 2. No 1		
2. Passenger train 5. Single car 8. Light loco(s).		3. Commuter train 6. Cut of cars 9. Maint./inspect.car				27. Train Number/Symbol Y191-30		
28. Speed (recorded speed, if available) Code R - Recorded 6 MPH R E - Estimated		30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits				30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 3		
29. Trailing Tons (gross tonnage, excluding power units) 6418								
31. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded (yes/no)		
(1) First involved (derailed, struck, etc)		N/A		94		yes		
(2) Causing (if mechanical cause reported)		0		0		N/A		
						32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.		
						Alcohol 0 Drugs 0		
						33. Was this consist transporting passengers? (Y/N) N/A		
34. Locomotive Units		a. Head End		Mid Train		Rear End		
		b. Manual		c. Remote		d. Manual c. Remote		
(1) Total in Train 2		0		0		0		
(2) Total Derailed 0		0		0		0		
35. Cars		a. Freight		b. Pass.		c. Freight d. Pass. e. Caboose		
(1) Total in Equipment Consist 43		0		51		0 0		
(2) Total Derailed 8		0		3		0 0		
36. Equipment Damage This Consist 251410		37. Track, Signal, Way, & Structure Damage 55000		38. Primary Cause Code S102		39. Contributing Cause Code N/A		
Number of Crew Members				Length of Time on Duty				
40. Engineer/Operators N/A		41. Firemen 0		42. Conductors 1		43. Brakemen 0		
44. Engineer/Operator Hrs 1 Mi 41		45. Conductor Hrs 5 Mi 41						
Casualties to:		46. Railroad Employees		47. Train Passengers		48. Other		
Fatal 0		0		0				
Nonfatal N/A		0		0				
						49. EOT Device? 1. Yes 2. No 2		
						50. Was EOT Device Properly Armed? 1. Yes 2. No N/A		
						51. Caboose Occupied by Crew? 1. Yes 2. No N/A		
OPERATING TRAIN #2								
52. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching		A. Spec. MoW Equip. Code N/A		53. Was Equipment Attended? Code 1. Yes 2. No N/A		
2. Passenger train 5. Single car 8. Light loco(s).		3. Commuter train 6. Cut of cars 9. Maint./inspect.car				54. Train Number/Symbol N/A		
55. Speed (recorded speed, if available) Code R - Recorded 0 MPH N/A E - Estimated		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track				57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable		

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2005-46</u>	
56. Trailing Tons (gross tonnage, excluding power units) <div style="text-align: right;">0</div>		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s) <div style="display: flex; justify-content: space-around; font-size: small;"> <div>N/A</div> <div>N/A</div> <div>N/A</div> <div>N/A</div> <div>N/A</div> </div>	
						2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter <div style="text-align: right;">N/A</div>	
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)	
(1) First involved (derailed, struck, etc)		CSXT2 52122		1		N/A	
(2) Causing (if mechanical cause reported)		0		0		N/A	
						59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	
						<div style="display: flex; justify-content: space-around; font-size: small;"> <div>Alcohol</div> <div>Drugs</div> </div> <div style="display: flex; justify-content: space-around; font-size: small;"> <div>N/A</div> <div>N/A</div> </div>	
						60. Was this consist transporting passengers? (Y/N) <div style="text-align: right;">N/A</div>	
61. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote	
(1) Total in Train		0		0 0		0 0	
(2) Total Derailed		0		0 0		0 0	
63. Equipment Damage This Consist		31021		64. Track, Signal, Way, & Structure Damage		0	
						65. Primary Cause Code	
						S102	
						66. Contributing Cause Code	
						N/A	
						Length of Time on Duty	
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen	
0		0		0		0	
						71. Engineer/Operator Hrs 0 Mi 0	
						72. Conductor Hrs 0 Mi 0	
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other	
Fatal		0		0		0	
Nonfatal		0		0		0	
						76. EOT Device? 1. Yes 2. No N/A	
						77. Was EOT Device Properly Armed? 1. Yes 2. No N/A	
						78. Caboose Occupied by Crew? 1. Yes 2. No N/A	
Highway User Involved				Rail Equipment Involved			
79. Type C. Truck-Trailer. F. Bus J. Other Motor Vehicle A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)				83. Equipment 3. Train (standing) 6. Light Loco(s) (moving) 1. Train(units pulling) 4. Car(s)(moving) 7. Light(s) (standing) 2. Train(units pushing) 5. Car(s)(standing) 8. Other (specify in narrative)			
80. Vehicle Speed (est. MPH at impact) 0				81. Direction geographical 1. North 2. South 3. East 4. West			
82. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				85. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User			
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				86b. Was there a hazardous materials release by 1. Highway User 2. Rail Equipment 3. Both 4. Neither			
86c. State here the name and quantity of the hazardous materials released, if any. <div style="text-align: center;">N/A</div>							
87. Type of Crossing Warning		1. Gates 4. Wig Wags 7. Crossbucks 10. Flagged by crew 2. Cantilever FLS 5. Hwy. traffic signals 8. Stop signs 11. Other (spec. in narr.) 3. Standard FLS 6. Audible 9. Watchman 12. None		88. Signaled Crossing Warning (See instructions for codes)		89. Whistle Ban 1. Yes 2. No 3. Unknown	
Code(s)		N/A N/A N/A N/A N/A N/A				N/A	
90. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach		Code N/A		91. Crossing Warning Interconnected with Highway Signals 1. Yes 2. No 3. Unknown		Code N/A	
93. Driver's Age 0		94. Driver's Gender 1. Male 2. Female N/A		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown		96. Driver 1. Drove around or thru the Gate 4. Stopped on Crossing 2. Stopped and then Proceeded 5. Other (specify in narrative) 3. Did not Stop	
						Code N/A	
97. Driver Passed Standing Highway Vehicle 1. Yes 2. No 3. Unknown		Code N/A		98. View of Track Obscured by (primary obstruction) 1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative) 2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed		Code N/A	
101. Casualties to Highway-Rail Crossing Users		Killed Injured 0 0		99. Driver Was 1. Killed 2. Injured 3. Uninjured		Code N/A	
				102. Highway Vehicle Property Damage (est. dollar damage) 0		100. Was Driver in the Vehicle? 1. Yes 2. No	
						103. Total Number of Highway-Rail Crossing Users (include driver) 0	
104. Locomotive Auxiliary Lights? 1. Yes 2. No		Code N/A		105. Locomotive Auxiliary Lights Operational? 1. Yes 2. No		Code N/A	
106. Locomotive Headlight Illuminated? 1. Yes 2. No		Code N/A		107. Locomotive Audible Warning Sounded? 1. Yes 2. No		Code N/A	

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

109. SYNOPSIS OF THE ACCIDENT

On May 30, 2005 at approximately 1:30 p.m. at Cumberland Yard, Cumberland, MD. an eastward CSX Transportation (CSXT) RCL Yard Switcher Y191-30 operating a train of mixed freight was involved in a side collision with a five car block of loaded cover hoppers that had just been humped to WO3 track. The train consisted of two locomotives, 94 cars, and was operating at a speed of 6 mph. Reportedly, the RCL lost remote control communication resulting in the locomotives defaulting to a full service brake application of the air brake system. The brake application was applied to the two locomotives and the twelve lead cars that were charged with air. This action caused a coupler knuckle to break at mile post 177.1 between the 33rd and 34th cars allowing 61 cars to roll freely without the knowledge of the crew. The 61 cars rolled freely approximately 1.4 miles gaining speed estimated to be 15 to 20 mph, and struck the first west car of the five car block that was humped to WO3. These cars had not yet cleared the east switch for track WO3. The impact derailed four of the humped cars, and eleven east cars of the 61 car runaway cut. Two of these cars struck the side of a standing intermodal train Q130-29 on track two main derailling the first east unit of articulated car TTX 553348 and dislodging one of the containers onto number 1 main track from car TTX 780310. The two man crew was operating the RCL on track WO2 in the classification yard after they were instructed to make-up train Q640-31.

There were no injuries reported and no hazardous materials involved.

Total damages are set at \$337431.

The weather was clear with an ambient temperature reported to be 65 F degrees.

The probable cause of the derailment and subsequent collision is the loss of signal communication between the Remote Control Operator (RCO) and the receiving unit on the RCL which caused the locomotive to initiate an emergency stop resulting in the broken knuckle on the 33rd car allowing the east 61 cars to roll free.

110. NARRATIVE

The following information was obtained from an investigation that was conducted by the Federal Railroad Administration.

Circumstances Prior to the Accident:

The crew of train CSX Y19030 included two Remote Control Operators (RCO) assigned to operate a remote control locomotive consist in CSX Cumberland Yard. The job consisted of switching cars in the yard. The Remote Control Operator Foreman reported for duty at 07:59 am (EST) on May 30, 2005 with 16 hours of statutory rest and had been on duty for 5 hours and 41 minutes. The Remote Control Operator Switchman reported on duty at 11:00 PM (EST) May 29, 2005 on job Y39029 and worked until 6:05am. After 4 hours 8 minutes interim release, he reported for duty at 11:59 AM (EST) on May 30, 2005 on job Y19030 and had been on duty for 1 hour and 41 minutes. He had a 72 hours of statutory rest period.

After receiving orders from the yardmaster to use remote control locomotives CSXT 2432 and 2431 the RCO's linked their Operator Control Unit(OCU) to the Remote Control Locomotive Control Unit(LCU) on locomotive CXST 2431. After linking with the LCU their job was to build train Q640-31 on WO2. They assembled 94 cars of mixed freight, which consisted of 43 loads and 51 empties, and proceeded west on #1 yard track to clear the west end switch for WO2. The RCO Switchman was controlling the move west while seated in the cab of the lead locomotive CXST 2432, while the RCO Foreman was at the east end of one yard waiting for the last car to clear the switch for WO2. When the last car cleared, the RCO foreman told the controlling RCO by radio to stop. The train had stopped west of the WO2 switch and the RCO foreman lined the switch for WO2 and radioed clearance to proceed back for a distance of about 100 cars. The movement on #1 yard was on level, tangent track with a descending grade into track WO2 in the classification yard.

The Accident:

The RCO controlling the move from the lead locomotive CSXT2432 started east at a speed of 6 mph according to the locomotive event recorder. After the cars started back on WO2 the RCO foreman got in his All Terrain Vehicle(ATV) and drove down to the car shop area to crossover the yard to direct the movement back. As the RCO foreman got out of his ATV, he lost communication between his OCU and the LCU on the locomotive. A penalty full service brake application was initiated to both locomotives and the twelve lead cars with a charged air system on the west end. When the train stopped a knuckle broke between the 33rd car and the 34th car causing the east 61 cars to keep rolling east on track WO2. The separation occurred on level, tangent track, although the majority of the cars were on a descending grade. As the 61 cars proceeded to roll east on WO2 for a mile, they gained speed estimated to be between 15 and 20 mph.

The RCO's regained communication with the LCU after a few seconds and they reset their OCU's and proceeded with the east move without knowing that a separation had occurred. An outbound road crew Q353-30 reported to the yardmaster that the train on WO2 was separated in two pieces and one of the cars had broken coupler knuckle. Five cars had just been humped to WO3 and were not in the clear at the east end of WO3 switch.

A collision occurred when the east car of the 61 car cut, HAFX 1018 struck car CSXT 252122 on WO3 sending HAFX 1018 towards W01. This started a general pile up towards #2 main track which was occupied with a standing block of cars from intermodal train Q130-29. The momentum of this collision resulted in car SOU 530313 being shoved into the Q130-29, derailling the first east unit of articulated car TTX 553348, also dislodging container ECU 161677 on the west unit of the first car TTX 780310 and sending it onto #1 Main track

Total equipment damages were set at \$ 282,431 and total of \$55,000 for track.

Analysis and Conclusions:

CSX Transportation at Cumberland, MD uses a remote control system that is manufactured by Cattron-Theimeg™. The two main components of this operating

system are the: Operator Control Unit and the Locomotive Control unit.

The Operator Control Unit is a portable radio remote control unit worn by the employee to control locomotive operations. It interfaces with the locomotive through a micro-computer electronic unit that "relays" command signals from the controller to the locomotive.

The Locomotive Control Unit is located on a remote control locomotive. The LCU responds to commands from the OCU and "relays" them to the locomotive's control system to cause the locomotive to move, adjust speed, or stop movement as directed by the OCU operator.

The LCU is designed in such a way that its default function is to keep the locomotive from moving or to stop locomotive movement. The OCU must send specific commands to the locomotive in normal switching and train operations.

Whenever a communication loss occurs while the locomotive is moving, a full service penalty will be initiated. A full service penalty consists of the throttle returning to idle, a full application of the locomotive independent brake, and a full service brake pipe reduction.

Some causes of communication loss are: when the remote control operator occupies a motor vehicle, goes inside a building, is out of range with the RCL, and when repeaters are used the RCO is in a communication zone other than the zone where the RCL is operating.

The CSX Communication Department and Cattron-Theimeg™ did joint testing of the radio signals the week of June 6th in the Cumberland yard to determine if any interference was causing some of the signal losses that were occurring periodically in the yard. They installed event recorders on the LCU of all RCL locomotives in the yard to verify any loss of communication between the LCU's and the OCU's.

The results of CSX Communication Department and Cattron-Theimeg™ testing in Cumberland yard concluded that the communication repeater at the west end of the yard near Virginia Avenue had a low Radio Frequency coverage. The repeater may have been hit by lightning at some point, which later was found to have a burnt out duplexer. They also concluded that the repeater zone (#1) at Virginia Avenue and repeater zone(#2) at the hump were coinciding a little too much. The zones were coinciding near the car shop area where some of the communication losses were occurring.

To correct the communication losses in the yard CSX replaced the communication repeater at Virginia Avenue, raise both communication towers additional thirty feet in height and relocate the communication tower at the hump farther east to revise the zones. The estimated time for the planned improvements barring weather conditions is July 30, 2005. Additional testing of the radio frequency coverage is planned after the improvements have been made.

Inspection of the locomotives revealed all systems were functioning properly and were in compliance according to Federal regulations. The locomotive event recorder was operating and did verify the speed of the train at the time of the accident.. The remote control system on the locomotives functioned as designed when a loss of communication occurs.

No Post Accident Toxicological Tests were performed on train crew Y19030.

Conclusions:

After lining the switch, the RCO Foreman instructed the RCO Switchman to control the shove move from the lead locomotive. Normally the Foreman would control the move from his end so that he could directly observe the entire movement. The Foreman, in this case, did not gain control of the move because he was driving a ATV to the location of the coupling. The railroad requires that an employee driving a vehicle cannot be in control of a remote control locomotive.

Through interviews, it was discovered that a loss of communication of the remote control equipment occurs frequently in this yard, especially near the high power lines at the car shop. The Foreman knew he would be driving his ATV through the area of the high power lines while the shove move was taking place.

After the loss of communication, and the subsequent full service application of the air brakes on the locomotives and the head twelve cars, the remote operators control units regained communication automatically within a few seconds, which is normal. After communication was restored, the Switchman immediately began the movement as originally instructed. At no time did the Foreman or the Switchman discuss the incident verbally.

Probable Cause

The FRA determined that the accident occurred because of the communication loss between the remote control operator unit and the remote locomotive control unit. This initiated a system penalty brake application on both remote controlled locomotives and the twelve cars with charged air brake. The brake application resulted in the train stopping abruptly causing the knuckle to break on the 33rd car, which subsequently caused 61 cars to roll freely.