



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2005-59***

***Union Pacific (UP)
Thrall, Texas
August 2, 2005***


Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

| DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION | | FRA FACTUAL RAILROAD ACCIDENT REPORT | | | | FRA File # <u>HQ-2005-59</u> | |
|--|--|---|--|--|--|---|--|
| 1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP] | | | | 1a. Alphabetic Code UP | | 1b. Railroad Accident/Incident No. 0805SA001 | |
| 2. Name of Railroad Operating Train #2 N/A | | | | 2a. Alphabetic Code N/A | | 2b. Railroad Accident/Incident N/A | |
| 3. Name of Railroad Responsible for Track Maintenance: Union Pacific RR Co. [UP] | | | | 3a. Alphabetic Code UP | | 3b. Railroad Accident/Incident No. 0805SA001 | |
| 4. U.S. DOT_AAR Grade Crossing Identification Number | | | | 5. Date of Accident/Incident Month Day Year 08 02 2005 | | 6. Time of Accident/Incident 06:30: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM | |
| 7. Type of Accident/Incident (single entry in code box) | | | | | | | |
| 1. Derailment | | 4. Side collision | | 7. Hwy-rail crossing | | 10. Explosion-detonation | |
| 2. Head on collision | | 5. Raking collision | | 8. RR grade crossing | | 11. Fire/violent rupture | |
| 3. Rear end collision | | 6. Broken Train collision | | 9. Obstruction | | 12. Other impacts | |
| | | | | | | 13. Other (describe in narrative) 01 | |
| 8. Cars Carrying HAZMAT 0 | | 9. HAZMAT Cars Damaged/Derailed 0 | | 10. Cars Releasing HAZMAT 0 | | 11. People Evacuated 0 | |
| | | | | | | 12. Division San Antonio Division | |
| 13. Nearest City/Town Thrall | | | | 14. Milepost (to nearest tenth) 137.3 | | 15. State Abbr Code N/A TX | |
| 16. County WILLIAMSON | | | | | | | |
| 17. Temperature (F) (specify if minus) 82 F | | 18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 1 | | 19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1 | | 20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1 | |
| 21. Track Name/Number Single Main | | | | 22. FRA Track Code Class (1-9, X) 4 | | 23. Annual Track Density (gross tons in millions) 46 | |
| | | | | 24. Time Table Direction Code 1. North 3. East 1 | | | |
| OPERATING TRAIN #1 | | | | | | | |
| 25. Type of Equipment Consist (single entry) | | 1. Freight train 4. Work train 7. Yard/switching | | A. Spec. MoW Equip. Code | | 26. Was Equipment Attended? Code | |
| 2. Passenger train 5. Single car 8. Light loco(s). | | 3. Commuter train 6. Cut of cars 9. Maint./inspect.car | | 1 | | 1. Yes 2. No 1 | |
| 27. Train Number/Symbol RHXTB C-01 | | | | | | | |
| 28. Speed (recorded speed, if available) Code R - Recorded 46 MPH R E - Estimated | | 30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits | | | | 30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0 | |
| 29. Trailing Tons (gross tonnage, excluding power units) 7424 | | | | | | | |
| 31. Principal Car/Unit | | a. Initial and Number | | b. Position in Train | | c. Loaded (yes/no) | |
| (1) First involved (derailed, struck, etc) | | N/A | | 12 | | yes | |
| (2) Causing (if mechanical cause reported) | | 0 | | 0 | | N/A | |
| | | | | | | 32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. | |
| | | | | | | Alcohol Drugs N/A N/A | |
| | | | | | | 33. Was this consist transporting passengers? (Y/N) N | |
| 34. Locomotive Units | | a. Head End | | Mid Train | | Rear End | |
| | | b. Manual | | c. Remote | | d. Manual c. Remote | |
| (1) Total in Train | | 4 | | 0 | | 0 | |
| (2) Total Derailed | | 0 | | 0 | | 0 | |
| | | | | | | 35. Cars | |
| | | | | | | a. Freight b. Pass. c. Freight d. Pass. e. Caboose | |
| | | | | | | (1) Total in Equipment Consist 58 0 0 0 0 | |
| | | | | | | (2) Total Derailed 36 0 0 0 0 | |
| 36. Equipment Damage | | 37. Track, Signal, Way, & Structure Damage | | 38. Primary Cause Code | | 39. Contributing Cause Code | |
| This Consist 557591 | | 236480 | | M204 | | N/A | |
| Number of Crew Members | | | | Length of Time on Duty | | | |
| 40. Engineer/Operators N/A | | 41. Firemen 0 | | 42. Conductors 1 | | 43. Brakemen 0 | |
| | | | | | | 44. Engineer/Operator Hrs 9 Mi 30 | |
| | | | | | | 45. Conductor Hrs 9 Mi 30 | |
| Casualties to: | | 46. Railroad Employees | | 47. Train Passengers | | 48. Other | |
| Fatal | | 0 | | 0 | | 0 | |
| Nonfatal | | N/A | | 0 | | 0 | |
| | | | | | | 49. EOT Device? 1. Yes 2. No 1 | |
| | | | | | | 50. Was EOT Device Properly Armed? 1. Yes 2. No 1 | |
| | | | | | | 51. Caboose Occupied by Crew? 1. Yes 2. No 2 | |
| OPERATING TRAIN #2 | | | | | | | |
| 52. Type of Equipment Consist (single entry) | | 1. Freight train 4. Work train 7. Yard/switching | | A. Spec. MoW Equip. Code | | 53. Was Equipment Attended? Code | |
| 2. Passenger train 5. Single car 8. Light loco(s). | | 3. Commuter train 6. Cut of cars 9. Maint./inspect.car | | N/A | | 1. Yes 2. No N/A | |
| 54. Train Number/Symbol N/A | | | | | | | |
| 55. Speed (recorded speed, if available) Code R - Recorded 0 MPH N/A E - Estimated | | 57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track | | | | 57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable | |

| DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION | | FRA FACTUAL RAILROAD ACCIDENT REPORT | | | | FRA File # <u>HQ-2005-59</u> | |
|--|--|---|--|---|--|---|--|
| 56. Trailing Tons (gross tonnage, excluding power units) <div style="text-align: right;">0</div> | | c. Auto train stop d. Cab e. Traffic f. Interlocking | | i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits | | o. Positive train control p. Other (Specify in narrative) Code(s) <div style="display: flex; justify-content: space-around; font-size: small;"> <div>N/A</div> <div>N/A</div> <div>N/A</div> <div>N/A</div> <div>N/A</div> </div> | |
| | | | | | | 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter <div style="text-align: right;">N/A</div> | |
| 58. Principal Car/Unit | | a. Initial and Number | | b. Position in Train | | c. Loaded(yes/no) | |
| (1) First involved (derailed, struck, etc) | | 0 | | 0 | | N/A | |
| (2) Causing (if mechanical cause reported) | | 0 | | 0 | | N/A | |
| | | | | | | 59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. | |
| | | | | | | <div style="display: flex; justify-content: space-around; font-size: small;"> <div>Alcohol</div> <div>Drugs</div> </div> <div style="display: flex; justify-content: space-around; font-size: small;"> <div>N/A</div> <div>N/A</div> </div> | |
| | | | | | | 60. Was this consist transporting passengers? (Y/N) <div style="text-align: right;">N/A</div> | |
| 61. Locomotive Units | | a. Head End | | Mid Train b. Manual c. Remote | | Rear End d. Manual c. Remote | |
| (1) Total in Train | | 0 | | 0 | | 0 | |
| (2) Total Derailed | | 0 | | 0 | | 0 | |
| | | | | | | 62. Cars | |
| | | | | | | a. Freight b. Pass. c. Freight d. Pass. e. Caboose | |
| | | | | | | (1) Total in Equipment Consist | |
| | | | | | | 0 | |
| | | | | | | (2) Total Derailed | |
| | | | | | | 0 | |
| 63. Equipment Damage This Consist | | 0 | | 64. Track, Signal, Way, & Structure Damage | | 0 | |
| | | | | | | 65. Primary Cause Code | |
| | | | | | | N/A | |
| | | | | | | 66. Contributing Cause Code | |
| | | | | | | N/A | |
| | | | | | | Length of Time on Duty | |
| 67. Engineer/Operators | | 0 | | 68. Firemen | | 0 | |
| | | | | 69. Conductors | | 0 | |
| | | | | 70. Brakemen | | 0 | |
| | | | | | | 71. Engineer/Operator Hrs 0 Mi 0 | |
| | | | | | | 72. Conductor Hrs 0 Mi 0 | |
| Casualties to: | | 73. Railroad Employees | | 74. Train Passengers | | 75. Other | |
| Fatal | | 0 | | 0 | | 0 | |
| Nonfatal | | 0 | | 0 | | 0 | |
| | | | | | | 76. EOT Device? 1. Yes 2. No N/A | |
| | | | | | | 77. Was EOT Device Properly Armed? 1. Yes 2. No N/A | |
| | | | | | | 78. Caboose Occupied by Crew? 1. Yes 2. No N/A | |
| Highway User Involved | | | | Rail Equipment Involved | | | |
| 79. Type C. Truck-Trailer. F. Bus J. Other Motor Vehicle A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative) | | | | 83. Equipment 3. Train (standing) 6. Light Loco(s) (moving) 1. Train(units pulling) 4. Car(s)(moving) 7. Light(s) (standing) 2. Train(units pushing) 5. Car(s)(standing) 8. Other (specify in narrative) | | | |
| 80. Vehicle Speed (est. MPH at impact) 0 | | | | 81. Direction geographical 1. North 2. South 3. East 4. West | | | |
| 82. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped | | | | 85. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User | | | |
| 86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither | | | | 86b. Was there a hazardous materials release by 1. Highway User 2. Rail Equipment 3. Both 4. Neither | | | |
| | | | | | | | |
| 86c. State here the name and quantity of the hazardous materials released, if any. <div style="text-align: center;">N/A</div> | | | | | | | |
| 87. Type of Crossing Warning | | 1. Gates 4. Wig Wags 7. Crossbucks 10. Flagged by crew 2. Cantilever FLS 5. Hwy. traffic signals 8. Stop signs 11. Other (spec. in narr.) 3. Standard FLS 6. Audible 9. Watchman 12. None | | 88. Signaled Crossing Warning (See instructions for codes) | | 89. Whistle Ban 1. Yes 2. No 3. Unknown | |
| Code(s) | | N/A N/A N/A N/A N/A N/A | | | | N/A | |
| 90. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach | | Code N/A | | 91. Crossing Warning Interconnected with Highway Signals 1. Yes 2. No 3. Unknown | | Code N/A | |
| 93. Driver's Age 0 | | 94. Driver's Gender 1. Male 2. Female N/A | | 95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown N/A | | 96. Driver 1. Drove around or thru the Gate 4. Stopped on Crossing 2. Stopped and then Proceeded 5. Other (specify in narrative) 3. Did not Stop N/A | |
| 97. Driver Passed Standing Highway Vehicle 1. Yes 2. No 3. Unknown | | Code N/A | | 98. View of Track Obscured by (primary obstruction) 1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative) 2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed | | Code N/A | |
| 101. Casualties to Highway-Rail Crossing Users | | Killed Injured 0 0 | | 99. Driver Was 1. Killed 2. Injured 3. Uninjured N/A | | 100. Was Driver in the Vehicle? 1. Yes 2. No N/A | |
| | | | | 102. Highway Vehicle Property Damage (est. dollar damage) 0 | | 103. Total Number of Highway-Rail Crossing Users (include driver) 0 | |
| 104. Locomotive Auxiliary Lights? 1. Yes 2. No | | Code N/A | | 105. Locomotive Auxiliary Lights Operational? 1. Yes 2. No | | Code N/A | |
| 106. Locomotive Headlight Illuminated? 1. Yes 2. No | | Code N/A | | 107. Locomotive Audible Warning Sounded? 1. Yes 2. No | | Code N/A | |

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.
HQ-59-
2005.jpg

03



109. SYNOPSIS OF THE ACCIDENT

A northbound Union Pacific Train RHXBTC-01 derailed on August 02, 2005 at approximately 6:30 a.m. The accident occurred near Thrall, Texas at milepost 137.3 on the Union Pacific San Antonio subdivision.

There were no injuries to the train crew. The train derailed at the 8th car in the consist, (12th position in train with 4 locomotives on the lead) with 36 of 58 cars derailed. Damage to cars and track is estimated at 794,071 dollars.

At the time of the accident it was dawn and clear with a temperature of 82 degrees.

The cause of derailment was car DISX 2680 being out of the center bowl and resting on the center pin when the car was loaded.

110. NARRATIVE

The crew of the Union Pacific train RHXBTC - 01 included a locomotive engineer and a conductor. They first went on duty at 09:00 p.m. hours CST on August 01, 2005. Both crew members received more than the statutory off duty period, prior to reporting for duty. The crew was taken to their train at the Texas Lehigh Company, Southwest of Austin, where they performed an initial terminal brake test.

Their assigned freight train consisted of four locomotives and 58 loaded cement cars. It was 2,666 ft. in length and weighed 7,424 tons. The train was scheduled to travel to Beaumont, Texas.

As the Northbound train approached the accident area, the engineer was in his seat facing forward on the right side of the cab, at the controls of the leading locomotive. The conductor was seated in the front seat on the left hand side of the cab of the leading locomotive.

In this area, the track is tangent for about 15,000 feet in both directions from the point of the accident with no descending/ascending grade. Texas Highway 79 runs parallel to the track on the North side.

The railroad timetable direction of this train is North. The geographic direction of the train is East.

The Accident/Derailment:

The train was being operated at 46 mph at the time of the derailment as recorded by the event recorder. The timetable speed for this section of track is 60 mph as per current Union Pacific San Antonio Timetable No. 2 Effective 10/29/2000..

At approximately 06:30 a.m. CST on August 02, 2005 Union Pacific train RHXBTC-01 derailed at milepost 137.3 on the Union Pacific San Antonio Subdivision. The derailment started with the 8th car in the consist (12th position due to 4 locomotives on the lead of the train) and 36 of 58 loaded cement cars derailed. As per statements from the train crew, and downloaded interpretations of the event recorder, the train went into emergency. Due to the fact that it was a trainline induced emergency, the crew did not realize that the derailment had occurred and took no immediate action.

Analysis and Conclusion:

Evaluation and Testing of Equipment Involved

The Union Pacific Railroad evaluated 18% of the derailed cars. These were the cars that they were able to salvage to reconstruct the conditions prior to, and after the accident. The evaluation consisted of measurements taken on the wheels, trucks, side bearings and brake rigging. It was noted that all of the mechanical measurements were within the requirements as set forth in the Code of Federal Regulations.

The Union Pacific Railroad simulated the conditions that they alleged caused the derailment. With the car being out of the center bowl and resting on the pin, the simulation of the derailment revealed similar damage to one or more of the cars. The damage characteristics caused to the bolster and the center pin were consistent with the damages caused by the derailment. They concluded that it could have been loaded in an with the car up out of the bowl resting on the center pin, creating shifting and an unbalanced load enroute. Due to the catastrophic damage at the derailment sight, there is no evidence to refute these findings as they are consistent with the damage and other data available.

FRA Testing and Inspections

FRA on sight investigation of the derailment showed that the lead five cars had been pulled in the opposite direction of movement as the center pins holding the trucks into the bolster were either missing or bent in the reverse position. Other damage showed that the cars were pulled to the left side of the train and almost all of the damaged/derailed cars were on the North side (left side) of the track area.

FRA inspections of locomotive and cars repair and maintenance records did not reveal any conditions that would have caused or contributed to the cause of the accident. FRA Inspections of the track repair records showed that the computer repair records for the this area of track were not updated; however subsequent proper maintenance records were provided by the carrier.

Tox Test Results

The crew was tested in accordance with requirements set forth in 49 CFR Part 219 (Subpart C). The toxicological test results on the crew were negative.

Conclusion:

The railroad was in full compliance with their own and , and all applicable Federal standards. The train crew members were the only witnesses to the derailment and they had no pertinent information as to why the train derailed. Based on the information available, testing performed by the railroad, and the characteristics of the derailment, if the freight car was loaded with the car off center and out of the bowl resting on the pin, it could cause a shifted or shifting load and that could have been the primary cause of the accident. Due to the extensive damage to track and equipment it is difficult to determine with any certainty if there were any other contributing factors. The FRA does not dispute the findings of the railroad at this time.