

# Federal Railroad Administration Office of Safety Headquarters Assigned Accident Investigation Report HQ-2005-60

Amtrak (ATK)/Norfolk Southern (NS) Belton, Montana August 5, 2005

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.


DEPARTMENT OF TRANSPORTATION FRA FACTUAL RAILROAD ACCIDENT REPORT FRA File # HQ-2005-60																			
1.Name of Railroad (	rai i irpinacene code					Railroad Accident/Incident No.													
Amtrak [ATK ]			ATK					097639											
2.Name of Railroad Operating Train #2									•					Railroad Accident/Incident					
N/A	N/A					21.	N/A Railroad Accident/Incident No.												
3.Name of Railroad R	1					30.	Kanroad A			ent No.									
Amtrak [ATK ] 4. U.S. DOT_AAR G	ATK					( 7	·	097639											
4. U.S. DUI_AAR G	5.1	5. Date of Accident/Incident  Month   Day   Year					Time of Accident/Incident												
735480V									08 02 2005					12:35: AM ✓ PM					
7. Type of Accident/Indicent 1. Derailment 4. Side collision									7. Hwy-rail crossing 10. Explosion-detonation 13. Other										
(single entry in co	g collision n Train co		8. RR grade crossing 11. Fire/violent ruptu n 9. Obstruction 12. Other impacts						ure (describe in narrative) 07				07						
8. Cars Carrying HAZMAT 0	9. HAZMAT Cars Damaged/Derailed								g 11. People Evacuated					12. Division 0 Piedmont					
13. Nearest City/Tow	13. Nearest City/Town				14. Milepost (to nearest t			enth)	15. State Abbr			Code	16	. County					
Raleigh							icarest to		H83.6			N/A   NC			WAK				
17. Temperature (F) (specify if minus) 18. Visibility 1. Dawn 94 F 2 Day			3.D	3.Dusk						5.Sleet				Iain 3.	Siding		Code		
94 F 2. Day 21. Track Name/Number			Day	4.Dark 2 22. FRA Ti				, <u> </u>			6.Snow 1 Annual Track Density			2. Yard 4. Indus				Code	
М				ain		Clas	s (1-9, X	()	4 (gross tons in millions) 3.9					1. North 3. East 3					
						•	OPER	ATI	NG TRA	IN #1				1					
25. Type of Equipme		. Freight tr				. Yard/swi	_	A.	Spec. Mo	W Equip	. Code		as Equip	ment (	Code	27. Tr	ain Nun	nber/Symbol	
Consist (single entry) 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.c									Attended?					1 1					
28. Speed (recorded					Method(s)		•		r code(s)	that ap	ply)			30a. Rem	otely C	ontroll	ed Loco	motive?	
R - Recorded	1	,			ATCS	•	. Autom			• • •	ial instru	ctions		0 = Not a	2-Smit	hy <del>l</del> oN	Vienled		
E - Estimated 48 MPH R b. Auto train control h. Curre															1 = Remote control portable				
29. Trailing Tons		ole/train orders o. Positive train control p. Other (Specify in narrative)						ote cont		/er									
avaluding navor unita)									traffic control (Specify in narrative)  Code(s)						3 = Remote control transmitter - more than one				
									ic control			1	NT/A	remote				1 0	
31. Principal Car/Uni	e N/A N/A N/A 0																		
(1) First involved (derailed, struck, etc)					1						number	number that were positive				Alcohol N/A	Drugs N/A		
(2) Causing (if mechanical 0					0			ľ	N/A 33. Was this consist to					nsporting passengers? (Y/N)					
cause reported)  34. Locomotive Units a. Head				Mid T	`rain	Re	ar End		35. Car	s		<u> </u>	Lo	ade		Empty	у		
(1) m . 1: m .			nd b. Manual		c. Remote		0 0 0				a. Fi		Freight		1	ight d.		e. Caboose	
(1) Total in Train			1 0						(2) Total Derailed				0	7	0		0	0	
(2) Total Deraile 36. Equipment Dama		1		0	0	0	0		` ′				0	4	0	_	0	0	
This Consist 650000			3	7. Track, Signal, Way, & Structure Damage   8000					38. Primary Cause Code M308						39. Contributing Cause Code N/A				
Number of Crew Members									Length of Time on Duty										
40. Engineer/ Operators	41. Fir	1			onductors	43. Bra	43. Brakemen		44. Engineer/Oper					45. Conductor				Mi o	
N/A	46 70 11		0 1				1		Hrs 2 Mi					Hrs 2 Mi 2  50. Was EOT Device Properly Armed?					
Casualties to:	46. Kaili	road Employees 47. Train							49. EOT Device?  1. Yes 2. No 2					1. Yes 2. No N/A					
Fatal	0			0		2		51. Caboose Occupied by Crew?											
Nonfatal	N/A		12			0		1. Yes			2. No	. No				N/A			
OPERATING TRAIN #2																			
52. Type of Equipme	a	Freight tra				Yard/swit	_	A.	Spec. Mo	W Equip	. Code		as Equip	ment C	Code	54. Tra	ain Nun	nber/Symbol	
Consist (single chiry)						Light loce Maint./ins		-		Attend		tended?	2 No   N/A			N/A			
55. Speed (recorded							•		r code(s)	that are			1. 1 es	2.110		ontroll			
55. Speed (recorded speed, if available) Code  R - Recorded  a. ATCS  g. Auto									enter code(s) that apply)  atic block m.Special instructions					57a. Remotely Controlled Locomotive?  0 = Not a remotely controlled					
E - Estimated 0 MPH N/A b. Auto train control h. Current of															1 = Remote control portable				

Form FRA F 6180.39 (11/06) Page 1 of 5

FEDERAL RA						FRA F	ACTUA	L RAILR	OAD AC	CIDENT F	REPO	ORT	F	RA File #	HQ-200	<u>5-60</u>			
56. Trailing Tons (gross tonnage, excluding power units)  C. Auto train stop d. Cab e. Traffic f. Interlocking							j.' k.	i. Time table/train orders j.Track warrant control k. Direct traffic control l.Yard limits  o. Positive train control p. Other (Specify in narrative) Code(s)  2 = Remote control 3 = Remote control transmitter - more remote control trainsmitter - more remote - more rem						te control ter - more t	han one	N/A			
58. Principal Car/Unit a. Initial and Number b. Position in T							ion in Trair	n c. Load	ded(yes/no)	59. If railroad	oyee(s) teste	d for drug							
(1) First involved (derailed, struck, etc)							0		N/A	enter the the appro		er that were box.	positive in	Drugs N/A					
(2) Causing (if mechanical cause reported) 0							0		N/A	60. Was this	consi	st transporti	ng passen	ı N/A					
61. Locomotive Units a. Head				Mid '			ar End	62. Cars		Loa a. Freight		a Cabassa							
(1) Total in	(1) Total in Train 0			b. Manual 0		c. Remote	d. Manual	c. Remote		Total in Equipment Consist			0	c. Freight	0	e. Caboose			
(2) Total De	(2) Total Derailed		0		0	0	0	0	(2) Total D	erailed		0	0	0	0	0			
63. Equipment Damage					64. Tra	ick, Signal,	Way,		65. Primar	y Cause			66. Contributing Cause						
This Consist 0					& S	Structure D		0	Code N/A Code  Length of Time on Duty										
	68	Firer					70 Br	akemen	71 Engine	eer/Onerator			72. Cond						
67. Engineer/ Operators	68. Firemen 0				69. Conductors 70			0		71. Engineer/Operator Hrs 0 Mi 0				Hrs 0 Mi					
Casualties to:	73. R	Railro	ad Empl	oyees	74. Trai	in Passenge	rs 75. Oth	ner	76. EOT Device?  1. Yes 2. No N/A				77. Was l	Armed?					
Fatal			0			0		0		se Occupied by			N/A						
Nonfatal			0 Highw	av II	ser Invo	0 olved		0		1. Yes 2. No									
79. Type			IIIgiiw	ay O	SCI IIIV	Jiveu		Rail Equipment Involved  83. Equipment											
C. Truck-Trailer. F. Bus J. Other Motor Vehicle 3. Train (standing) 6. Light Loco(s) (moving)  A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian 1. Train(units pulling) 4. Car(s) (moving) 7. Light(s) (standing)													Code 1						
B. Truck E. Va		H.						2. Train(units pushing) (standing) 6. Other (specify in narrative)											
80. Vehicle Speed 81. Direction geographical) Code (est. MPH at impact) 00 1.North 2.South 3.East 4.West 2										84. Position of Car Unit in Train									
(est. MPH at impact) 00   1.North 2.South 3.East 4.West   2 82. Position Code										85. Circumstance									
1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 1. Rail Equipme											ment Struck Highway User ment Struck by Highway User								
86a. Was the hi						olved		Code		here a hazardo				Code					
in the impa	-	_				4 Neither		1 4	1. High	way User 2.	Rail E	quipment	3. Both	4. Neither	:	4			
1. Highway User 2. Rail Equipment 3. Both 4. Neither 4 1. Highway User 2. Rail Equipment 3. Both 4. Neither 4 86c. State here the name and quantity of the hazardous materials released, if any.																			
		•	•					N/A											
Crossing	1.Gates 2.Cantileve 3.Standard		4.Wig S 5.Hw 6.Au	y. tra			signs 11	O.Flagged by Other (spec O.None	I	88. Signaled C		-	Code	1. Yes	89. Whistle Ban 1. Yes 2. No				
Code(s)	01		I/A	N/	'A	N/A	N/A	N/A	N/A 3. Unknown						known	2			
90. Location of V 1. Both Side	_								Interconnecte gnals	ed Code				luminated by Street Special Lights					
Side of Vehicle Approach     Opposite Side of Vehicle Approach     1								. Yes . No		2	1. Yes 2. No					2			
					05.0			Unknown		3. Unknown						Code			
93. Driver's 94. Driver's Gender Code Age 1. Male 2. Female					and	d Struck or		n Front of T by Second ' 3. Unknown	1. Drove around or thru the Gate 4. Stopped on Crossing										
34 1 1 00 View 6 To de Obra								2											
97. Driver Passed Standing Highway Vehicle 98. View of Track Obscured by (primary obstruction) 1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative)													Code						
1. Yes 2. No 3		_	2		2. Stan	ding Railro			graphy 6. l	Highway Vehic		Not obstru				8 Code			
101. Casulties to Highway-R Crossing Users			Killed		ed 1			Was 2.Injured 3.	Uninjured	Code   1				Driver in the Vehicle? Yes 2. No					
			02		$\top$	00	_	way Vehicle	Property Damage 0 103. Total Number of Highway-Rail C (include driver)					Rail Cross	ing Users				
(est. doint damage)													Code						
1. Yes	s		2. No	)				1		Yes		2. No				1			
106. Locomotive Headlight Illuminated?							'	Code	107. Locomotive Audible Warning Sounded?							Code			
1. Yes 2. No									1. Yes 2. No										

Form FRA F 6180.39 (11/06) Page 2 of 5

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.  $^{\rm HQ-60-}_{\rm 2005}$  sketch.jpg



Form FRA F 6180.39 (11/06) Page 3 of 5

### FRA File # HQ-2005-60

## 109. SYNOPSIS OF THE ACCIDENT

On August 2, 2005, Amtrak (ATK) Passenger Train No. 80 was operating on the Norfolk Southern Corporation (NS), Piedmont Division main track in Raleigh, North Carolina (NC). This track segment extends from Goldsboro to Greensboro, NC. There were 204 passengers, four ATK on-board crew members, a locomotive engineer, conductor, and assistant conductor totaling 211 people.

About 12:35 p.m. Eastern Standard Time (EST), ATK Train No. 80 struck a moving dump truck at milepost (mp) H83.6. The truck was traveling southbound across highway-rail grade crossing (Rush Street/State Route 2683, U.S. DOT No. 735480V). The collision caused the derailment of the locomotive, baggage car, and first three passengers cars. The last four passenger cars of the consist did not derail and all the equipment remained upright. 18 passengers, three ATK on-board service personnel, and the locomotive engineer were taken to area hospitals. The engineer was treated and released from the hospital that day. Two passengers were admitted into the hospital. The remaining passengers were transported by Raleigh City Buses to Raleigh Civic Center, which was utilized as a staging area. ATK provided transportation for these passengers to their final destination.

According to eyewitnesses, ATK Train No. 80 was blowing the whistle. The active warning devices (lights, gates, and bell) were operating when the dump truck went around the crossing gates in front of the approaching train.

The collision resulted in the deaths of the driver and passenger of the truck. Damages are \$650,000 to rail equipment and \$8,000 to track structures.

At the time of the accident it was daylight and clear. The temperature was 94 °F.

The probable cause of the accident was the failure of the truck driver to stop at the crossing.

# 110. NARRATIVE

The following information was obtained from an investigation that was conducted by the Federal Railroad Administration.

Circumstances Prior to the Accident

ATK Train No. 80 crew consisted of a locomotive engineer, conductor, assistant conductor, and four on-board service employees. The train crew went on duty at 10:33 a.m., on August 2, 2005, at ATK's Raleigh station, which is their away from home terminal. The crew received 12 hours 28 minutes off duty time prior to reporting for duty.

ATK Train No. 80 consisted of ATK Locomotive No. 69, one baggage car, and seven passenger coaches. After receiving the required initial terminal air brake test at Charlotte, NC, the train departed at 7:50 a.m. eastward toward Raleigh, NC where there was a crew change. The train departed Raleigh at 12:27 p.m. and was uneventful until the accident site. As Train No. 80 approached Rush Street, the engineer was seated at the controls on the south side of the locomotive, assistant conductor was in the business class coach, and the conductor was in the fifth coach collecting tickets. Eastbound trains approaching traverse a long left hand curve with a 0.92-percent ascending grade that extends through the crossing.

The NS timetable direction of the train and the geographic direction is east. Timetable directions are used throughout this report.

The Accident

ATK Train No. 80 was operating at a recorded speed of 48 miles per hour (mph) as it approached the Rush Street crossing. The engineer began sounding the train horn at the whistle board, which is located 1,789 feet west of the highway crossing. As he came out of the sweeping left hand curve, the engineer did not notice anyone on either side of the road crossing. He sounded another long whistle approaching Rush Street and noticed a dump truck pulling up to the north side of Rush Street road crossing. The truck went around the activated crossing gate and did not appear to be slowing down. He dove to the floor of the locomotive cab and did not have time to apply the train's emergency brake application.

The dump truck was struck on the passenger side cab door, causing the truck cab to separate from the bed of the truck. The cab of the truck and front axle landed down the embankment on the east side of the roadway, 15 feet north of the main track. The bed of the truck and rear axle were still near the area of impact. The locomotive derailed at the point of impact and traveled east about 300 feet before it stopped. After the accident, the assistant conductor went to the locomotive to check on the engineer while the conductor stayed on the coaches attending to the passengers. The assistant conductor notified the train dispatcher by radio from the cab of the locomotive about the accident.

The driver and passenger of the dump truck were both ejected by the force of the impact. Witnesses at a convenience store near the Rush Street crossing called 911 to alert the local authorities. Raleigh Police, EMS and Fire departments responded within minutes of the accident.

The driver and passenger were pronounced dead at the scene of the accident by the Wake County Coroner.

Highway Vehicle

The dump truck was a 1973 Ford dump truck with an NC registration no. U902VR54342. The dump truck was driven by a 34 year old male with an NC driver's license. His driving record showed four charges of driving without a license, three charges of speeding, and one case of failure to stop at a red light. Also recorded was an accident that occurred on January 24, 2005. There was a collision with injuries and he was cited for expired plates, no registration, parking a vehicle in the highway, and defective tail light. The other occupant of the dump truck was a 33 year old male.

Form FRA F 6180.39 (11/06) Page 4 of

# DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

### FRA FACTUAL RAILROAD ACCIDENT REPORT

FRA File # HQ-2005-60

The dump truck was traveling south on Rush Street. According to two eyewitnesses, the driver of the dump truck made no attempt to stop at the crossing. The dump truck was totally destroyed.

### Description of Accident Site

Rush Street is a straight two lane undivided asphalt roadway with a median center isle. The road crossing is equipped with gates mounted on ground masts, flashing lights, and a bell mounted on cantilever signals. There is an advance warning sign 374 feet north of the crossing. The street is equipped with a painted stop bar 23 feet from the north rail. The southbound lane is equipped with a railroad advance pavement marking and a railroad advance warning sign, 381 and 374 feet respectively from the north rail. The highway speed in the area of the crossing is posted as 45 mph and the view is unlimited for highway users.

No toxicological tests were performed on the ATK train crew.

### Analysis and Conclusion

West of Rush Street there is a whistle post about 1,789 feet at the point where the crossing gate warning system would be activated and provides 30 seconds of warning time to highway users. ATK Train No. 80 horn and bell were sounding for 40 seconds prior to impact, as indicated by the trains event recorder.

An NS signal supervisor arrived at Rush Street crossing shortly after the collision and sealed the crossing case. When the Federal Railroad Administration (FRA) Signal & Train Control (S&TC) inspector arrived, the crossing case was unsealed and testing of the crossing system began. Operation tests of the Safetran Grade Crossing Predictor, Model 3000, were observed by FRA and North Carolina Department of Transportation (NCDOT) S&TC inspectors with no exceptions noted. According to the highway-rail grade crossing control equipment that was tested, the recorded warning time for ATK Train No. 80 was 32 seconds. When the control equipment is activated, four seconds later the gates break away and eight seconds after that the gates are horizontal for a total of 12 seconds. This indicates with 32 seconds warning time, the crossing gates would have been horizontal for 20 seconds before ATK Train No. 80 entered the Rush Street highway-rail grade crossing.

The crossing width of the road at Rush Street is 61 feet. The gate length protecting the southbound lane is 24 feet. This completely protects the southbound lane for highway traffic when the crossing is activated by an approaching train.

The locomotive is equipped with headlights, auxiliary lights, and an audible warning device required by the Code of Federal Regulations Part 229 Railroad Safety Standards. The engineer observed that these devices were working as ATK Train No. 80 was pulling into the Raleigh station. Eyewitness statements at the time of the accident stated the same.

Several eye witnesses to the accident gave statements that the dump truck driver made no attempts to stop short of the Rush Street crossing at the time of the accident. Two eyewitness statements state that the vehicle never slowed down before entering onto the highway-rail grade crossing or stopped. They also said the gates were down, and the bell and crossing lights were working properly as the dump truck attempted to drive around the lowered railroad crossing gates.

### Conclusion

The dump truck driver failed to stop at Rush Street crossing and proceeded to drive around the crossing gates as the train entered the crossing, striking the dump truck. The ATK engineer complied with all railroad operating rules.

### Probable Cause

The FRA determined that the probable cause of the accident was the failure of the motor vehicle driver to stop at the highway-rail grade crossing and yield the right

Form FRA F 6180.39 (11/06) Page 5 of 5