

Federal Railroad Administration Office of Safety Headquarters Assigned Accident Investigation Report HQ-2005-70

Burlington Northern Santa Fe (BNSF) Bear, Nebraska August 27, 2005

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

DEPARTMENT ( FEDERAL RAILR					FRA FA	ACTUA	AL RA	ILROAD	AC	CIDENT I	REPO	RT	I	FRA Fi	le #	<u>HQ-200</u>	<u>95-70</u>		
1.Name of Railroad C BNSF Rwy Co. [BN		g Train #1					1a. Alphabetic Code 1b. BNSF					Railroad Accident/Incident No. NE0805107							
2.Name of Railroad O	2a. Alphabetic Code   2b. 1					Railroad Accident/Incident													
N/A							N/A					N/A							
3.Name of Railroad R	esponsit	ole for Trac	k Mai	ntenan	ce:		3a. Alphab	3b. 1	Railroad A	ccident	/Incic	lent No.							
BNSF Rwy Co. [BN 4. U.S. DOT_AAR Gr	ISF]	asing Ident	fication	Nue	whee					0805L									
4. U.S. DUI_AAR G	rade Cro	ssing ident	meano	on Nur	nber		5. Date of A Mont	Fime of Accident/Incident											
							08		Day 27	Year 2005		07:55: 🖌 AM 🗌 PM							
7. Type of Accident/I	ndicent	1. Deraili	nent		4. Side c	ollision		7. Hwy-ra	uil cro	ossing 10.	on-deton	h-detonation 13. Other							
(single entry in cod	le box)	2. Head of			•	g collisior		-	8. RR grade crossing 11. Fire/violent rupture (describe in narrative) 9. Obstruction 12. Other impacts										
		3. Rear er	nd col	lision	6. Broke	n Train co	ollision	9. Obstru	ction	12. Other impac							01		
8. Cars Carrying HAZMAT	ZMAT Democod/Deroiled						10. Cars Releasir HAZMAT						12. Division						
0 Damaged/Deranet					0	0		Evacuated			0			lebraska	l				
13. Nearest City/Tow			a1.5	1	5. State Abbr	16	16. County												
	Τe	ecumseh			(to nearest to			165.1		N/A	Code			JOHNSON					
17. Temperature (F)		18. Visit	oility	(sing	single entry) Code   19. V			eather (sir	igle e	ntry)	Co	de	20. Typ	pe of Track			Code		
(specify if minus)			Dawn		3.Dusk			. Clear 3.	Rair	-		1. M	Aain 3. Siding			1 1			
65		2.1	Day	4.I	Dark				Fog	6.Snow		1		2. Yard 4. Industry			1		
21. Track Name/Num	ber					22. FRA	A Track ss (1-9, X	Code				nual Track Density ross tons in			24. Time Table Direction 1. North 3. East				
	Ν	rack				4	10.36	1. Norui 5. East 3											
Main Track     4     millions)     110.36     3       OPERATING TRAIN #1																			
25. Type of Equipme	nt 1	. Freight tra	nin	4. W	ork train 7.	Yard/sw	itching	A. Spec. M	ЛоW	Equip. Code	26. W	as Equip	ment (	Code	27. T	rain Nur	nber/Symbol		
Consist (single en	co(s).	-		ttended?	nded?														
		. Commute			t of cars 9	spect.ca	r		1	1. Yes	2. No         1         CBTMLRT107           30a. Remotely Controlled Locomotive?								
28. Speed (recorded speed, if available)         Code         30. Method(s) of Operation         (enter code(s) that appl           R - Recorded         a. ATCS         g. Automatic block         m.Special																	omotive?		
R - Recorded	-	t of traffic	•						0 = Not a4 <b>chautt</b> ly <b>toWented</b> 1 = Remote control portable										
E - Estimated 50 MPH R c. Auto train stop i. Time t									ers o	. Positive train	n control		2 = Remote control tower						
29. Trailing Tons (		arrant contro	•		ify in na	rrative)													
excluding power units) e. Traffic   19227 f. Interlocking								traffic contro	ol  -	Code			transmitter - more than one remote control transmitter				1		
						-	.Yard lin	lits		e N/A N	J/A N/.	A N/A					0		
31. Principal Car/Unit		a. Initial	and Ni	umber	b. Positio	on in Train	n c. I	Loaded(yes/n	0)	32. If railroad			-						
<ol> <li>(1) First involved (derailed, struck, e</li> </ol>	tc)				yes the appropri					positive i	n		Alcohol 0	Drugs 0					
(2) Causing (if med	,	1				33 Was ti			-		ting passengers? (Y/N)			0	0				
cause reported)		KP	LX10'	71				yes		55. was uns	consist		01	gers. (	,		N		
34. Locomotive Units	a. Head End b. Ma		Mid 1	Frain c. Remote		ear End	35. 0	Cars			Lo . Freight	aded b. Pass.	a Eroi	Emp	ty 1. Pass.	e. Caboose			
(1) Total in Train		<u>End</u> 3	D. Ma	0	c. Remote	0	0		tol in	Equipment Co		135	0.1 ass.	0	-	0	0		
		3		0	0	0	0	(1) 10	nai II		olisist	155	0	0		0	0		
(2) Total Derailed	d	0		0	0	0	0	(2) To	tal D	erailed		39	0	0	)	0	0		
36. Equipment Damage				37. Tra	ick, Signal, V	Way,		38. Primary Cause					39. Contributing Cause						
This Consist		2027911		&	Structure Da	mage	58600	EU/C I II/A											
		embers							of Time on Duty 45. Conductor										
40. Engineer/ Operators			42. Co	onductors	43. Brakemen 0		44. E	0	er/Operator Hrs 4		10	45. Con		rs	4	Mi 10			
	N/A 0		_	1							Mi	10				-			
Casualties to:	46. Railı	Railroad Employees 47. Train Passeng				s 48. 0	Other			evice?			50. Was EOT Device Properly Armed?						
Fatal	Fatal 0				0 0			1. Yes 2. No 1					1. Yes 2. No 1						
Nonfatal	Nonfatal N/A		-		-		0	51. Caboos		se Occupied by Crew?							N/A		
Nomatai		N/A		0			1. Yes	2. No	2. No										
	OPERATING TRAIN #2																		
52. Type of Equipment 1. Freight train 4. Work train 7. Yard/switching A. Spec. MoW Equip. Code 53. Was Equipment Code 54. Train Number/Symbol Attended?																			
Consist (single en		0				tended?				N/A									
55. Speed (recorded)						Maint./in	•		s) th				2.10		ontrol				
55. Speed (recorded speed, if available)     Code     57. Method(s) of Operation       R - Recorded     a. ATCS     g. Auto									enter code(s) that apply) atic block m.Special instructions						57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled				
E - Estimated 0 MPH N/A b. Auto train control b. Current of traffic n. Other than main track $1 = \text{Remote control } p$										•									

DEPARTME FEDERAL RA						FRA F.	ACTUA	L RAILI	ROAD AC	CI	DENT I	REPO	ORT	F	RA File #	<u>HQ-200</u>	<u>5-70</u>			
56. Trailing Tons (gross tonnage, excluding power units) 0					d. e.	c. Auto train stop i. Time table/tr d. Cab j.Track warran e. Traffic k. Direct traffi f. Interlocking l.Yard limits				Code(s)					2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter					
58. Principal Car/Unit a. Initial and Nu					lumber	b. Posit	ided(yes/no)								I					
(1) First involved 0					0		N/A		enter the	Alcohol	Drugs									
(derailed, struck, etc)								IN/A	the appropriate box. N/A							N/A				
(2) Causing (if mechanical cause reported)			0			0		N/A	6	0. Was thi	s consi	st transport	ng passen	N/A						
61. Locomotive U	Units				Mid 7 anual			ear End ll c. Remot	62. Cars	62. Cars         Loaded         Empty           a. Freight         b. Pass.         c. Freight         d. F							e. Caboose			
(1) Total in Train			0	0 0		0	0	0	(1) Total in	(1) Total in Equip			uipment Consist 0			0	0			
(2) Total De	(2) Total Derailed		0		0	0	0	0	(2) Total D	Derai	railed 0			0	0	0	0			
	Equipment Damage 0				ick, Signal, Structure D		0	65. Primar Code							luse	N/A				
			Number	r of C	rew Me	mbers							Length of							
67. Engineer/ Operators		68. Firemen 6			69. Co	nductors 0	70. Bi	rakemen 0	71. Engin	eer/( Hrs	Operator 0	Mi	0	72. Con	ductor Hrs	Mi 0				
Casualties to:	-	Railroa	ad Emplo	yees	74. Trai	n Passenge	rs 75. Ot	her		76. EOT Device?				77. Was	EOT Devic	Armed?				
Fatal			0			0		0		1. Yes 2. No N/A						1. Yes 2. No				
Nonfatal			0			0		0		78. Caboose Occupied by Crew?       1. Yes     2. No							N/A			
			Highwa	ıy Us	er Invo	olved				Rail Equipment Involved										
79. Type C. Tru	ıck-Traileı	г. F	Bus	1	I Other	Motor Veh	icle	Code	83. Equip	83. Equipment 3.Train (standing) 6.Light Loco(s) (moving)										
A. Auto D. Pic B. Truck E. Var			1.Train(units pulling)     4.Car(s) (moving)     7.Light(s) (standing)       N/A     2.Train(units pushing)     5.Car(s) (standing)     8.Other (specify in narrative)																	
80. Vehicle Spe	ical)	Code	_	84. Position of Car Unit in Train																
(est. MPH	N/A	05.0	0 85. Circumstance																	
82. Position	Creasing	2 540		~~~~:			- Crossina													
1.Stalled on Crossing 2.Stopped on Crossing 3.Moving Over Cross 4. Trapped								N/A				-	ighway Use	er			N/A			
86a. Was the highway user and/or rail equipment involved								Code	86b. Was t	here	a hazardo	us mat	erials releas	e by			Code			
in the impa	-	-				4 No. 14		I N/A	1. High	wav	User 2.	Rail E	auipment	3. Both	4. Neithe	r	N/A			
1. Highway User       2. Rail Equipment       3. Both       4. Neither       N/A       1. Highway User       2. Rail Equipment       3. Both       4. Neither         86c. State here the name and quantity of the hazardous materials released, if any.														1011						
		- 1					,	N/A												
	.Gates		4.Wig			7.Cross		0.Flagged b		88.	Signaled C	Crossin	g Warning	Code	89. Whis		Code			
***	als 8.Stop 9.Watc		1.Other (spe 2.None	c. in narr.)	(	(See instru	ctions	for codes)	1. Yes 2. No											
Code(s)	3.Standard N/A	ard FLS 6.Audible			4	N/A	N/A	N/A	N/A					N/A	3. Un	known	N/A			
90. Location of W 1. Both Side	0		1			Code		ing Warning Highway S		Interconnected Code 92. Crossing Illuminated by S gnals Lights or Special Lights							Code			
2. Side of Vehicle Approach								l. Yes 2. No					1. Yes							
3. Opposite Side of Vehicle Approach						N/A	3		N/A 2. No 3. Unknown							N/A				
						ver Drove														
Age 0		1. Male 2. Female N/A				d Struck or Yes 2	was Strucl 2. No	'n I	2. Stopped and then Proceeded 5. Other (specify in											
97. Driver Passed Standing         Code         98. View of Track Obscured b							cured by													
Highway Vehicle     N/A     Permanent Structure     Passing Train 5. Vegetation     Other     (specify in narrative)       1. Yes 2. No 3. Unknown     N/A     2. Standing Railroad Equipment     4. Topography     6. Highway Vehicle     8. Not obstructed														Code N/A						
101. Casulties to Highway-Rail							r Was	ograpny 0.	rngr	Code 100. Was				Code						
Crossing Users Killed				1   1	Injured	1. Killed	1 2.Injured 3	-		N/A		1. Ye	es	N/A						
	0	0	•		Property Damage 103. Total Number of Highway-Rail Crossing (include driver) 0															
Image: Construction of the second													Code							
1. Yes			2. No					N/A		Yes			2. No				N/A			
106. Locomotive Headlight Illuminated?								Code N/A	107. Locor	107. Locomotive Audible Warning Sounded?							Code			
1. Yes 2. No									1.	Yes		N/A								

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED. nosketch. bmp

# No Sketch Included With This Incident

### 109. SYNOPSIS OF THE ACCIDENT

On August 27, 2005, at 7:55 a.m. CST, eastbound BNSF freight Train Symbol C-BTMLRT1-07, consisting of 3 locomotives and 135 loaded coal cars and operating at a recorded speed of 50 mph, derailed 39 loaded coal cars at milepost 165.1 of the Nebraska Division, St. Joseph Subdivision. The accident occurred approximately 4.7 miles northwest of Tecumseh, Nebraska. The 66th through 104th head cars derailed as a result of this accident.

At the time of the accident, the weather was daylight and clear with a temperature of 65 °F.

Track and signal damage was reported at \$586,000 and equipment damage at \$2,027,911. These costs totaled \$2,613,911.

Probable cause is dragging equipment (E07C). Markings found on the concrete ties to the field side of the south rail indicated equipment dragging from the point of derailment back approximately 1,500 feet prior to and all the way up to the point of derailment. The point of derailment was at the switch located at West Bear. It was at this point that the dragging equipment caught the switch structure resulting in the derailment.

## 110. NARRATIVE

Circumstances Prior to the Accident

The crew of Train Symbol C-BTMLRT1-07A included a locomotive engineer and a conductor. They first went on duty at 3:45 a.m. CST, August 27, 2005, at the BNSF Hobson Yard in Lincoln, Nebraska. This was the home terminal for the crew members, and all received more than the statutory off duty period, prior to reporting for duty.

Their assigned freight train consisted of three locomotives and 135 loaded coal cars. It was 7,388 feet long with 19,172 trailing tons. The train was scheduled to travel to Tecumseh, Kansas, where it would be unloaded. The train received a Class I air brake test at Guernsey, Wyoming, on August 24, 2005. The train also received a Class IA air brake test performed by mechanical department personnel at Lincoln on August 27, 2005, and departed at 6:10 a.m. There were no changes made to the consist after departing Lincoln.

As the eastbound train approached the accident area, the locomotive engineer was seated at the controls on the south side of the leading locomotive. The conductor was seated on the north side of the leading locomotive.

In this area of the railroad there are in succession, a 0-degree 30-minute curve to the left of about 3,700 feet, followed by a tangent of 2,950 feet to the point of the accident and 5,400 feet beyond. The grade is undulating in this area with a 0.37 percent ascending grade for about 1,060 feet prior to the point of accident. The grade is 0.39 percent descending after the point of accident for about 1,480 feet.

The railroad timetable direction of the train was east. The geographic direction was southeast. Timetable directions are used throughout this report.

The Accident

The train was being operated at 50 mph approaching the accident area and at the time of the accident. Speeds were recorded by the event recorder of the controlling locomotive. The maximum authorized speed for loaded coal trains is 50 mph, as designated in the current BNSF Timetable No. 5.

At 7:55 a.m. CST, on August 27, 2005, Train Symbol C-BTMLRT1-07A was traveling eastward at milepost 165.1, at a recorded speed of 50 mph. The engineer was seated at the control stand and the conductor was seated at his normal position in the cab when a trainline initiated emergency air brake application brought the head end of the train to a stop, at milepost 163.9. The accident resulted in the 66th head car through the 104th head car derailed at milepost 165.1. The weather was daylight and clear with a temperature of 65 °F. Visibility was unrestricted approaching the accident area.

Track and signal damage was reported at \$586,000 and equipment damage at \$2,027,911. These costs totaled \$2,613,911.

Analysis

Railroad personnel responded to the accident. BNSF conducted inspections of the track and equipment following the accident. A download of the event recorder was analyzed by the BNSF and FRA to determine if train handling contributed to the cause of the accident.

Post-accident toxicology testing of the crew was conducted. Results were negative.

# FRA FACTUAL RAILROAD ACCIDENT REPORT

FRA made observations of the track structure from the point of derailment back approximately 1,500 ft., examining markings found on the ties.

FRA made observations of derailed equipment after such equipment had been cleared from the track. There was no evidence of truck component failure found on any of the derailed cars.

BNSF and FRA analyzed readouts from the last traversed failed equipment, dragging equipment, and wheel load impact detectors (WILD). The failed equipment detector located at milepost 183.1 and the dragging equipment detector located at milepost 166.7 produced no alarms. The WILD detector located at Bingham, Nebraska, approximately 300 miles prior to the derailment, detected the 68th head car (KPLX 1115) having a high impact reading of 109 kips. Set-out criteria for BNSF eastbound alarms is 113 kips. No impact affected rail was found at the accident site.

FRA was informed by BNSF that no prior signal failures were reported at West Bear Station prior to the accident.

No FRA tests or inspections of the non-derailed equipment were conducted.

All post accident analysis focused on markings found on the concrete ties, specifically, on the field side of the south rail. The markings began approximately 1,500 ft. prior to the point of derailment and continued up to the point of derailment. These marks were located 7 inches out from the base of the rail and 10 inches in from the outside, of the ties. The marks were parallel to the rail and perpendicular to the end of the tie. The marks were uniform in that each mark had similar characteristics. Post accident analysis could not isolate the dragging equipment to a specific car. BNSF responders stated that these markings were found with a layer of fresh powder, caused by the impact to the concrete, and that the markings were not found past the point of derailment. These observations indicated to the BNSF that no prior train caused the markings found on the ties.

Conclusions

The railroad was in full compliance with their own, and all applicable Federal regulations.

Post accident analysis focused on markings found on the ties prior to and up to the point of derailment. These markings indicated that equipment was dragging prior to the point of derailment. At the point of derailment, milepost 165.1, there is a No. 20 turnout. It was at this switch (West Bear) that the dragging equipment caught the track structure resulting in the derailment.

Post accident inspections and observations of the track, equipment, and train operations revealed no other causal or contributing causal factors.

#### Probable Cause & Contributing Factors

The accident occurred due to dragging equipment (E07C). Evidence of dragging equipment was found approximately 1,500 feet prior to and all the way up to the point of derailment. The point of derailment was at the switch located at West Bear. It was at this point that the dragging equipment caught the switch structure resulting in the derailment.