



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2005-77***

***Union Pacific (UP)
Gibbon, Nebraska
September 13, 2005***


Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2005-77</u>	
1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP]				1a. Alphabetic Code UP		1b. Railroad Accident/Incident No. 0905NP017	
2. Name of Railroad Operating Train #2 N/A				2a. Alphabetic Code N/A		2b. Railroad Accident/Incident N/A	
3. Name of Railroad Responsible for Track Maintenance: Union Pacific RR Co. [UP]				3a. Alphabetic Code UP		3b. Railroad Accident/Incident No. 0905NP017	
4. U.S. DOT_AAR Grade Crossing Identification Number				5. Date of Accident/Incident Month Day Year 09 13 2005		6. Time of Accident/Incident 06:15:00 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM	
7. Type of Accident/Incident (single entry in code box)							
1. Derailment		4. Side collision		7. Hwy-rail crossing		10. Explosion-detonation	
2. Head on collision		5. Raking collision		8. RR grade crossing		11. Fire/violent rupture	
3. Rear end collision		6. Broken Train collision		9. Obstruction		12. Other impacts	
						13. Other (describe in narrative) 01	
8. Cars Carrying HAZMAT 0		9. HAZMAT Cars Damaged/Derailed 0		10. Cars Releasing HAZMAT 0		11. People Evacuated 0	
12. Division North Platte							
13. Nearest City/Town Gibbon				14. Milepost (to nearest tenth) 179.9		15. State Abbr Code N/A NE	
16. County BUFFALO							
17. Temperature (F) (specify if minus) 57 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 1		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1	
21. Track Name/Number Main Track No. 3				22. FRA Track Code Class (1-9, X) 5		23. Annual Track Density (gross tons in millions) 197	
24. Time Table Direction Code 1. North 3. East 3							
OPERATING TRAIN #1							
25. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching		A. Spec. MoW Equip. Code		26. Was Equipment Attended? Code	
2. Passenger train 5. Single car 8. Light loco(s).		3. Commuter train 6. Cut of cars 9. Maint./inspect.car		1		1. Yes 2. No 1	
27. Train Number/Symbol CJRHP911							
28. Speed (recorded speed, if available) Code R - Recorded 49 MPH R E - Estimated		30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits				30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0	
29. Trailing Tons (gross tonnage, excluding power units) 18968							
31. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded (yes/no)	
(1) First involved (derailed, struck, etc)		N/A		82		yes	
(2) Causing (if mechanical cause reported)		0		0		N/A	
						32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	
						Alcohol Drugs 0 0	
						33. Was this consist transporting passengers? (Y/N) N	
34. Locomotive Units		a. Head End		Mid Train		Rear End	
		b. Manual		c. Remote		d. Manual c. Remote	
(1) Total in Train		2		0		0	
(2) Total Derailed		0		0		0	
						35. Cars	
						a. Freight b. Pass. c. Freight d. Pass. e. Caboose	
						134 0 0 0 0	
						(1) Total in Equipment Consist	
						(2) Total Derailed	
						27 0 0 0 0	
36. Equipment Damage		37. Track, Signal, Way, & Structure Damage		38. Primary Cause Code		39. Contributing Cause Code	
This Consist 113405		399430		T299		N/A	
Number of Crew Members				Length of Time on Duty			
40. Engineer/Operators N/A		41. Firemen 0		42. Conductors 1		43. Brakemen 0	
44. Engineer/Operator Hrs 7 Mi 35		45. Conductor Hrs 7 Mi 35					
Casualties to:		46. Railroad Employees		47. Train Passengers		48. Other	
Fatal		0		0		0	
Nonfatal		N/A		0		0	
						49. EOT Device? 1. Yes 2. No 1	
						50. Was EOT Device Properly Armed? 1. Yes 2. No 1	
						51. Caboose Occupied by Crew? 1. Yes 2. No N/A	
OPERATING TRAIN #2							
52. Type of Equipment Consist (single entry)		1. Freight train 4. Work train 7. Yard/switching		A. Spec. MoW Equip. Code		53. Was Equipment Attended? Code	
2. Passenger train 5. Single car 8. Light loco(s).		3. Commuter train 6. Cut of cars 9. Maint./inspect.car		N/A		1. Yes 2. No N/A	
54. Train Number/Symbol N/A							
55. Speed (recorded speed, if available) Code R - Recorded N/A MPH N/A E - Estimated		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track				57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION		FRA FACTUAL RAILROAD ACCIDENT REPORT				FRA File # <u>HQ-2005-77</u>	
56. Trailing Tons (gross tonnage, excluding power units) N/A		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A	
						2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A	
58. Principal Car/Unit (1) First involved (derailed, struck, etc) (2) Causing (if mechanical cause reported)		a. Initial and Number N/A		b. Position in Train N/A		c. Loaded(yes/no) N/A	
						59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol Drugs N/A N/A	
						60. Was this consist transporting passengers? (Y/N) N/A	
61. Locomotive Units (1) Total in Train (2) Total Derailed		a. Head End N/A		Mid Train b. Manual c. Remote N/A N/A		Rear End d. Manual e. Remote N/A N/A	
						62. Cars (1) Total in Equipment Consist (2) Total Derailed	
						Loaded a. Freight b. Pass. c. Freight d. Pass. e. Caboose N/A N/A N/A N/A N/A	
63. Equipment Damage This Consist		N/A		64. Track, Signal, Way, & Structure Damage N/A		65. Primary Cause Code N/A	
						66. Contributing Cause Code N/A	
Number of Crew Members				Length of Time on Duty			
67. Engineer/Operators N/A		68. Firemen N/A		69. Conductors N/A		70. Brakemen N/A	
						71. Engineer/Operator Hrs N/A Mi N/A	
						72. Conductor Hrs N/A Mi N/A	
Casualties to: Fatal Nonfatal		73. Railroad Employees N/A		74. Train Passengers N/A		75. Other N/A	
						76. EOT Device? 1. Yes 2. No N/A	
						77. Was EOT Device Properly Armed? 1. Yes 2. No N/A	
						78. Caboose Occupied by Crew? 1. Yes 2. No N/A	
Highway User Involved				Rail Equipment Involved			
79. Type C. Truck-Trailer F. Bus J. Other Motor Vehicle Code A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian B. Truck E. Van H. Motorcycle M. Other (spec. in narrative) N/A				83. Equipment 3. Train (standing) 6. Light Loco(s) (moving) Code 1. Train(units pulling) 4. Car(s)(moving) 7. Light(s) (standing) 2. Train(units pushing) 5. Car(s)(standing) 8. Other (specify in narrative) N/A			
80. Vehicle Speed (est. MPH at impact) N/A				81. Direction (geographical) 1. North 2. South 3. East 4. West Code N/A			
82. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped Code N/A				84. Position of Car Unit in Train N/A			
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither Code N/A				85. Circumstance 1. Rail Equipment Struck Highway User Code 2. Rail Equipment Struck by Highway User N/A			
86b. Was there a hazardous materials release by 1. Highway User 2. Rail Equipment 3. Both 4. Neither Code N/A				86c. State here the name and quantity of the hazardous materials released, if any. N/A			
87. Type of Crossing Warning Code(s)		1. Gates 4. Wig Wags 7. Crossbucks 10. Flagged by crew 2. Cantilever FLS 5. Hwy. traffic signals 8. Stop signs 11. Other (spec. in narr.) 3. Standard FLS 6. Audible 9. Watchman 12. None N/A N/A N/A N/A N/A		88. Signaled Crossing Warning (See instructions for codes) Code N/A		89. Whistle Ban 1. Yes 2. No 3. Unknown Code N/A	
90. Location of Warning 1. Both Sides Code 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach N/A		91. Crossing Warning Interconnected with Highway Signals 1. Yes 2. No 3. Unknown Code N/A		92. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown Code N/A		93. Driver's Age N/A	
94. Driver's Gender 1. Male 2. Female Code N/A		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown Code N/A		96. Driver 1. Drove around or thru the Gate 4. Stopped on Crossing 2. Stopped and then Proceeded 5. Other (specify in narrative) 3. Did not Stop Code N/A		97. Driver Passed Standing Highway Vehicle 1. Yes 2. No 3. Unknown Code N/A	
98. View of Track Obscured by (primary obstruction) 1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative) 2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed Code N/A		99. Driver Was 1. Killed 2. Injured 3. Uninjured Code N/A		100. Was Driver in the Vehicle? 1. Yes 2. No Code N/A		101. Casualties to Highway-Rail Crossing Users Killed Injured N/A N/A	
102. Highway Vehicle Property Damage (est. dollar damage) N/A		103. Total Number of Highway-Rail Crossing Users (include driver) N/A		104. Locomotive Auxiliary Lights? 1. Yes 2. No Code N/A		105. Locomotive Auxiliary Lights Operational? 1. Yes 2. No Code N/A	
106. Locomotive Headlight Illuminated? 1. Yes 2. No Code N/A		107. Locomotive Audible Warning Sounded? 1. Yes 2. No Code N/A					

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.

HQ-2005-
77
Sketch.jpg



109. SYNOPSIS OF THE ACCIDENT

An eastbound loaded coal train derailed the 80th through 106th head cars of their train on September 13, 2005, at 6:15 a.m. CDT. The derailment occurred approximately 4.3 miles east of Gibbon, Nebraska, at milepost (MP) 179.9, on main Track No. 3, of the UP Kearney Subdivision.

As a consequence to the accident, the derailed cars also blocked main Tracks No. 1 and No. 2, that run parallel on the north side of main Track No. 3. There were no injuries or hazardous material spills as result of the derailment. Monetary damages reported for the derailment totaled \$1,532,835.

At the time of the accident, it was dawn with cloudy skies and a temperature of 57 °F.

The probable cause of the derailment was determined to be a broken rail, although the exact type of break was not determined.

110. NARRATIVE

The following information was obtained from an investigation that was conducted by the Federal Railroad Administration.

Circumstances Prior to the Accident

The train crew of Train Symbol CJRHP9-11 consisted of an engineer and conductor. They first went on duty at 11:15 p.m., CDT, September 12, 2005, at North Platte Terminal in North Platte, Nebraska. This was their home terminal and both had received more than the required statutory off-duty period prior to reporting for duty.

Their assigned train consisted of two locomotives on the head end, 134 loaded coal cars, and a remote locomotive on the rear-end. The loaded unit coal train was 7,458 feet long and weighed 18,968 tons. This crew was scheduled to take the train to Marysville, Kansas.

There was no work performed en route after departing and the trip was uneventful for the 108 miles leading up to the derailment.

As the eastbound train approached the accident area, the locomotive engineer was seated at the controls on the south side of the lead locomotive. The conductor was seated on the north side of the same locomotive.

The track structure through, and leading up to, the accident site is tangent track with very little grade at this location. It is constructed of 133-pound continuous welded rail on concrete crossties. A left-hand turnout was also located at the derailment sight. The turnout was a No. 10 turnout with a spring-rail frog on concrete ties that leads to two stub tracks owned by Nutra-Flow, a fertilizer company. It was a trailing movement over this turnout.

The railroad timetable direction and geographical direction of the train is east.

The Accident

The train was being operated at 48 mph approaching the derailment area. According to the train crew, they did not observe or feel anything unusual prior to this area. The speed at the time of the derailment was also 48 mph. Both speeds were recorded by the event recorder of the controlling locomotive. Maximum authorized speed for this train was 50 mph as designated in current UP Council Bluffs Area Timetable No. 2.

Analysis and Conclusions

Analysis

The two crew members of Train Symbol CJRHP9-11 were FRA mandatory post-accident toxicologically tested after the accident. The test results obtained from the FRA Alcohol and Drug Control Program Manager were negative.

The event recorders for both lead locomotives revealed nothing inconsistent with normal train handling at, or 10 miles prior to, the time of the derailment.

The last ultrasonic rail detection test through this area was on August 29, 2005, and the last geometry car survey with the railroad's EC-4 car, was on July 7, 2005, with no defects noted in the immediate area.

Two suspicious pieces of broken rail found in the derailment were sent to the UP lab in Omaha, Nebraska, for analysis. There was some receiving batter on the

ends of these rails, but no indications of defects could be found. The lab determined the batter happened after the derailment and did not contribute to the cause.

U.S. Department of Transportation
Federal Railroad Administration

Conclusion

The railroad was in compliance with their own and all applicable FRA standards. There were no witnesses to the accident, other the train crew, who stated they didn't feel anything out of the ordinary before they experienced the undesired emergency application of the train's air brakes.

Nothing was found at the derailment that could positively be attributed as the cause. The data reviewed from the event recorder ruled out train handling as a cause. There were no marks found on the rail or ties prior to the point of derailment (POD) . There were also no track components, i.e. bridges, grade crossings, or culverts, at the POD area that could have contributed to the cause. The one turnout near the POD was a trailing point move. The spring wing rail frog and switch point were recovered, and showed no signs that they were contacted by the outer edge of a wheel or other contributory factors. The grade and curvature of the track were not a factor in this derailment for the speed involved.

It was found that the 79 rail cars prior to the first car derailed had marks on their south wheels. The marks were progressively worse from the cars at the head of the train to the last car to stay on the rail. This indicated that a rail most likely broke under one of the locomotives in this train, causing the eventual accident.

Probable Cause & Contributing Factors

T-299 Other rail and joint bar defects. Although field investigations and lab analysis concluded a broken rail was the probable cause of this derailment, it was impossible to determine the exact rail defect due to the extensive damage to the rail