

Federal Railroad Administration Office of Safety Headquarters Assigned Accident Investigation Report HQ-2005-84

CSX Transportation (CSX) Rocky Mount, North Carolina October 1, 2005

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.


FEDERAL RAILRO				FKAF	ACTUA	L RA	ILR	OAD A	CCIDE	ENT F	REPOR'	Γ		FRA Fi	ile#	HQ-200)5-84	
1.Name of Railroad Ope	rai i i piacette code					1b. 1	b. Railroad Accident/Incident No.											
CSX Transportation	CSX						000015510											
2.Name of Railroad Operating Train #2								•					b. Railroad Accident/Incident					
CSX Transportation 3.Name of Railroad Resp	2-	CSX					000015510											
•	F					30.1	b. Railroad Accident/Incident No.											
CSX Transportation 4. U.S. DOT_AAR Grad	5 D	CSX 5. Date of Accident/Incident					ime of A	000015		-nt								
	J. D	Month Day Year					6. Time of Accident/Incident											
			10 01 2005					04:50: 🗸 AM 🔲 PM										
7. Type of Accident/Ind		7. Hwy-rail crossing 10. Explosion-detonation 13. Other																
(single entry in code	,	Head or Rear en		J. Ruki		8. RR grade crossing 11. Fire/violent rupture (describe in narrative) 9. Obstruction 12. Other impacts 04									04			
8. Cars Carrying HAZMAT 0	10. Cars HAZMA		ıg			11. People Evacuated		0		12. Division Florence		Florence	;					
13. Nearest City/Town	14. Mile	epost		T	15. State	tate G.		16. County										
•	(to r	nearest te	enth) A121.(Code NC	EDGE				MBE						
17. Temperature (F) (specify if minus)	1	8. Visibi		single entry)	Code		eather (single e Clear 3. Rair			•				ype of Track			(Code
\ I	(specify if minus) 1. Dawn 3.Dusk 65 F 2. Day 4.Dark						. Clea . Clou	ır 3. Ka ıdv 4. Fo		1 -					Siding Industry			2
21. Track Name/Number	r				22. FRA					23. Annual Track Density			24. Tin	ne Table	Table Direction			Code
	ssover	Clas	Class (1-9, X) (gross tons in 1. North 1 millions) 0							h 3.	East	1	1					
						OPER	ATI	NG TRA	IN #1				•					
25. Type of Equipment	1. Fr	eight trai	in 4.	Work train	7. Yard/swi	itching	A.	Spec. MoV	W Equip.	Code			ment (Code	27. Т	Train Nu	mber/	Symbol
Consist (single entry) 2. Passenger train 5. Single car 8. Light loco(s)								17					ided?					
5. Commuter train 6. Cut of cars 9. Maint./inspect.car 1. 168 2. No 15/150												wo?						
28. Speed (recorded speed, if available) Code R - Recorded 30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m.Special instructions 30a. Remotely Controlled Locomotive? 0 = Not a 2 controlled by the first of the controlled by the controll												<i>/</i> C:						
E - Estimated 3 MPH E b. Auto train control h. Curr								of traffic n. Other than main track					1 = Remote control portable					
20. Trailing Tons			ble/train orders o. Positive train control					2 = Remote control tower										
avaludina mayyan yaita)								varrant control p. Other (Specify in narrati traffic control Code(s)					e) 3 = Remote control transmitter - more than one					
e. Traffic k. Dire								control		remote				1 2				
21 72 1 2 77 2		Initial a				1			_		I/A N/A						3	
31. Principal Car/Unit	ion in Trair	1 C. I	Loade					e(s) tested for drug/alcohol use, tat were positive in Alcohol						Drugs				
(1) First involved (derailed, struck, etc) N/A					1		r	no			e appropriate box.							N/A
(2) Causing (if mechanical cause reported)					0		N	N/A 33. Was this consist			consist tra	ransporting passengers? (Y/N)					i	N
34. Locomotive Units				id Train	1	ar End		35. Cars	<u> </u>			Lo	Loaded			Empty		
(1) Total in Train			b. Manua	al c. Remote	d. Manua	1 c. Rer 0				a. Fr			b. Pass.			d. Pass.	e. C	aboose
(1) Total in Train		1	0	0	0	- 0		(1) Total	III Equipi	ment Co	DIISISU	0	0	17				0
(2) Total Derailed		0	0	0	0	0		(2) Total	Derailed			0	0	()	0		0
36. Equipment Damage		500	37.	Track, Signal,	Way,			38. Prima	ıry Cause	:	•		39. Con	tributing	g Caus	se		
This Consist	amage	0		Code H30					Code				N/A					
Number of Crew Members 40. Engineer/ 41. Firemen 42. Conductors						.1		,					h of Time on Duty 45. Conductor					
Operators				43. Brakemen			44. Engıı	•	eer/Operator Hrs 5 Mi		20	45. Cor		Irs	5	Mi	20	
N/A				1							Mi	20						
Casualties to: 46	46. Railroad Employees 47. Train Passengers				ers 48. C	Other		49. EOT Device? 1. Yes 2. No 2								Properly		
Fatal 0			0 0			-						1. Yes 2. No N/A						
Nonfatal	N	N/A 0		0		0		51. Caboose Occupied by Crew? 1. Yes				2. No N/A						
'					O	PERAT	ΓING	TRAIN	#2								•	
52. Type of Equipment	1. Fre	eight train	n 4.	Work train	7. Yard/swi					Code	53. Was	Equip	ment c	Code	54 T	rain Nur	nber/S	Symbol
Consist (single entry) 2. Passenger train 5. Single car 8. Light 1						o(s).). Atte					ided?			1			,001
				Cut of cars	9. Maint./in	•				7	1.	Yes				Y390		
55. Speed (recorded speed, if available) Code 57. Method(s) of Operation								enter code(s) that apply)					57a. Remotely Controlled Locomotive?					
R - Recorded E - Estimated 5 MPH E a. ATCS g. Aut b. Auto train control h. Cur								atic block m.Special instructions n. Other than main track						0 = Not a remotely controlled 1 = Remote control portable				
L Loumated 5	171	1		 b. Auto trair 	i control I	. curren	t OI II	arric					1 – KUII	.ou coll	aoi p			

Form FRA F 6180.39 (11/06) Page 1 of 5

FEDERAL RAII					FRAF	ACTUA	L RAILR	COAD AC	CIDENT R	REPOR	T	F	RA File #	HQ-200	<u>5-84</u>			
56. Trailing Tons (gross tonnage, excluding power units) 0 c. Auto train d. Cab e. Traffic f. Interlocking					j. k	Time table/t Track warrar . Direct traffi Yard limits	nt control I	o. Positive train o. Other (Specific Code(s) n N/A N	ative)	2 = Remo 3 = Remo transmit remote co	3							
58. Principal Car/Unit a. Initial and Number b. Position in						ion in Trai	n c. Load	ded(yes/no)	59. If railroad	/alcohol us	e,							
(1) First involved (derailed, struck, etc) CSX 603					1 1 1				N/A enter the number that were positive in the appropriate box. Alcohology N/A									
(2) Causing (if mechanical cause reported)					0			N/A 60. Was this consist transp				ng passen	N					
61. Locomotive Un				Mid T	Гrain c. Remote		ar End	62. Cars	62. Cars L a. Freigh				Em c. Freight		e. Caboose			
(1) Total in Tr	in Train 1		0 0		0	0	(1) Total in Equipment Consist			0	0	12	0	0				
(2) Total Dera	(2) Total Derailed 0)	0	0	0	0	(2) Total Derailed		0	0	0	0	0				
63. Equipment Dan	nage	300	n	64. Tra	ck, Signal,	Way,	0	65. Primar Code	y Cause		66. Contributing Cause							
This Consist 3000					& Structure Damage					H306	Code N/A							
	1 co E		mber of	Crew Me		1 70 P		71 F :	10	Lei	ngth of T	72. Cond						
67. Engineer/ Operators 1	gineer/ perators 1 68. Firemen 0			69. Conductors 70. B			akemen 1	71. Engineer/Operator Hrs 5 Mi			20	72. Con	Hrs	Mi 20				
Casualties to:	73. Ra	ilroad E	mployees	74. Trai	n Passenge	rs 75. Otl	her	76. EOT D	evice?		77. Was l	Armed?						
Fatal		0 0					0		1. Yes 2. No 2 1. Yes 2 78. Caboose Occupied by Crew?									
Nonfatal		0			0		0	/8. Caboo	1. Yes	2. No				2				
Highway User Involved									Rail Equipment Involved									
79. Type							83. Equipr	83. Equipment										
C. Truck A. Auto D. Pick-	k-Trailer. -Up Truck	F. Bus G. Sch	ool Bus		Motor Veh strian	icle		3.1ram (standing) 6.Light Loco(s) (moving) 1.Train(units pulling) 4.Car(s) (moving) 7.Light(s) (standing)										
B. Truck E. Van H. Motorcycle M. Other (spec. in narrative) N/A 2. Train(units pushing) 5. Car(s) (standing) 8. Other (specify in												narrative)	N/A					
80. Vehicle Speed		0					84. Positio	84. Position of Car Unit in Train 0										
(est. MPH at impact) 0 1.North 2.South 3.East 4.West N/A 82. Position Code 85. Circumstance																		
1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 1. Rail Equipment Struck Highway User												Code N/A						
4. Trapped N/A 2. Rail Equipment Struck by Highway U 86a. Was the highway user and/or rail equipment involved Code 86b. Was there a hazardous materials rel-													Code					
in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither N/A 1. Highway User 2. Rail Equipment 3. Both 4. Neither													N/A					
86c. State here the i						eleased if:		1.11.5		Turi Equi	Pinent				1771			
oce. State here the l	name and	quantity	or the in	azuruous	materials it	orcused, ir i	N/A											
J 1	Gates		.Wig Wa).Flagged by 1.Other (spec		88. Signaled Cr	_	_	Code	89. Whist 1. Yes		Code			
Crossing 2.Cantilever FLS 5.Hwy. traffic signals 8.Stop signs Warning 3.Standard FLS 6.Audible 9.Watchman							2.None	:. III IIair.)	2. No									
Code(s) N	N/A	N/A	N	/A	N/A	N/A	N/A	N/A							N/A			
90. Location of Wa 1. Both Sides										Code								
2. Side of Vehicle Approach 1. Yes																		
3. Opposite Side of Vehicle Approach N/A							l. No . Unknown		N/A		2. No 3. Unkno	own	N/A					
93. Driver's 94. Driver's Gender Code 95. Driver Drove Behind or in 1							in Front of T								Code			
Age 1. Male and Struck or was Struck							by Second 7 3. Unknown	2 Stepped and then Decembed 5 Oct						on Crossin ecify in	g			
0 2. Female N/A 1. Yes 2. No						INO	3. Ulikilowi		N/A 3. Did not Stop narrative) N/.									
97. Driver Passed Standing Highway Vehicle 98. View of Track Obscured by (primary obstruction) 1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative)													Code					
1. Yes 2. No 3. U		N	/A					-	vegetation Highway Vehic		ot obstru		u114114C)		N/A			
101. Casulties to Highway-Rail							r Was		Code				Driver in the Vehicle?					
Crossing Users		Kille		zu l	injuicu		2.Injured 3.	-	- 1				N/A					
							way Vehicle Property Damage dollar damage) 103. Total Number of Highwa (include driver)						ruguway-	Rail Cross	mg Users			
104. Locomotive A	uxiliary L	ights?	'			,	Code		notive Auxiliary	y Lights (Operatio	nal?		-	Code			
1. Yes	:		2. No				N/A		Yes		No				N/A			
106. Locomotive Headlight Illuminated?							Code		notive Audible	_		1?			Code			
1. Yes		- 2	2. No			ļ	N/A	1.	Yes	2.	No				N/A			

Form FRA F 6180.39 (11/06) Page 2 of 5

 $108.\,DRAW\,A\,SKETCH\,OF\,ACCIDENT\,AREA\,INCLUDING\,ALL\,TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.\\84.bmp$



Form FRA F 6180.39 (11/06) Page 3 of 5

FRA File # HQ-2005-84

109. SYNOPSIS OF THE ACCIDENT

On October 1, 2005, CSX Transportation (CSX) Remote Control Locomotive (RCL) Yard Switchers Y391-30 and Y390-30 were switching on the north end of CSX Rocky Mount Yard in Rocky Mount, North Carolina (NC). Both RCL yard crews consisted of a foreman, switchman, and a trainee.

RCL Y391-30 established a Remote Control Zone (RCZ) in the Rocky Mount Yard without protecting the leading end of the movement. CSX Special Instructions identify this RCZ to be located on the North End East Yard Lead, 25 feet north of the road crossing, north of "CO", 10 feet north of A14 switch.

About 4:50 a.m., Eastern Standard Time (EST), RCL Y390-30 with Locomotive No. CSXT 6031 and 70 cars, received permission to enter the remote control zone of RCL Y391-30. They were making a cross yard move from Track No. A21 to Track No. A12, using the rip track crossover. After shoving cars into A12, RCL Y390-30 was instructed to hold onto 12 cars and return back to Track No. A21. As they were shoving through the Rip track crossover, RCL Y391-30 with Locomotive No. CSXT 9498 was pulling out of Track No. A02 with 17 cars, striking RCL Y390-30 locomotive as it moved through the crossovers.

The side collision ruptured the fuel tank of Locomotive No. CSXT 6031, leaking about 1,000 gallons of diesel fuel. There was \$3,500 damage to both locomotives. No car derailed and there was no personal injuries or track damage as a result of the impact.

At the time of the accident, it was dark and cloudy. The temperature was 65 F

The probable cause of the accident was the failure of the remote control operator of RCL Y391-30 to check the RCZ after use by another crew, and failure to protect the leading end of the movement.

110. NARRATIVE

The following information was obtained from an investigation that was conducted by the Federal Railroad Administration.

Circumstances Prior to the Accident

RCL Y391-30

The crew of CSX Yard Switcher RCL Y391-30 included a foreman, switchman, and a trainee. On September 30, 2005, at 11:30 p.m., they went on duty at the Rocky Mount Yard in Rocky Mount, NC. Rocky Mount is the home terminal for all the crew members and all received the statutory off duty period in excess of eight hours prior to reporting for duty. The crew received a job briefing from the trainmaster on duty and switching instructions from the yardmaster. They were using the Northwest Ladder with the North End East Yard Lead RCZ, activated for their switching moves.

RCL Y390-30

The crew of CSX Yard Switcher RCL Y390-30 included a foreman, switchman, and a trainee. On September 30, 2005, at 11:30 p.m., they went on duty at the Rocky Mount Yard in Rocky Mount, NC. Rocky Mount is the home terminal for all the crew members and all received the statutory off duty period in excess of eight hours prior to reporting for duty. The crew received a job briefing from the trainmaster on duty and instructions from the yardmaster on the work to be performed during their shift. They were performing switching moves off of the Northeast Ladder.

The Accident

RCL Y390-30 received permission to enter the RCZ of the RCL Y391-30 to make a crossover yard move with 70 cars from Track No. A21 through the rip track crossover switches to Track No. A12. After completing the move, RCL Y390-30 was instructed by the yardmaster to take 12 cars back to Track No. A21. When the cars cleared Track No. A12, the foreman and trainee of RCL Y391-30 lined the switch back for the ladder. The foreman pitched the Remote Control Unit (RCU) to his switchman, who started the RCL moving north on the northwest ladder with 17 cars. The RCL Y391-30 foreman called his switchman over the radio instructing him to stop the movement when he noticed their train moving north on the northwest ladder track. The RCL Y391-30 switchman immediately placed the RCU speed selector switch in the stop position, but the train continued to move northward colliding with the RCL Y390-30 locomotive. The RCL Y390-30 switchman and trainee were riding on the locomotive that was shoving back through the rip track crossover when their Locomotive No. CSXT 6031 was struck by the RCL Y391-30 locomotive.

Analysis

The foreman on RCL Y390-30 requested and received permission via radio from the foreman on RCL Y391-30 to occupy their RCZ using the rip track crossovers. The RCL Y390-30 was in the process of clearing the RCZ. The foreman on RCL Y391-30 pitched the control of the RCL to his switchman who started moving the RCL northward in the direction where RCL Y390-30 was still occupying the RCZ. The RCL Y391-30 conductor noticed his RCL moving northward and immediately told the switchman to stop the movement. The crew on RCL Y390-30 was also telling the conductor of RCL Y391-30 via the radio to stop his train. RCL Y391-30 did not stop and collided with RCL Y390-30, which was operating through the rip track crossover switches.

The foreman on RCL Y390-30 had not released the use of RCZ back to the RCL Y391-30 crew. The switchman on RCL Y391-30 failed to comply with CSX RCL

Form FRA F 6180.39 (11/06) Page 4 of 5

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

FRA FACTUAL RAILROAD ACCIDENT REPORT

FRA File # HQ-2005-84

Instructions, Rules R22 and R24, which state in part: "Before resuming utilization of the zone without point protection, it must be inspected. Tracks within the RCZ must be inspected and known to be clear of cars, engines or employees fouling the tracks, switches improperly lined. The switchman was required to ride the leading end of the movement to ensure compliance with CSX RCL Instruction Rule 22.

Conclusion

The switchman on RCL Y391-30 failed to check his RCZ after use by another crew. He failed to comply with CSX instructions governing Remote Control Locomotive Operating Rules R24 and R22.

Probable Cause

The FRA determined the primary cause of the accident was the failure of the RCL Y391-30 switchman to provide head end protection and ensure the RCZ was clear prior to movement, which resulted in the side swipe collision.

Form FRA F 6180.39 (11/06) Page 5 of 5