

Federal Railroad Administration Office of Safety Headquarters Assigned Accident Investigation Report HQ-2005-87

Burlington Northern Santa Fe (BNSF) Mason, North Dakota October 3, 2005

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

DEPARTMENT ( FEDERAL RAILR	OF TRA ROAD A	ANSPORT ADMINIST	TATI( TRAT	NC ION	FRA FA	ACTUA	AL RA	ILROAD	) A(	CCIDENT I	REPO	RT	Ι	FRA Fil	le # <u>H</u>	IQ-200	<u>5-87</u>	
1.Name of Railroad C BNSF Rwy Co. [BN	1a. Alphabetic Code 1b BNSF					o. Railroad Accident/Incident No. TC1005102												
2.Name of Railroad O	2a. Alphabetic Code   2b.					. Railroad Accident/Incident												
N/A	N/A					N/A												
3.Name of Railroad R	3a. Alphabetic Code 3b					. Railroad Accident/Incident No.												
BNSF Rwy Co. [BN	NSF]	ecing Ident	ificati	on Nur	nber			5 Dete of		TC1005102								
4. 0.3. DOI_AAR 0		issing ident	mean	JII INUI	liber		5. Date of Accident/Incident 6. '					Time of Accident/Incident						
							10	ui	03	2005		11:58: 🔽 AM 🗌 PM						
7. Type of Accident/I	7. Hwy-i	. Hwy-rail crossing 10. Explosion-detonation 13. Other																
(single entry in coo	de box)	2. Head of	on coll	ision	5. Raking	ı	8. RR gr	8. RR grade crossing 11. Fire/violent rupture (describe in narrative)										
		3. Rear e	nd col	lision	6. Broke	n Train co	ollision	9. Obstru	ictio	n 12.	. Other ir	npacts	oacts 01					
8. Cars Carrying		9. HAZMA	rs		Releasin	ig 11. People					12. Division				•			
HAZMAI 0	HAZMAT 0 Damaged/Derailed					a 0 HAZMAT				Evacuated			0			Twin Cities		
13 Nearest City/Tow	'n	1						15. State	5. State									
1511(calest city, 10)		Mason				nearest te	enth) 33.8		Abbr N/A	Abbr Code			CASS					
17 Temperature (F)		10 17:01		(010)	(single entry) Code			<u> </u>	Ļ	IN/A	INL	<b>'</b>						
(specify if minus)	)	10. VISIC	Dawn	(Sing 3.D	3.Dusk Code 19.			Clear (si	ngle 8. Rai	entry) in 5.Sleet	Co	de	20. Typ	1 Main 3 Siding			Code	
58	F	2.	Day	4.I	Dark	2.	. Cloudy 4	I. Fog	g 6.Snow	1	2. Ya	2. Yard 4. Industry			1			
21. Track Name/Num	iber					Code		23. Annual Tra	ty	24. Tim	me Table Direction			Code				
			Mai	n		Clas	ss (1-9, X	<sup>(1)</sup>		(gross tons	in	15 1		1. North 3. East			3	
										minions)		15.1					5	
							OPER	ATING T	'RA	IN #1								
25. Type of Equipment 1. Freight train 4. Work train 7. Yard/switching A. Spec. MoW Equip. Code 26. Was Equipment Code 27. Train No. Attended?												ain Nun	nber/Symbol					
Consist (single en	10ry) 2	Commute	r train	5. 51	igle car 8.	co(s).		1	1 Yes	Yes 2 No 1 GEINSTI 902								
28. Speed (recorded)	sneed if	available)	Code	- 0. Cl	Method(s)	of Operati	on (	enter code	(s) t	hat apply)			30a. Rem	otely Co	ontrolle	ed Loco	motive?	
R - Recorded $R$ -												<b>Menled</b>						
E - Estimated	46	MPH	R	b	. Auto train o	control h	n. Curren	t of traffic	of traffic n. Other than main track					1 = Remote control portable				
c. Auto train stop i. Time t									ders	<ul> <li>o. Positive train</li> <li>a. Other</li> </ul>	n control		2 = Remo	ote conti	rol tow	er		
27. Training tons (gross tonnage, d. Cab j.Track excluding power units)										p. Other (Speci	ify in naı (s)	rative)	tive) 3 = Remote control transmitter - more than one					
	Yard lin	nits	01	·	(3)		remote control transmitter											
				<u> </u>			-			J N/A N	N/A N/A	A N/A					0	
31. Principal Car/Unit	t	a. Initial	and N	imber	b. Positio	on in Traii	n c. 1	Loaded(yes/	no)	32. If railroad	employe	e(s) teste that were	d for drug	/alcoho	l use,	loobol	Druge	
(1) First involved (derailed, struck, e	etc)		N/A			51		yes		the appro	priate bo	x.	positive		A	0	1 Drugs	
(2) Causing (if med	chanica	1								33 Was this	consist t	ransporti	ng nassen	oers? (Y	/N)	0	1 *	
cause reported)	)	BNS	F4717	93	3 51			yes		55. was uns	consist (	ransport	ng passen	gers: (1	/11)		N	
34. Locomotive Units a. Head			Mid 7	Frain	Re	ar End	35.	Cars			Lo	aded	Empty		/			
		End	b. Ma	inual	c. Remote	d. Manua	l c. Rer	note			a.	Freight	b. Pass.	c. Frei	ght d.	Pass.	e. Caboose	
(1) Total in Train	1	5		0	0	0	0	(1) T	otal i	n Equipment C	onsist	107	0	0		0	0	
(2) Total Deraile	d	0		0	0	0	0	(2) T	otal l	Derailed		33	0	0		0	0	
36. Equipment Dama	ige			37 Tr	ck Signal V	Vav		38 P	rima	ry Causa			30 Cont	ributing	Cause			
This Consist	1	1578781		۶۲. ۱۱۵ &	Structure Da	mage 1	51045	0 Code	:		)C	Code N/A						
		Numbe	r of Ci	ew Me	embers	Ũ			Length of Time on Duty									
40. Engineer/ 41. Firemen 4					42. Conductors   43. Brakemen				44. Engineer/Operator			0	45. Conductor					
Operators N/A	N/A N/A				1		1		-	Hrs 4	Mi	58		H	rs 4	L I	Mi 58	
Casualties to:	46. Rail	road Emplo	vees 2	es 47 Train Passengers 48 Oth				49. EOT Device?					50. Was	EOT De	roperly	Armed?		
E ( 1	Eatel						-		es 2. No	2. No   1		1. Yes 2. No 1						
Fatal		0			0		51 Caboose Occupier											
Nonfatal		N/A			0		0		Jubbo	1. Yes	1. Yes 2. N						N/A	
OPERATING TRAIN #2																		
52 Type of Equipment 1. Freight train 4. Work train 7. Yard/switching A Spec MoW Equip Code 53. Was Equipment Code 54 Train Number/Symbol																		
Consist (single entry) 2. Passenger train 5. Single car 8. Light loco(s).								71. Spcc.	A. Spec. Mow Equip. Code S5. Was Attend					?				
	3.	. Commuter	train	6. Cu	t of cars 9.	Maint./in	spect.car	·		N/A		1. Yes	2. No N	I/A		N/A		
55. Speed (recorded	speed, if	available)	Code	e 57	. Method(s)	of Operati	on (	nter code(s) that apply)					57a. Remotely Controlled Locomotive?					
R - Recorded a. ATCS g. Aut								atic block m.Special instructions					0 = Not a remotely controlled					
E - Estimated	U	MPH	ın/A	b	. Auto train o	control h	n. Curren	t of traffic	1	n. Omei ulali m	am uack		1 = Rem	ote cont	rol por	table		

DEPARTME FEDERAL R	ENT OF AILRO	TRAN AD AD	NSPORT MINIST	ΓΑΤΙ ΓRΑΊ	ON TION	FRA F.	ACTUA	L RAIL	ROAD AC	CUI	DENT I	REPO	ORT	F	RA File #	<u>HQ-200</u>	<u>5-87</u>			
56. Trailing Tons (gross tonnage, excluding power units)					c. d. e.	c. Auto train stop i. Time table/tu d. Cab j.Track warran e. Traffic k. Direct traffi				ain orders o. Positive train control control p. Other (Specify in narrative) Code(s)					2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter					
59 Dringing Cor/Unit					t.	Interlockin	Y ard limits	had ( )			N/A N/A									
(1) First involved					Number	D. POSI			ided(yes/no)	59.1	59. It railroad employee(s) tested for drug/alcohol use,									
(derailed, struck, etc) 0							N/A		N/A	the appropriate box.						N/A	N/A			
(2) Causing (if mechanical cause reported) 0							N/A		N/A	60. Was this consist transporting passengers? (Y/N)						)	N/A			
61. Locomotive	Units	a. Head End b. Mar			Mid Ianual <sub>I</sub>	Mid Train nual c. Remote		ear End l   c. Remot	62. Cars	62. Cars			Lo a. Freight	Loaded Em I. Freight b. Pass. c. Freight			e. Caboose			
(1) Total in Train		0	0 0		0	0	0	(1) Total in	1) Total in Equipment Consist 0 0 0				0	0						
(2) Total D	erailed	d 0		0	0 0		0	(2) Total I	(2) Total Derailed			0	0	0	0	0				
63. Equipment I This Consi	Equipment Damage 6 This Consist 0				64. Tr	ack, Signal, Structure D	Way, amage	0	65. Primar Code	65. Primary Cause 66. Contributing Cause Code N/A Code						use	N/A			
			Numbe	er of C	rew Me	embers							Length of	Time on D	uty					
67. Engineer/	6	58. Firei	men		69. Co	onductors	70. Bi	rakemen	71. Engin	71. Engineer/Operator 72. Conduc					ductor	0	Mi			
Operators	N/	N/A				N/A		N/A		Hrs 0			0		M1 ()					
Casualties to	p: 73	. Railro	ad Empl	oyees	74. Tra	in Passenge	rs 75. Ot	her	76. EOT E	76. EOT Device?					77. Was EOT Device Properly					
Fatal			0			0		0	1. 1	es	2. No	<u> </u>	N/A	1.	Yes	2. No	N/A			
Nonfatal			0			0		0		78. Caboose Occupied by Crew?							N/A			
	olved		-		Rail Equipment Involved															
79. Type	nek Trai	iler D	D		LOther	M-4 X-1	:.1.	Code	83. Equip	83. Equipment										
A. Auto D. Pi	J. Other K. Pede M. Other	strian	ncle	1.Train(units pulling)         4.Car(s) (moving)           7.Light(s) (standing)           V(e)         N/A           2.Train(units pushing)         5.Car(s) (moving)           8.Other (moving)									N/A							
80. Vehicle Sp	eed			81. D	virection	geograph	ical)	Code	84. Position of Car Unit in Train											
(est. MPH	outh 3.East	4.West	N/A		N/A															
82. Position Code 85. Circur											5. Circumstance									
1.Stalled on Crossing 2.Stopped on Crossing 3.Moving Over Cross 4. Trapped								N/A	2. Rail Ed	quipm	ent Struc	k high k by H	ighway User	er			N/A			
86a. Was the highway user and/or rail equipment involved								Code	86b. Was t	there a	a hazardo	us mat	erials releas	e by			Code			
in the imp	ıs ma	terials?			• N/A	1 High	way I	lser 2	Rail F	auinment	3 Both	4 Neithe	r	N/A						
1. Highway User       2. Rail Equipment       3. Both       4. Neither       N/A       1. Highway User       2. Rail Equipment       3. Both       4. Neither         866       State has also and quantity of the baserdous metaziole released if any														IVA						
obe. State here t	ne name	ana qui	unity of	une na	izaruous	materials r	cicasca, ii	N/A												
87. Type of	1.Gates		4.Wi	g Wag	gs	7.Cross	bucks 1	0.Flagged b	y crew	88. S	ignaled C	Crossin	g Warning	Code	89. Whis	tle Ban	Code			
Crossing Warning	ffic sign	als 8.Stop 9 Wate	signs 1 hman 1	1.Other (spe 2 None	c. in narr.)	(5	See instru	ctions	for codes)	s										
Code(s)	N/A	N/A         N/A         N/A         N/A         N/A         N/A         3. Unit							known	N/A										
90. Location of	Warning	I	<u> </u>		I	Code	91. Cross with	ing Warning Highway S	Interconnect	ed	Code	92. 0	Crossing Illu Lights or S	ig Illuminated by Street s or Special Lights						
2. Side of Vehicle Approach								I. Yes	0				1. Yes							
3. Opposite Side of Vehicle Approach						N/A	3	2. No 5. Unknown			N/A		2. No 3. Unkn	own	N/A					
93. Driver's 94. Driver's Gender Code 9						iver Drove	Behind or	Frain Cod	ain Code 96. Driver											
Age 0	1. N 2. F	/lale <sup>7</sup> emale	l N	/ <b>A</b>	an 1.	d Struck or Yes 2	was Strucl 2. No	Train	2. Stopped and then Proceeded 5. Other (specify in N/A 3 Did not Stop											
97. Driver Passed Standing Code 98. View of Track Obscured by								ed by (primary obstruction)												
Highway Vehicle 1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative)																				
1. Yes     2. No     3. Unknown     19/A     2. Standing Railroad Equ       101. Casulties to Highway-Rail     00 Dr							ad Equipn	nent 4. Top	ography 6.	gnway Vehicle 8. Not obstructed						IN/A Code				
Crossing Users Killed					d	Injured	1. Killed	1 was 12.Injured 3	. Uninjured		N/A 1. Y			es	N/A					
0						0	102. High	Property Damage 103. Total Number of Highway-Rail Cro (include driver)							Rail Cross	ing Users				
104. Locomotive Auxiliary Lights?     Code     105. Locomotive Auxiliary Lights Operational?													Code							
1. Ye	es		2. No	o				N/A	1.	Yes			2. No				N/A			
106. Locomotive Headlight Illuminated?								Code	107. Loco	107. Locomotive Audible Warning Sounded?							Code			
1. Yes 2. No									1.	1. Yes 2. No							N/A			



108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED. 87.bmp

## 109. SYNOPSIS OF THE ACCIDENT

An eastbound BNSF Railway Company (BNSF) freight train derailed on October 3, 2005, at 11:58 a.m., CDT. The accident occurred approximately 5 miles west of Mason, North Dakota, on a single main track, at milepost 33.8, on the Twin Cities Division, Prosper Subdivision.

The train consisted of five locomotives and 107 loaded cars. The 46th car behind the locomotives derailed as it was traveling east on tangent track. The train continued eastward for approximately 9020 feet and when it passed over a main line turnout an additional 32 cars derailed. It was determined that the 45th through the 77th cars behind the locomotives derailed.

There were no injuries to the train crew and no hazardous materials involved.

The railroad estimated that there was track damage of \$504,950, signal damage (track-side warning detector) of \$5,500, and equipment damage of \$1,578,781.

At the time of the derailment it was 58° F and clear.

The probable cause of the accident was "other axle and journal bearing defects" (CAR). The roller bearing adapter became dislodged from the truck side and the top of the roller bearing. The roller bearing adapter then sheared off the three roller bearing cap screws, allowing the roller bearing cap and truck side frame to drop off the roller bearing and make contact with the rail and crossties.

## 110. NARRATIVE

The following information was obtained from an investigation that was conducted by the Federal Railroad Administration.

Circumstances Prior to the Accident

The crew of Train Symbol G-FINSTL9-02 consisted of a locomotive engineer, a conductor, and a brakeman. They first went on duty at 7:00 a.m., CDT, October 3, 2005, at Dilworth Yard in Dilworth, Minnesota. This was the home terminal for all crew members, and all received more than the statutory off duty period, prior to reporting for duty.

The crew was transported to Finley, North Dakota, where another crew previously added two locomotives and 27 loaded cars to the train.

The assigned freight train then consisted of five locomotives, 107 loaded cars, 15,288 trailing tons, and was 6782 feet in length. It was a grain train scheduled to travel from Finley, North Dakota to Dilworth, Minnesota, a distance of 72.15 miles.

On October 3, 2005, a Class 1 air brake test and daily locomotive inspection was conducted at Finley, ND. The train departed Finley at approximately 10:10 a.m. on October 3, 2005.

As the train approached the derailment area, the locomotive engineer was seated at the controls on the right (south) side of the leading locomotive. The conductor was seated on the left (north) side, and the brakeman was seated in the center of the cab of the leading locomotive.

Interviews conducted by the Federal Railroad Administration (FRA) revealed the trip was uneventful prior to the derailment.

Approaching the derailment site from the west traversing eastward, there is tangent track for approximately 2.3 miles in length, followed by a 1-degree 32-minute curve to the right, approximately 2112 feet in length, followed by tangent track for approximately 1450 feet in length to the point of derailment (POD). The derailment occurred on tangent track and the derailed car was dragged for approximately 1.7 miles, where an additional 32 cars derailed. The track is tangent beyond the accident site for approximately 32 miles. The approach to the POD (milepost 33.8) has a descending grade of 0.60-percent.

## The Accident

Train G-FINSTL9-02 was traveling timetable and geographical direction east on single main track at a recorded speed of 46 mph while approaching the POD. The speed was recorded by the event recorder of the controlling locomotive. The maximum authorized speed for the Prosper Subdivision is 49 mph, as designated by the current BNSF Timetable No. 2, dated Wednesday, November 17, 2004.

As the train was traveling eastward the train went into an emergency brake application and came to a stop. It was later determined that the derailed car had been derailed for approximately 9020 feet. When the derailed car struck a turnout at milepost 31.95, an additional 32 cars derailed.

After coming to a stop, the engineer notified the train dispatcher. The conductor and brakeman walked back to inspect the train and determined that the 45th through the 77th cars behind the locomotives had derailed.

Further investigation of the derailment determined that the initial POD was at milepost 33.8, on tangent track. Approximately 1340 west of the POD an end cap and an end cap screw for a roller bearing were found about 20 feet south of the south rail. The above mentioned pieces had started two small fires and were still warm to

## FRA FACTUAL RAILROAD ACCIDENT REPORT

the touch when found. Further investigation of the POD showed that something other than a wheel was on the ground. The marks on the ties were wider than wheel marks. When all information was compiled, it was determined that the marks were made by the truck side frame of the first derailed car.

The three person train crew did not report any injuries.

There were no hazardous materials involved, and no evacuations were required. All cars derailed were transporting grain.

There were no local emergency responders dispatched to the accident scene.

Analysis and Conclusions

The accident met the criteria for FRA Post Accident Toxicology Testing, as required under Title 49 CFR, Part 219, Subpart C. The crew was blood and urine tested at an Occupational Health Services Collection Facility. One crew member tested positive for Cannabinolds. The other two crew members tested negative.

An inspection of the data print out from the lead locomotive event recorder indicated that the train was being operated at 46 mph at the location of the POD. The event recorder also indicated no unusual events related to train handling.

Probable Cause

The FRA determined that the probable cause of the derailment was "other axle and journal bearing defects (CAR)". The roller bearing adapter became dislodged from the truck side and the top of the roller bearing. The roller bearing adapter then sheared off the three roller bearing cap screws, allowing the roller bearing cap and truck side frame to drop off the roller bearing and make contact with the rail and crossties.