

Locomotive Collision Test #7 Freight Locomotive (DASH8-C39) Colliding with a Stationary Hopper Car




Test #7: Set-Up



Test #7: Pre-Test Photos



Bullet locomotive and trailing hopper cars



Stationary hopper cars

Test #7: Post Test Photos



Position of locomotive following collision test



View of locomotive front end damage

Test #7: Post Test Photos



Extensive damage to the front end of the locomotive





Test #7: Outcome

What did we learn from this test?

- Even at low speeds (~30 mph), the locomotive can override stationary vehicles (Similar to Test #1)
- Anticlimber did not directly affect the outcome of this collision
- End plate and draft gear pocket formed a ramp that allowed the locomotive to ride up on top of the comparatively weaker hopper structure
- Hopper body provided no resistance to locomotive override
- Damage to the anticlimber and locomotive front, including the collision posts, was massive (locomotive to hopper car collision at 40 mph), and the draft gear failed